

P.Eng Seal

SC-8243
SC-8243

MALASPINA km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Fair

Corner

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Good

Riprap Fair

Bearings

Corrosion Protection

SC-8243
SC-8243

MALASPINA km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Culvert

Baffles

Bolted Connections Good

Coating Good

Coupled Connections N/A

Embedment Materials Good

Fill Good

Floor Unrated Na

Footing Fair Exposed in some places

Head Walls

Inlet Fair

Outlet Good

Overall Good

Rip Rap Fair

Roof Good

Sidewalls Good

Trash Rack

Weirs/Backwater
Structures

Wing Walls

SC-8243
SC-8243

MALASPINA km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

3

SC-8243
SC-8243

MALASPINA km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Outlet



Outlet



SC-8243
SC-8243

MALASPINA km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Upstream Profile



Upstream Profile



Culvert Floor

