

SC-8337
SC-8337

SECHELT CREEK 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°40'44.29" Longitude -123°33'4.8"

Site Status Active

Insp. Status Inspect

Crossing Name Sechelt Creek

FSR # 10228 Branch # 2

Road Name SECHELT CREEK

User km 0.2

Previous Load Rating (tonnes) 136

Structure Class Permanent Bridge

Portable N

Superstructure Compo Girders

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 30.5

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5530237.9 Accuracy (m)

Inspection

Date of Inspection 2022-09-28 12:01:11 PM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate
Pipe / cable on us side

Recommended Next Inspection

Inspection Company MoF

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 24, 2023
Load Rating: L150 or 136 tonnes
Next Inspection: 2025



PERMIT TO PRACTICE: 1003022

SC-8337
SC-8337

SECHELT CREEK 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete **Good**

Caps or Sills **Good**

Piles or Posts **Good**

Ballast Wall

Wing Wall

Bracing **Good**

Hardware **Good**

Fill **Good**

Riprap **Fair** Ds right side partially scoured. Monitor.

Bearings **Good**

Corrosion Protection **Good**

SC-8337
SC-8337

SECHELT CREEK 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good** New fir guardrails

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8337
SC-8337

SECHELT CREEK 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Good

Diaphragms Good

Bracing N/A

Under Trussing

Hardware Good

Splice appears ok

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8337
SC-8337

SECHELT CREEK 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	2.0	High Water	☒	Debris	☐
Estimated Present Water Level Width (m)	5.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance	5.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Monitor ds right riprap	Routine Inspection

2

3

SC-8337
SC-8337

SECHELT CREEK 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Downstream profile - from left



Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



SC-8337
SC-8337

SECHELT CREEK 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Upstream Profile - from right



Downstream Profile - from right