

SC-8354
SC-8354

SECHELT GRAY 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°34'57.39"
Longitude -123°42'58.9"

Site Status Active

Insp. Status Inspect

Crossing Name Not Known

FSR # 7575 Branch # 17

Road Name SECHELT GRAY

User km 0.2

Previous Load
Rating (tonnes) 0

Structure Class Temporary Bridge

Portable N

Superstructure Log Stringers

Deck Type Gravel

Abutment Left Other

Abutment Right Other

Spans 1

Total Length (m) 11

Deck Width (m) 5

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5519511.0 Accuracy (m)

Inspection

Date of Inspection 2022-09-29 9:05:27 AM

Inspector Name Richard Mills

Recommended Next Inspection 2023

Inspection Company MoF

Inspector Comments Serial/ID Plate

No change since last inspection. Recently surveyed. Ensure access is blocked.

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 24, 2023
Load Rating: 0 tonnes
Next Inspection: 2023
Comments: Ensure access to bridge is closed.



PERMIT TO
PRACTICE: 1003022

SC-8354
SC-8354

SECHELT GRAY 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 0

Road Surface Fair

Abutment

Log/Timber Cribs Fair Scoured

Tie Backs Fair

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Fair

Riprap

Bearings Fair

Corrosion Protection

SC-8354
SC-8354

SECHELT GRAY 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface Poor

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Rotten

Hand Rails/Walkouts

Hardware

Overall Deck Condition Poor Rotten

Gravel Depth (mm)

Pier Deck

SC-8354
SC-8354

SECHELT GRAY 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Poor

Rotten stringers

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8354
SC-8354

SECHELT GRAY 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance	1.8	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8354
SC-8354

SECHELT GRAY 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Left Bank Abutment when facing downstream




Load Rating Sign



Right Bank Abutment when facing downstream



Approach from Right Bank when facing downstream



SC-8354
SC-8354

SECHELT GRAY 0.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Load Rating Sign



Left Bank Abutment when facing downstream

