

SC-8509
PC-052

BRITAIN RIVER 7.99km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 50°2'8.99"
Longitude -124°3'53"

Site Status Active

Insp. Status Inspect

Crossing Name Not known

FSR # 6104 Branch # 1

Road Name BRITAIN RIVER

User km 7.99

Previous Load
Rating (tonnes) 150

Structure Class Permanent Bridge

Portable Y

Superstructure Steel Box Beam

Deck Type Steel

Abutment Left Concrete Lock Blocks

Abutment Right Concrete Lock Blocks

Spans 1

Total Length (m) 18.3

Deck Width (m) 4.88

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5569963.5 Accuracy (m)

Inspection

Date of Inspection 2022-09-27 10:01:40 AM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection

Inspection Company MoF

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 30, 2023

Load Rating: L165 or 150 tonnes

Next Inspection: 2025



PERMIT TO
PRACTICE: 1003022

SC-8509
PC-052

BRITAIN RIVER 7.99km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills **Good**

Piles or Posts

Ballast Wall **N/A**

Wing Wall

Bracing

Hardware **Good**

Fill **Good**

Riprap **Good**

Bearings **Good**

Corrosion Protection

SC-8509
PC-052

BRITAIN RIVER 7.99km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints **Good**

Steel Deck Plate **Good**

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8509
PC-052

BRITAIN RIVER 7.99km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Good

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8509
PC-052

BRITAIN RIVER 7.99km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8509
PC-052

BRITAIN RIVER 7.99km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Structure ID



Right Bank Abutment when facing downstream