

SC-8559
SC-8559

SALTARY-FAIRVIEW 6.3km

2022 Inspection

CBR iPad Offline Ver



CBR Data

Latitude 49°48'.9" Longitude -124°6'44.6"

Site Status Active

Insp. Status Inspect

Crossing Name UNKNOWN

FSR # 8135 Branch # 3

Road Name SALTARY-FAIRVIEW

User km 6.3

Previous Load Rating (tonnes) 150

Structure Class Temporary Bridge

Portable Y

Superstructure Steel Box Beam

Deck Type Steel

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 18.2

Deck Width (m) 4.88

Updated Data

Latitude 49°48'.66" Longitude -124°6'45.17"

HD Diff. (m) 13.6 Accuracy (m) 5

Inspection

Date of Inspection 2022-07-26 12:29:34 PM

Inspector Name Jonathon Harvey

Inspector Comments Serial/ID Plate

Recommended Next Inspection 2024

Inspection Company MoF

P.Eng Comments

Load Rated by: MoF, J. Harvey P.Eng., November 2022

Load Rating: 150 Tonnes GVW

Next Inspection Year: 2024

Comments:



SC-8559
SC-8559

SALTERTY-FAIRVIEW 6.3km

2022 Inspection

CBR iPad Offline Ver



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair Minimal logs

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Crib Good Cedar

Tie Backs Fair

Bin Wall N/A

Pier N/A

Concrete N/A

Caps or Sills Fair

Piles or Posts N/A

Ballast Wall Fair

Wing Wall N/A

Bracing N/A

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection Fair

SC-8559
SC-8559

SALTERY-FAIRVIEW 6.3km

2022 Inspection

CBR iPad Offline Ver



Deck

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck N/A

Grout Pockets N/A

Deck Joints Fair

Steel Deck Plate Fair Anti skid worn off

Gravel Surface N/A

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts N/A

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck N/A

SC-8559
SC-8559

SALTERY-FAIRVIEW 6.3km

2022 Inspection

CBR iPad Offline Ver



Steel/Concrete

Girders Fair

Diaphragms N/A

Bracing N/A

Under Trussing N/A

Hardware Fair

Welded/grouted
shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8559
SC-8559

SALTERY-FAIRVIEW 6.3km

2022 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	8.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	2.2	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Deck



Guard Rail



Upstream from Crossing



Downstream from Crossing



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Superstructure



Bearing



Downstream Profile