

SC-8635
SC-8635

MCNAB-POTLATCH 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°35'6.9"
Longitude -123°23'12.7"

Site Status Active

Insp. Status Inspect

Crossing Name Unnamed

FSR # 10209 Branch # 4

Road Name MCNAB-POTLATCH

User km 1.5

Previous Load
Rating (tonnes) 150

Structure Class Major Culvert

Culvert Type Round

Culvert Material Corrugated Steel

Opening Height (mm) 2000

Opening Width (mm) 2000

Inlet Cover (mm) 950

Outlet Cover (mm) 1200

Culvert Gradient % 5

Culvert Length (m) 16

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5519804.8 Accuracy (m)

Inspection

Date of Inspection 2022-09-28 10:15:08 AM

Inspector Name Richard Mills

Inspector Comments

Recommended Next Inspection

Inspection Company MoF

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 30, 2023

Load Rating: L165 or 150 tonnes

Next Inspection: 2025



PERMIT TO
PRACTICE: 1003022

SC-8635
SC-8635

MCNAB-POTLATCH 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **Y**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Unrated** **Na**

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall **N/A**

Bracing

Hardware

Fill **Good**

Riprap **Good**

Bearings

Corrosion Protection

SC-8635
SC-8635

MCNAB-POTLATCH 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert

Baffles N/A

Bolted Connections N/A

Coating Good

Coupled Connections Good

Embedment Materials N/A

Fill Good

Floor Good

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

SC-8635
SC-8635

MCNAB-POTLATCH 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8635
SC-8635

MCNAB-POTLATCH 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	1.2	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8635
SC-8635

MCNAB-POTLATCH 1.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Inlet



Approach from Left Bank when facing downstream



Inlet

