

SC-8637
SC-8637

MCNAB-POTLATCH 7.55km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°35'.89"
Longitude -123°20'14.5"

Site Status Active

Insp. Status Inspect

Crossing Name Unnamed

FSR # 10209 Branch # 4

Road Name MCNAB-POTLATCH

User km 7.55

Previous Load Rating (tonnes) 150

Structure Class Major Culvert

Culvert Type Round

Culvert Material Corrugated Steel

Opening Height (mm) 2200

Opening Width (mm) 2200

Inlet Cover (mm) 1050

Outlet Cover (mm) 1100

Culvert Gradient % 3

Culvert Length (m) 16

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5519619.2 Accuracy (m)

Inspection

Date of Inspection 2022-09-28 9:47:48 AM

Inspector Name Richard Mills

Inspector Comments

Add rock protection to outlet the next time machine in area. Monitor.

Recommended Next Inspection

Inspection Company MoF

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 30, 2023

Load Rating: L165 or 150 tonnes

Next Inspection: 2025



PERMIT TO PRACTICE: 1003022

SC-8637
SC-8637

MCNAB-POTLATCH 7.55km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Unrated** **Na**

Posted Load Rating

Road Surface **Fair**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall **N/A**

Bracing

Hardware

Fill **Good**

Riprap **Fair**

Bearings

Corrosion Protection

SC-8637
SC-8637

MCNAB-POTLATCH 7.55km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert

Baffles N/A

Bolted Connections N/A

Coating Good

Coupled Connections Good

Embedment Materials N/A

Fill Good

Floor Good

Footing Good

Head Walls N/A

Inlet Good

Outlet Fair Scoured

Overall Good

Rip Rap Fair

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

SC-8637
SC-8637

MCNAB-POTLATCH 7.55km

2022 Inspection

CBR iPad Offline Ver 0.36



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8637
SC-8637

MCNAB-POTLATCH 7.55km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.0	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance	1.5	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Monitor outlet for erosion	Routine Inspection

2

3

SC-8637
SC-8637

MCNAB-POTLATCH 7.55km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach from Right Bank when facing downstream



Inlet



Inlet



SC-8637
SC-8637

MCNAB-POTLATCH 7.55km

2022 Inspection

CBR iPad Offline Ver 0.36



Inlet



Inlet

