

SC-8653
SC-8653

Brittain River 8.21km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude Longitude
°0'0" °0'0"

Crossing Name Brittain River

FSR # 6104 Branch # 3

Road Name Brittain River

User km 8.21km

Previous Load Rating (tonnes) None

Structure Class

Portable

Superstructure

Deck Type

Abutment Left

Abutment Right

Spans

Total Length (m)

Deck Width (m)

Updated Data

Latitude Longitude
50°2'13.92" -124°3'50.19"

HD Diff. (m) 10027144.8 Accuracy (m) 5

Inspection

Date of Inspection 2022-09-27 9:53:11 AM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2025

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 31, 2023
Load Rating: L165 or 150 tonnes
Next Inspection: 2025



P.Eng Seal

SC-8653
SC-8653

Brittain River 8.21km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

SC-8653
SC-8653

Brittain River 8.21km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8653
SC-8653

Brittain River 8.21km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Steel/Concrete

Girders Good

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8653
SC-8653

Brittain River 8.21km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)	1.0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	8	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8653
SC-8653

Brittain River 8.21km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck



Downstream Profile



Structure ID



Right Bank Abutment when facing downstream

SC-8653
SC-8653

Brittain River 8.21km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Left Bank Abutment when facing downstream



Upstream Profile



Upstream Profile