

SC-8655
SC-8655

LOIS 9.83km

2022 Inspection

CBR iPad Offline Ver



CBR Data

Latitude 49°50'3.99" Longitude -124°14'36.1"

Site Status Active

Insp. Status Inspect

Crossing Name Unnamed

FSR # 8133 Branch # 1

Road Name LOIS

User km 9.83

Previous Load Rating (tonnes) 150

Structure Class Major Culvert

Culvert Type Round

Culvert Material Corrugated Steel

Opening Height (mm) 2000

Opening Width (mm) 2000

Inlet Cover (mm) 1600

Outlet Cover (mm) 2000

Culvert Gradient %

Culvert Length (m) 14

Updated Data

Latitude 49°50'4" Longitude -124°14'36.24"

HD Diff. (m) 2.9 Accuracy (m) 4

2

Inspection

Date of Inspection 2022-07-26 10:16:51 AM

Inspector Name Jonathon Harvey

Inspector Comments

Recommended Next Inspection 2025

Inspection Company MoF

P.Eng Comments

Load Rated by: MoF, J. Harvey P.Eng., November 2022

Load Rating: 150 Tonnes GVW

Next Inspection Year: 2025

Comments:



SC-8655
SC-8655

LOIS 9.83km

2022 Inspection

CBR iPad Offline Ver



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition N/A

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

SC-8655
SC-8655

LOIS 9.83km

2022 Inspection

CBR iPad Offline Ver



Culvert

Baffles

Bolted Connections

Coating Good

Coupled Connections Good

Embedment Materials Good Some material has migrated Downstream approx 10cm

Fill Good

Floor Good

Footing Good

Head Walls

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack

Weirs/Backwater
Structures

Wing Walls

SC-8655
SC-8655

LOIS 9.83km

2022 Inspection

CBR iPad Offline Ver



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8655
SC-8655

LOIS 9.83km

2022 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Inlet



Outlet



Culvert Floor



Looking Downstream Through CMP