

SC-8660
PC-082

RAINY RIVER 0.78km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°35'6.9" Longitude -123°30'50.7"

Site Status Active

Insp. Status Inspect

Crossing Name Stream 8

FSR # 7590 Branch # 2

Road Name RAINY RIVER

User km 0.78

Previous Load Rating (tonnes) 150

Structure Class Temporary Bridge

Portable Y

Superstructure Steel Box Beam

Deck Type Steel

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 9.1

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5519804.8 Accuracy (m)

Inspection

Date of Inspection 2022-11-08 10:55:31 AM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection 2024

Inspection Company MoF

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 23, 2023
Load Rating: L165 or 150 tonnes
Next Inspection: 2024



PERMIT TO PRACTICE: 1003022

SC-8660
PC-082

RAINY RIVER 0.78km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills **Good**

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill **Good**

Riprap **Good**

Bearings **Good**

Corrosion Protection

SC-8660
PC-082

RAINY RIVER 0.78km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints **Good**

Steel Deck Plate **Unrated** Unable to see

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8660
PC-082

RAINY RIVER 0.78km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Good

Diaphragms Good

Bracing

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8660
PC-082

RAINY RIVER 0.78km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)

High Water ☐

Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance

Ic ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream