

SC-8662
SC-8662

RAINY RIVER 0.66km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°35'8.7" Longitude -123°30'47.5"

Site Status Active

Insp. Status Inspect

Crossing Name Unnamed

FSR # 7590 Branch # 2

Road Name RAINY RIVER

User km 0.66

Previous Load Rating (tonnes) 150

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 30.5

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5519860.4 Accuracy (m)

Inspection

Date of Inspection

Inspector Name

Inspector Comments Serial/ID Plate

Recommended Next Inspection 2025

Inspection Company

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 23, 2023
Load Rating: L165 or 150 tonnes
Next Inspection: 2025



PERMIT TO PRACTICE: 1003022

SC-8662
SC-8662

RAINY RIVER 0.66km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

SC-8662
SC-8662

RAINY RIVER 0.66km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets

Deck Joints **Unrated** Unable to see

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8662
SC-8662

RAINY RIVER 0.66km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Good

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8662
SC-8662

RAINY RIVER 0.66km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	5.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	4.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8662
SC-8662

RAINY RIVER 0.66km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



SC-8662
SC-8662

RAINY RIVER 0.66km

2022 Inspection

CBR iPad Offline Ver 0.36

