

SQ-3012

RUTHERFORD 01 8km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
50°17'7.14"	-122°58'14.6"
Crossing Name	Tributary to Rutherford Creek
FSR #	5673
Branch #	1
Road Name	RUTHERFORD 01
User km	8
Previous Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	17.7
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
50°17'7.74"	-122°58'12.21"
HD Diff. (m)	50.7
Accuracy (m)	5

Inspection

Date of Inspection 2019-09-18 10:31:19 AM

Inspector Name Greg Dohm

Recommended Next Inspection Year

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Replace guard rails on upstream side and rotten guardrails on downstream side prior to industrial use

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 24, 2020
Load Rating: L150 or 136 tonnes
Next Inspection: 2022
Comments: Replace guard rails on upstream side and rotten guardrails on downstream side



P.Eng Seal

SQ-3012

RUTHERFORD 01 8km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 136

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Fair

Caps or Sills

Piles or Posts Fair

Ballast Wall Fair

Wing Wall

Bracing

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection Fair

SQ-3012

RUTHERFORD 01 8km

2019 Inspection

CBR iPad Offline Ver 0.31

**Deck**

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Replace guard rails on upstream side and rotten guardrails on downstream side

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Poor Due to guard rails

Gravel Depth (mm)

Pier Deck

SQ-3012

RUTHERFORD 01 8km

2019 Inspection

CBR iPad Offline Ver 0.31

**Steel/Concrete**

Girders Fair

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3012

RUTHERFORD 01 8km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	6	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	Replace guard rails on upstream side and rotten guardrails on downstream side

2

3

Item	Monitor Description	Frequency
1		

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Guard Rail



Guard Rail



Approach from Right Bank when facing downstream



Upstream Profile



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Downstream Profile



Guard Rail