

SQ-3026

BIRKENHEAD MAIN 9.2km

2019 Inspection

CBR iPad Offline Ver 0.31



## CBR Data

|                               |                            |
|-------------------------------|----------------------------|
| Latitude                      | Longitude                  |
| 50°30'52.4"                   | -122°44'21.6"              |
| Crossing Name                 | Birkenhead River           |
| FSR #                         | 5733                       |
| Branch #                      | 1                          |
| Road Name                     | BIRKENHEAD MAIN            |
| User km                       | 9.2                        |
| Previous Load Rating (tonnes) | 68                         |
| Structure Class               | Permanent Bridge           |
| Portable                      | N                          |
| Superstructure                | Compo Girders              |
| Deck Type                     | Concrete Composite         |
| Abutment Left                 | Steel Pipe and Precast Pad |
| Abutment Right                | Steel Pipe and Precast Pad |
| Spans                         | 1                          |
| Total Length (m)              | 31                         |
| Deck Width (m)                | 4.3                        |

## Updated Data

|              |           |
|--------------|-----------|
| Latitude     | Longitude |
| °0'0"        | °0'0"     |
| HD Diff. (m) | 5623254.7 |
| Accuracy (m) |           |

## Inspection

Date of Inspection 2019-09-17 11:59:09 AM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD

## P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., January 29, 2020  
Load Rating: L75 or 68 tonnes  
Next Inspection: 2022  
Comments:



P.Eng Seal

SQ-3026

BIRKENHEAD MAIN 9.2km

2019 Inspection



CBR iPad Offline Ver 0.31

## Approach

Alignment Good

Bridge Ahead Signs  
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing  
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing  
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair Large rocks

Posted Load Rating 68

Road Surface Fair

## Abutment

Log/Timber Cribbs Fair Fill retention only

Tie Backs Fair

Bin Wall N/A

Pier N/A

Concrete Good

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall N/A

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

SQ-3026

BIRKENHEAD MAIN 9.2km

2019 Inspection

CBR iPad Offline Ver 0.31

**Deck**

Running Surface      Good

Running Planks      N/A

Sub Deck      N/A

Ties      N/A

Nails      N/A

Deck to Girder Bolts      N/A

Concrete Deck      Good

Grout Pockets      Good

Deck Joints      Good

Steel Deck Plate      N/A

Gravel Surface      N/A

Curb Rail/Blocks/Posts      Good

Hand Rails/Walkouts      N/A

Hardware      Good

Overall Deck Condition      Good

Gravel Depth (mm)

Pier Deck

SQ-3026

BIRKENHEAD MAIN 9.2km

2019 Inspection



CBR iPad Offline Ver 0.31

**Steel/Concrete**

Girders Good

Diaphragms Good

Bracing N/A

Under Trussing

Hardware Good

Welded/grouted  
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/  
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

| Stringer<br>Number | Species | Peeled | Diameter<br>(mm) | Rot Depth<br>(mm) | Condition | Comment |
|--------------------|---------|--------|------------------|-------------------|-----------|---------|
|--------------------|---------|--------|------------------|-------------------|-----------|---------|

SQ-3026

BIRKENHEAD MAIN 9.2km

2019 Inspection

CBR iPad Offline Ver 0.31



### Hazards

|                                          |     |             |                          |        |                          |
|------------------------------------------|-----|-------------|--------------------------|--------|--------------------------|
| Estimated Present Water Level Depth (m)  | 1.0 | High Water  | <input type="checkbox"/> | Debris | <input type="checkbox"/> |
| Estimated Present Water Level Width (m)  | 8.0 | Aggradation | <input type="checkbox"/> | Scour  | <input type="checkbox"/> |
| Estimated High Water Level Clearance (m) | 4.0 | Ice         | <input type="checkbox"/> |        |                          |

Comments

### Repairs and Monitoring

| Repair Item | Priority | Repair Description |
|-------------|----------|--------------------|
|-------------|----------|--------------------|

1

2

3

| Item | Monitor Description | Frequency |
|------|---------------------|-----------|
|------|---------------------|-----------|

1

2

3

Sketch  
(Select Signature)



Approach from Left Bank when facing downstream



Guard Rail



Deck



Approach from Right Bank when facing downstream



Downstream Profile



Right Bank Abutment when facing downstream



Superstructure



Upstream Profile