

SQ-3043

LILLOOET RIVER 01 8.7km

2019 Inspection



CBR iPad Offline Ver 0.31

CBR Data

Latitude	Longitude
50°31'55.89"	-123°2'56.5"
Crossing Name	Railroad Creek
FSR #	6123
Branch #	1
Road Name	LILLOOET RIVER 01
User km	8.7
Previous Load Rating (tonnes)	54
Structure Class	Temporary Bridge
Portable	N
Superstructure	Rail Car
Deck Type	Timber - Untreated
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	15.8
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
50°31'55.87"	-123°2'56.27"
HD Diff. (m)	4.6
Accuracy (m)	5

Inspection

Date of Inspection 2019-09-18 3:49:14 PM

Inspector Name Greg Dohm

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 24, 2020
Load Rating: L60 or 54 tonnes
Next Inspection: 2021
Comments:



P.Eng Seal

SQ-3043

LILLOOET RIVER 01 8.7km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 54

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills Fair

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection Fair

SQ-3043

LILLOOET RIVER 01 8.7km

2019 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface Fair

Running Planks Fair

Sub Deck

Ties Fair

Nails Fair

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3043

LILLOOET RIVER 01 8.7km

2019 Inspection

CBR iPad Offline Ver 0.31

**Steel/Concrete**

Girders Fair

Diaphragms

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

SQ-3043

LILLOOET RIVER 01 8.7km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	6	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Downstream from Crossing



Upstream from Crossing



Approach from Right Bank when facing downstream



Upstream Profile



Upstream Profile



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Downstream Profile