

SQ-3114

LILLOOET WEST 01 66.7km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
49°49'58.4"	-122°16'3.82"
Crossing Name	Spring Creek (11 mile)
FSR #	8407
Branch #	1
Road Name	LILLOOET WEST 01
User km	66.7
Previous Load Rating (tonnes)	91
Structure Class	Major Culvert
Culvert Type	Elliptical
Culvert Material	Corrugated Steel
Opening Height (mm)	2200
Opening Width (mm)	3600
Inlet Cover (mm)	4000
Outlet Cover (mm)	5000
Culvert Gradient %	3
Culvert Length (m)	20.5

Updated Data

Latitude	Longitude
49°49'58.17"	-122°16'3.32"
HD Diff. (m)	12.3
Accuracy (m)	5

Inspection

Date of Inspection 2019-09-17 12:26:24 PM

Inspector Name Greg Dohm


Recommended Next Inspection Year

Inspection Company FLNRORD

Inspector Comments

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., January 28, 2020
Load Rating: L100 or 91 tonnes
Next Inspection: 2022
Comments:



P.Eng Seal

SQ-3114

LILLOOET WEST 01 66.7km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated Missing

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Fair

Riprap Fair

Bearings

Corrosion Protection

SQ-3114

LILLOOET WEST 01 66.7km

2019 Inspection

CBR iPad Offline Ver 0.31



Culvert

Baffles Fair

Bolted Connections

Coating Fair

Coupled Connections Fair

Embedment Materials N/A

Fill Fair

Floor Fair

Footing

Head Walls N/A

Inlet Fair

Outlet Fair

Overall Fair

Rip Rap Fair

Roof Fair

Sidewalls Fair

Trash Rack

Weirs/Backwater
Structures

Wing Walls

SQ-3114

LILLOOET WEST 01 66.7km

2019 Inspection

CBR iPad Offline Ver 0.31



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3114

LILLOOET WEST 01 66.7km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m) .1

High Water ☐Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐Scour ☒

Estimated High Water Level Clearance (m)

Ice ☐

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Downstream from Crossing



Upstream from Crossing



Inlet



Bottom



Outlet



Outlet