

SQ-3133

MAMQUAM 01 14.2km

2019 Inspection



CBR iPad Offline Ver 0.31

CBR Data

Latitude	Longitude
49°43'2.08"	-123°0'.97"
Crossing Name	Trib to Mamquam
FSR #	9283 Branch # 1
Road Name	MAMQUAM 01
User km	14.2
Previous Load Rating (tonnes)	150
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Steel (non-corrugated)
Opening Height (mm)	1830
Opening Width (mm)	1830
Inlet Cover (mm)	900
Outlet Cover (mm)	1000
Culvert Gradient %	8
Culvert Length (m)	11

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5534498.6 Accuracy (m)

Inspection

Date of Inspection 2019-09-16 3:37:11 PM

Inspector Name Richard Mills

Recommended Next Inspection Year


Inspection Company FLNRORD

Inspector Comments

Old riveted thick - walled pipe in Fair condition. Undersized for flow.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., January 30, 2020
Load Rating: L165 or 150 tonnes
Next Inspection: 2022
Comments:



P.Eng Seal

SQ-3133

MAMQUAM 01 14.2km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated Na

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap N/A

Bearings

Corrosion Protection

SQ-3133

MAMQUAM 01 14.2km

2019 Inspection

CBR iPad Offline Ver 0.31

**Culvert**

Baffles N/A

Bolted Connections N/A

Coating N/A

Coupled Connections Good

Embedment Materials Good

Fill Good

Floor Unrated Buried

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Fair

Rip Rap N/A

Roof Fair

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

SQ-3133

MAMQUAM 01 14.2km

2019 Inspection

CBR iPad Offline Ver 0.31



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3133

MAMQUAM 01 14.2km

2019 Inspection



CBR iPad Offline Ver 0.31

Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☒	Debris	☐
Estimated Present Water Level Width (m)	1.5	Aggradation	☒	Scour	☐
Estimated High Water Level Clearance (m)	0.6	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Inlet



Inlet



Outlet



Approach from Right Bank when facing downstream