

SQ-3148

BRITANNIA 01 2.3km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
49°36'17.1"	-123°11'39.4"
Crossing Name	Daisy #1
FSR #	8321
Branch #	1
Road Name	BRITANNIA 01
User km	2.3
Previous Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	10
Deck Width (m)	5.8

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5521975.5
Accuracy (m)	

Inspection

Date of Inspection 2019-09-16 1:24:11 PM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate


Area prone to debris / rockfall.

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., January 30, 2020
Load Rating: L75 or 68 tonnes
Next Inspection: 2022
Comments:



P.Eng Seal

SQ-3148

BRITANNIA 01 2.3km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor Missing

Posted Load Rating 68

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier N/A

Concrete Good

Caps or Sills Good Treated timber

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Good

Riprap Fair

Bearings Good

Corrosion Protection N/A

SQ-3148

BRITANNIA 01 2.3km

2019 Inspection

CBR iPad Offline Ver 0.31

**Deck**

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Fair

Grout Pockets N/A

Deck Joints Fair

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts N/A

Hardware Good

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3148

BRITANNIA 01 2.3km

2019 Inspection



CBR iPad Offline Ver 0.31

Steel/Concrete

Girders Fair

Diaphragms N/A

Bracing N/A

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors N/A**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

SQ-3148

BRITANNIA 01 2.3km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	0	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Upstream Profile



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream