

SQ-3149

BRITANNIA 01 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
49°36'20.3"	-123°11'35.9"
Crossing Name	Trib to Daisy Creek
FSR #	8321
Branch #	1
Road Name	BRITANNIA 01
User km	2.5
Previous Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	12
Deck Width (m)	4.4

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5522074.5
Accuracy (m)	

Inspection

Date of Inspection 2019-09-16 1:10:18 PM

Inspector Name Richard Mills

Recommended Next Inspection Year


Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Riprap scoured both sides. Will likely continue to scour and destabilize. Repair recommended. Concrete deck on left side damaged, rebar visible - Repair.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., January 30, 2020
Load Rating: L75 or 68 tonnes
Next Inspection: 2022
Comments:



P.Eng Seal

SQ-3149

BRITANNIA 01 2.5km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor Missing

Posted Load Rating 68

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier

Concrete N/A

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall N/A

Bracing Good

Hardware Good

Fill Good

Riprap Poor Scoured both sides.

Bearings Good

Corrosion Protection Good

SQ-3149

BRITANNIA 01 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31

**Deck**

Running Surface Fair

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Fair Damaged on camp side. Repair.

Grout Pockets N/A

Deck Joints Good

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware Good

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3149

BRITANNIA 01 2.5km

2019 Inspection



CBR iPad Offline Ver 0.31

Steel/Concrete

Girders Good

Diaphragms N/A

Bracing N/A

Under Trussing

Hardware Good

Welded/grouted
shear connectors Good**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

SQ-3149

BRITANNIA 01 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	Repair riprap
2	Medium	Repair concrete deck
3	Medium	Add approach barriers

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Deck



Deck



Deck



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream

