

SQ-3251

IN-SHUCK-CH FSR 54.1km

2019 Inspection



CBR iPad Offline Ver 0.31

CBR Data

Latitude	Longitude
49°55'20.1"	-122°19'40.9"
Crossing Name	Unknown
FSR #	7343
Branch #	1
Road Name	IN-SHUCK-CH FSR
User km	54.1
Previous Load Rating (tonnes)	91
Structure Class	Major Culvert
Culvert Type	Open Bottom
Culvert Material	Corrugated Steel
Opening Height (mm)	3600
Opening Width (mm)	1900
Inlet Cover (mm)	2500
Outlet Cover (mm)	2500
Culvert Gradient %	5
Culvert Length (m)	18

Updated Data

Latitude	Longitude
49°55'20.16"	-122°19'41.86"
HD Diff. (m)	19.2
Accuracy (m)	5

Inspection

Date of Inspection 2019-09-17 12:08:31 PM

Inspector Name Gino Fournier


Inspector Comments

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., January 28, 2020
Load Rating: L100 or 91 tonnes
Next Inspection: 2022
Comments:



P.Eng Seal

SQ-3251

IN-SHUCK-CH FSR 54.1km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2 Not needed as road is same width throughout

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated None needed

Posted Load Rating 91

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

SQ-3251

IN-SHUCK-CH FSR 54.1km

2019 Inspection

CBR iPad Offline Ver 0.31

**Culvert**

Baffles N/A

Bolted Connections Good

Coating Good

Coupled Connections Good

Embedment Materials N/A

Fill Good

Floor Good

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

SQ-3251

IN-SHUCK-CH FSR 54.1km

2019 Inspection

CBR iPad Offline Ver 0.31



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3251

IN-SHUCK-CH FSR 54.1km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.5	Ice	☐		

Comments Scout repairs working well.

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Upstream from Crossing



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Downstream from Crossing



Outlet



Inlet



Outlet