

SQ-3063
SQ-3063

IN-SHUCK-CH FSR 34.6km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
50°3'3.54"	-122°31'50.7"
Crossing Name	Tenas Creek
FSR #	7343
Branch #	1
Road Name	IN-SHUCK-CH FSR
User km	34.6
Previous Load Rating (tonnes)	62
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	18.3
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
50°3'.99"	-122°31'50.31"
HD Diff. (m)	79.4
Accuracy (m)	5
33	

Inspection

Date of Inspection 2020-09-10 11:05:45 AM

Inspector Name Greg Dohm

Recommended Next Inspection Year

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Old wbc in stran channel collapsing just downstream of crossing. Both townside and woodside abutments appears to be founded on bedrock so likely not an immediate concern although some downstream riprap on woodside may be affected. Monitor on routine inspection.


P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 6, 2021

Load Rating: BCL625 or 63 tonnes

Next Inspection: 2023

Comments: WBC in channel collapsing just downstream of crossing. Both townside and woodside abutments appears to be founded on bedrock, however should be investigated with inspection and excavator at abutment to confirm bedrock.



P.Eng Seal

SQ-3063
SQ-3063

IN-SHUCK-CH FSR 34.6km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

On curve on woodside

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 62

Road Surface Fair

Abutment

Log/Timber Cribs

Old wbc in stran channel collapsing just downstream of crossing. Both townside and woodside abutments appears to be founded on bedrock so likely not an immediate concern

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall Fair

Wing Wall

Bracing Fair

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection Fair

SQ-3063
SQ-3063

IN-SHUCK-CH FSR 34.6km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3063
SQ-3063

IN-SHUCK-CH FSR 34.6km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3063
SQ-3063

IN-SHUCK-CH FSR 34.6km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Old wbc in stran channel collapsing just downstream of crossing. Both townside and woodside abutments appears to be founded on bedrock so likely not an immediate concern although some downstream riprap on woodside may be affected. Monitor on routine inspection.	Routine Inspection
2		
3		



Approach from Left Bank when facing downstream



Approach from Left Bank when facing downstream




Deck



Guard Rail



Upstream from Crossing



Downstream from Crossing



Deck



Deck



Approach from Left Bank when facing downstream



Upstream Profile



Upstream Profile



Right Bank Abutment when facing downstream



Upstream from Crossing



Left Bank Abutment when facing downstream



Downstream from Crossing



Downstream Profile



Downstream Profile



Downstream from Crossing



Downstream Profile



Downstream from Crossing