

SQ-3089
SQ-3089

IN-SHUCK-CH FSR 20km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 50°9'32.4" Longitude -122°29'13.1"

Crossing Name Dragonfly

FSR # 7343 Branch # 1

Road Name IN-SHUCK-CH FSR

User km 20

Previous Load Rating (tonnes) 62

Structure Class Permanent Bridge

Portable N

Superstructure Concrete Slab Girders

Deck Type Concrete

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 11.5

Deck Width (m) 4.9

Updated Data

Latitude 50°9'32.76" Longitude -122°29'14.27"

HD Diff. (m) 25.7 Accuracy (m) 5

Inspection

Date of Inspection 2020-09-10 12:41:11 PM

Inspector Name Greg Dohm

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021
Load Rating: BCL625 or 63 tonnes
Next Inspection: 2023
Comments:



P.Eng Seal

SQ-3089
SQ-3089

IN-SHUCK-CH FSR 20km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 62

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Fair

Ballast Wall Fair

Wing Wall

Bracing Fair

Hardware Fair

Fill Fair

Riprap Fair Sone loss of riprap on abutments but still functioning.

Bearings Fair

Corrosion Protection Fair

SQ-3089
SQ-3089

IN-SHUCK-CH FSR 20km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3089
SQ-3089

IN-SHUCK-CH FSR 20km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Diaphragms

Bracing

Under Trussing

Hardware Fair

Welded/grouted
shear connectors Fair

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3089
SQ-3089

IN-SHUCK-CH FSR 20km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



Approach from Left Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Right Bank when facing downstream



Upstream Profile



Downstream Profile



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Upstream from Crossing



Downstream from Crossing