

SQ-3126
SQ-3126

WEDGE 01 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
50°10'15.3"	-122°53'10.2"
Crossing Name	Green River
FSR #	8723
Branch #	1
Road Name	WEDGE 01
User km	0.1
Previous Load Rating (tonnes)	54
Structure Class	Permanent Bridge
Portable	N
Superstructure	Compo Girders
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	30.5
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
50°10'15.18"	-122°53'10.4"
HD Diff. (m)	5.6
Accuracy (m)	5

Inspection

Date of Inspection 2020-09-09 4:09:10 PM

Recommended Next Inspection Year

Inspector Name Gino Fournier


Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Consider removing as no longer needed and MOTI blocking access off highway 99

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021
Load Rating: L60 or 54 tonnes
Next Inspection: 2022
Comments: replace curb rails asap and prior to industrial use or consider closing bridge.



P.Eng Seal

SQ-3126
SQ-3126

WEDGE 01 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair Logs

Posted Load Rating 54

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts Fair

Ballast Wall Good

Wing Wall N/A

Bracing Fair

Hardware Fair

Fill Good

Riprap Good

Bearings Good

Corrosion Protection N/A

SQ-3126
SQ-3126

WEDGE 01 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface	Fair	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	Fair	
Grout Pockets	Fair	
Deck Joints	Fair	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	Rotten side blocks and risers
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Fair	
Gravel Depth (mm)	0	
Pier Deck	N/A	

SQ-3126
SQ-3126

WEDGE 01 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Diaphragms N/A

Bracing Fair

Under Trussing N/A

Hardware Fair

Welded/grouted
shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3126
SQ-3126

WEDGE 01 0.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	1.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	25	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item

Repair Description

1	Structure. Full Curb Replacement. . Priority:High	Side blocks and risers fully rotten. Need to replace ASAP prior to any industrial use and consider blocking access to public as there is alternate access through wedgewood subdivision.
---	--	--

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Downstream from Crossing



Upstream from Crossing



Guard Rail



Downstream Profile



Upstream Profile



Left Bank Abutment when facing downstream



2020 Inspection

CBR iPad Offline Ver 0.33

WEDGE 01 0.1km

SQ-3126
SQ-3126



Right Bank Abutment when facing downstream