

SQ-3127
SQ-3127

DAISY 01 1km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
50°3'29"	-123°5'56.2"
Crossing Name	Cheakmus River
FSR #	9281
Branch #	1
Road Name	DAISY 01
User km	1
Previous Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	2
Total Length (m)	63.6
Deck Width (m)	4.32

Updated Data

Latitude	Longitude
50°3'26.92"	-123°5'54.23"
HD Diff. (m)	75.3
Accuracy (m)	5

Inspection

Date of Inspection 2020-09-08 5:13:27 PM

Recommended Next Inspection Year 2021

Inspector Name Greg Dohm

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Curb rails and curb blocks need replacing ASAP for continued use. Rotting and loose and missing blocks.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021

Load Rating: L75 or 68 tonnes

Next Inspection: 2021

Comments: No posts approach barriers pushed into ditch to be reinstalled. Curb rails being replaced with HSS in 2021.



P.Eng Seal

SQ-3127
SQ-3127

DAISY 01 1km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor

Pushed into ditch on woodside and townside

Posted Load Rating 68

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

SQ-3127
SQ-3127

DAISY 01 1km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Curb rails need replacing ASAP for continued use. Rotting and loose and missing blocks.

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Poor Curb rails need replacing ASAP for continued use.

Gravel Depth (mm)

Pier Deck

SQ-3127
SQ-3127

DAISY 01 1km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3127
SQ-3127

DAISY 01 1km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)

High Water ☐

Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance (m)

Ice ☐

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Full Curb Replacement. . Priority:High	Curb rails need replacing ASAP for continued use. Rotting and loose and missing blocks.
2	
3	
4	
5	
6	
7	

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Approach Barrier



Deck



Downstream from Crossing



Upstream from Crossing



Deck



Deck



Guard Rail



Approach from Right Bank when facing downstream



Approach Barrier



Downstream Profile - downstream span 1



Downstream Profile



Downstream Profile



Superstructure



Pier



Pier



Upstream Profile



Upstream Profile



Upstream Profile



Left Bank Abutment when facing downstream