

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 49°42'19" Longitude -123°6'52.3"

Crossing Name Stawamus River

FSR # 9283 Branch # 1

Road Name MAMQUAM 01

User km 4.5

Previous Load Rating (tonnes) 136

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 24.8

Deck Width (m) 4.88

Updated Data

Latitude 49°42'19.43" Longitude -123°6'51.62"

HD Diff. (m) 19.0 Accuracy (m) 5

Inspection

Date of Inspection 2020-09-08 2:32:19 PM

Recommended Next Inspection Year 2021

Inspector Name Greg Dohm

Inspection Company FLNRORD

Serial/ID Plate

Inspector Comments

Bearings corroding. Minor amount of corrosion on girders. Inspect annually. Inspect in 2021 as close proximity inspection with ultrasonic tester.


P.Eng Comments:

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021

Load Rating: L150 or 136 tonnes

Next Inspection: 2021

Comments: Inspect annually due to corroding bearing places and girders. FLNRO to conduct close proximity inspection to determine extent of corrosion.



P.Eng Seal

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 136

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Fair

Caps or Sills N/A

Piles or Posts Fair Slight corrosion

Ballast Wall Fair

Wing Wall Fair

Bracing Fair

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair Bearing look ok except for significant corrosion

Corrosion Protection Poor Bearings corroding. Minor amount of corrosion on girders

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair Bearing plates corroding and girder

Diaphragms Fair

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	6	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	6	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1 Structure. . . Priority:

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Bearings corroding. Minor amount of corrosion on girders. Stiffeners have some corrosion too.	Anually

2

3



Approach from Left Bank when facing downstream



Deck



Deck



Downstream from Crossing



Upstream from Crossing



Approach from Right Bank when facing downstream



Bearing



Upstream Profile



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Bearing - townside corroding bearing



Right Bank Abutment when facing downstream



Downstream Profile



Bearing



Superstructure



Upstream Profile



Bearing - u/s woodside corroding bearing plates