

SQ-3155
SQ-3155

SQUAMISH RIVER 53.1km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
50°3'51.8"	-123°20'.77"
Crossing Name	Shovel Nose Creek
FSR #	9160
Branch #	1
Road Name	SQUAMISH RIVER
User km	53.1
Previous Load Rating (tonnes)	62
Structure Class	Temporary Bridge
Portable	N
Superstructure	Rail Car
Deck Type	Timber - Treated
Abutment Left	Sill -Temporary Materials
Abutment Right	Sill -Temporary Materials
Spans	1
Total Length (m)	17.5
Deck Width (m)	4.8

Updated Data

Latitude	Longitude
50°3'51.88"	-123°20'1.31"
HD Diff. (m)	11.0
Accuracy (m)	6

Inspection

Date of Inspection 2020-09-08 11:36:09 AM

Inspector Name Gino Fournier

Recommended Next Inspection Year

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Consider downrating due to rails not being replaced as per last inspections.


P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021

Load Rating: BCL625 or 63 tonnes

Next Inspection: 2021

Comments: Replace all rail components prior to next industrial use as they are very rotten.



P.Eng Seal

SQ-3155
SQ-3155

SQUAMISH RIVER 53.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good Noposts

Posted Load Rating 62

Road Surface Good

Abutment

Log/Timber Cribs Fair

Tie Backs Poor Getting old

Bin Wall N/A

Pier N/A

Concrete N/A

Caps or Sills Fair

Piles or Posts N/A

Ballast Wall Fair

Wing Wall N/A

Bracing N/A

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection N/A

SQ-3155
SQ-3155

SQUAMISH RIVER 53.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface	Fair	
Running Planks	Fair	4x12
Sub Deck	N/A	
Ties	Fair	8x8 treated
Nails	Fair	
Deck to Girder Bolts	Fair	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	Rotten and need to be replaced
Hand Rails/Walkouts	N/A	
Hardware	Fair	
Overall Deck Condition	Poor	Due to rails.
Gravel Depth (mm)	0	
Pier Deck	N/A	

SQ-3155
SQ-3155

SQUAMISH RIVER 53.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Railcars

Diaphragms N/A

Bracing N/A

Under Trussing N/A

Hardware Fair

Welded/grouted
shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3155
SQ-3155

SQUAMISH RIVER 53.1km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.3	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	5	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance (m)	2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. . . Priority:High	Replace all rail components prior to next industrial use as they are very rotten.

2

3

4

5

6

7

Item	Monitor Description	Frequency
1		
2		
3		




Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Downstream from Crossing



Upstream from Crossing



Guard Rail



Deck



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



2020 Inspection

CBR iPad Offline Ver 0.33

SQUAMISH RIVER 53.1km

SQ-3155
SQ-3155



Upstream Profile



Downstream Profile