

SQ-3174
SQ-3174

CHEAKAMUS/BLACKTUSK

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
50°3'9.69"	-123°2'2.8"
Crossing Name	Tributary to Cheakamus
FSR #	3077
Branch #	3
Road Name	CHEAKAMUS/BLACKTUSK
User km	3.45
Previous Load Rating (tonnes)	62
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	8
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
50°3'8.41"	-123°2'2.68"
HD Diff. (m)	39.8
Accuracy (m)	5

Inspection

Date of Inspection 2020-09-11 8:56:52 AM

Inspector Name Greg Dohm

Recommended Next Inspection Year

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

3.5km bridge closed sign at 0 km ok cheakamus fsr should be removed.

Appears upstream channel shifted and created two branches into the stream just upstream of the bridge. However, just new branch is flowing. Check with historical photos. Check change at next inspection.

Same stringers as before. See chr database. No rot.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021
Load Rating: BCL625 or 63 tonnes
Next Inspection: 2022
Comments:



P.Eng Seal

SQ-3174
SQ-3174

CHEAKAMUS/BLACKTUSK

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 27

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills Fair

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection Fair

SQ-3174
SQ-3174

CHEAKAMUS/BLACKTUSK

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface Fair

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm) 300

Pier Deck

SQ-3174
SQ-3174

CHEAKAMUS/BLACKTUSK

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs Fair

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

1

Same stringers as before. See cbr database.

SQ-3174
SQ-3174

CHEAKAMUS/BLACKTUSK

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.1	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	1.5	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance (m)	0.1	Ice	☐		
Comments	Shifting upstream stream channel.				

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Appears upstream channel shifted and created two branches into the stream just upstream of the bridge. However, just new branch is flowing. Check with historical photos. Check change at next inspection.	Routine Inspection
2		
3		



Approach from Right Bank when facing downstream



Load Rating Sign



Deck



Approach from Right Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Upstream from Crossing



Upstream from Crossing



Upstream from Crossing



Upstream Profile



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



2020 Inspection

CBR iPad Offline Ver 0.33

CHEAKAMUS/BLACKTUSK

SQ-3174
SQ-3174



Downstream from Crossing



Upstream from Crossing