

SQ-3184
SQ-3184

SQUAMISH RIVER 35.5km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°55'59.59"	-123°17'30.4"
Crossing Name	Powerhouse
FSR #	9160
Branch #	1
Road Name	SQUAMISH RIVER
User km	35.5
Previous Load Rating (tonnes)	62
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Timber - Untreated
Abutment Left	Concrete Cast in Place
Abutment Right	Concrete Cast in Place
Spans	2
Total Length (m)	45.4
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
49°55'59.8"	-123°17'30.47"
HD Diff. (m)	6.5
Accuracy (m)	6

Inspection

Date of Inspection 2020-09-08 12:54:24 PM

Inspector Name Gino Fournier

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD


P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 7, 2021

Load Rating: BCL625 or 63 tonnes

Next Inspection: 2022

Comments: cross-ties getting old and may be deteriorating indicated by planks lifting. Plan to replace deck in relatively near future.



P.Eng Seal

SQ-3184
SQ-3184

SQUAMISH RIVER 35.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good Noposts

Posted Load Rating 62

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier Fair

Concrete Fair

Caps or Sills Fair

Piles or Posts N/A

Ballast Wall Fair

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection N/A

SQ-3184
SQ-3184

SQUAMISH RIVER 35.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface	Fair	
Running Planks	Fair	
Sub Deck	N/A	
Ties	Poor	8x12 treated 400 c/c. Deck boards moving up and down with traffic. Nails starting to get loose.
Nails	Poor	Deck boards moving up and down with traffic. Nails8x12 treated 400 c/c. Deck boards moving up and down with traffic. Nails starting to get loose. starting to get loose.
Deck to Girder Bolts	Fair	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Fair	12x12 treated
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Fair	
Gravel Depth (mm)	0	
Pier Deck	N/A	

SQ-3184
SQ-3184

SQUAMISH RIVER 35.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Diaphragms Fair

Bracing Fair

Under Trussing N/A

Hardware Fair

Welded/grouted
shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3184
SQ-3184

SQUAMISH RIVER 35.5km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	2	High Water	☒	Debris	☐
Estimated Present Water Level Width (m)	30	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Ties may be getting old. Planks starting to lift.	Routine Inspection

2

3



2020 Inspection

CBR iPad Offline Ver 0.33

SQUAMISH RIVER 35.5km

SQ-3184
SQ-3184



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Downstream from Crossing



Upstream from Crossing



Deck



Pier



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream