

SQ-3205
SQ-3205

SLOQUET CREEK MAIN 12km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°43'2.94"	-122°21'43.3"
Crossing Name	Tributary to Sloquet
FSR #	6780
Branch #	1
Road Name	SLOQUET CREEK MAIN
User km	12
Previous Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	N
Superstructure	Rail Car
Deck Type	Concrete Removable
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	17.2
Deck Width (m)	4.3

Updated Data

Latitude	Longitude
49°43'1.95"	-122°21'43.01"
HD Diff. (m)	31.4
Accuracy (m)	5

Inspection

Date of Inspection 2020-09-09 2:40:12 PM

Inspector Name Greg Dohm

Recommended Next Inspection Year

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Curb Blocks ok but curb rails poor and need replacing ASAP for continued use.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 11, 2021
Load Rating: L75 or 68 tonnes
Next Inspection: 2021
Comments: Replace curb rails asap for continued use.



P.Eng Seal

SQ-3205
SQ-3205

SLOQUET CREEK MAIN 12km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 68

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Fair

Caps or Sills Fair

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection Fair

SQ-3205
SQ-3205

SLOQUET CREEK MAIN 12km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Curb Blocks ok but curb rails poor and need replacing

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3205
SQ-3205

SLOQUET CREEK MAIN 12km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders

Rail car

Diaphragms

Bracing

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3205
SQ-3205

SLOQUET CREEK MAIN 12km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	0	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance (m)	0.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. . 1 . Priority:High	Curb Blocks ok but curb rails poor and need replacing

2

3

4

5

6

7

Item	Monitor Description	Frequency
1		
2		
3		



Deck



Approach from Right Bank when facing downstream



Guard Rail



Upstream from Crossing



Guard Rail



Approach from Right Bank when facing downstream



Deck



Downstream from Crossing



Downstream Profile



Downstream Profile



Upstream from Crossing



Downstream from Crossing



Upstream Profile



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Bearing



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Deck



Deck