

SQ-3229
SQ-3229

HURLEY 01 4.7km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
50°32'51"	-123°5'1.41"
Crossing Name	Twenty Five Mile (Jim) Creek
FSR #	7973
Branch #	1
Road Name	HURLEY 01
User km	4.7
Previous Load Rating (tonnes)	68
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Steel (non-corrugated)
Opening Height (mm)	2100
Opening Width (mm)	2100
Inlet Cover (mm)	1000
Outlet Cover (mm)	1200
Culvert Gradient %	
Culvert Length (m)	6.3

Updated Data

Latitude	Longitude
50°32'51.32"	-123°5'2.28"
HD Diff. (m)	19.8
Accuracy (m)	5

Inspection

Date of Inspection 2020-09-09 2:47 PM

Inspector Name Gino Fournier


Inspector Comments

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 11, 2021
Load Rating: L75 or 68 tonnes
Next Inspection: 2023
Comments:



P.Eng Seal

SQ-3229
SQ-3229

HURLEY 01 4.7km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Unrated** **None**

Posted Load Rating

Road Surface **Fair**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall **N/A**

Bracing

Hardware

Fill **Good**

Riprap **Good**

Bearings

Corrosion Protection

SQ-3229
SQ-3229

HURLEY 01 4.7km

2020 Inspection

CBR iPad Offline Ver 0.33



Culvert

Baffles N/A

Bolted Connections N/A

Coating N/A

Coupled Connections N/A

Embedment Materials N/A

Fill Good

Floor Fair

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Fair

Rip Rap Good

Roof Fair

Sidewalls N/A

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

SQ-3229
SQ-3229

HURLEY 01 4.7km

2020 Inspection

CBR iPad Offline Ver 0.33



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3229
SQ-3229

HURLEY 01 4.7km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m) .2

High Water ☐

Debris ☐

Estimated Present Water Level Width (m) 2

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance (m) 1.2

Ice ☐

Comments

Repairs and Monitoring

Repair Item Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



2020 Inspection

CBR iPad Offline Ver 0.33

HURLEY 01 4.7km

SQ-3229
SQ-3229



Inlet



Upstream from Crossing



Downstream from Crossing