

SQ-3234
SQ-3234-A

LILLOOET WEST 02 57.4km

2020 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
50°5'48.3"	-122°32'23.6"
Crossing Name	Trib to Lillooet Lake
FSR #	8407
Branch #	2
Road Name	LILLOOET WEST 02
User km	57.4
Previous Load Rating (tonnes)	5
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Sill - Permanent Materials
Abutment Right	Sill - Permanent Materials
Spans	1
Total Length (m)	7.5
Deck Width (m)	4.3

Updated Data

Latitude	Longitude
50°5'47.44"	-122°32'24.25"
HD Diff. (m)	29.5
Accuracy (m)	5

Inspection

Date of Inspection 2020-09-10 11:51:58 AM

Inspector Name Greg Dohm

Recommended Next Inspection Year


Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

See previous inspection for diameters. Rot varies from 25 mm to 80mm on 3 stringers drilled on upstream half of bridge. Conk growths on some of the stringers.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Jan. 11, 2021
Load Rating: 5 tonnes
Next Inspection: 2022
Comments:



P.Eng Seal

SQ-3234
SQ-3234-A

LILLOOET WEST 02 57.4km

2020 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 20 Changed to 5 tonnes during inspection

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills Fair

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair

Corrosion Protection

SQ-3234
SQ-3234-A

LILLOOET WEST 02 57.4km

2020 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface Fair

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm) 300

Pier Deck

SQ-3234
SQ-3234-A

LILLOOET WEST 02 57.4km

2020 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs Fair

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

1

Sp

N

See previous inspection for diameters. Rot

SQ-3234
SQ-3234-A

LILLOOET WEST 02 57.4km

2020 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	0.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3



Approach from Right Bank when facing downstream



Deck



Downstream Profile



Downstream from Crossing



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Outlet



Approach from Left Bank when facing downstream



Deck



Upstream from Crossing



Upstream Profile



Upstream Profile



Left Bank Abutment when facing downstream



Load Rating Sign



Approach from Right Bank when facing downstream