

SQ-3044
SQ-3044

LILLOOET RIVER 01 10.4km

2021 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 50°32'10.29" Longitude -123°4'18.7"

Crossing Name Sampson Creek

FSR # 6123 Branch # 1

Road Name LILLOOET RIVER 01

User km 10.4

Previous Load Rating (tonnes) 68

Structure Class Temporary Bridge

Portable N

Superstructure Rail Car

Deck Type Timber - Untreated

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 16

Deck Width (m) 4.9

Updated Data

Latitude 50°32'10.08" Longitude -123°4'18.69"

HD Diff. (m) 6.8 Accuracy (m) 6

Inspection

Date of Inspection 2021-09-21 11:40:28 AM

Inspector Name Greg Dohm


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Oct. 14, 2021
Load Rating: L75 or 68 tonnes
Next Inspection: 2023
Comments:



P.Eng Seal

SQ-3044
SQ-3044

LILLOOET RIVER 01 10.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor Missing

Posted Load Rating 68

Road Surface Fair

Abutment

Log/Timber Cribs Fair

Tie Backs Poor Poor on wood side. Bearing is set on sill log behind abutments

Bin Wall

Pier

Concrete

Caps or Sills Fair

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Fair

Fill Fair

Riprap N/A

Bearings Fair

Corrosion Protection Fair

SQ-3044
SQ-3044

LILLOOET RIVER 01 10.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties Fair

Nails Fair

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3044
SQ-3044

LILLOOET RIVER 01 10.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair

Diaphragms

Bracing Fair

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3044
SQ-3044

LILLOOET RIVER 01 10.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	10	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	1.7	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3



Approach from Left Bank when facing downstream



Deck



Downstream from Crossing



Upstream from Crossing



Approach from Right Bank when facing downstream



Guard Rail



Guard Rail



Downstream from Crossing



Deck



Left Bank Abutment when facing downstream



Upstream Profile



Left Bank Abutment when facing downstream



Bearing



Right Bank Abutment when facing downstream