

SQ-3077
SQ-3077

5.8km

2021 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 50°10'47.3" Longitude -122°56'17.2"

Crossing Name Sixteen Mile Creek

FSR # 7910 Branch # 3

Road Name

User km 5.8

Previous Load Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Removable

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 14.3

Deck Width (m) 4.32

Updated Data

Latitude 50°10'46.66" Longitude -122°56'15.37"

HD Diff. (m) 41.3 Accuracy (m) 5

Inspection

Date of Inspection 2021-09-23 8:54:29 AM

Inspector Name Greg Dohm

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Oct. 14, 2021
Load Rating: L75 or 68 tonnes
Next Inspection: 2024
Comments:



P.Eng Seal

SQ-3077
SQ-3077

5.8km

2021 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated None

Posted Load Rating 68

Road Surface Poor Lots of large pot holes

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills

Piles or Posts Good

Ballast Wall Good

Wing Wall Good

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

SQ-3077
SQ-3077

5.8km

2021 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair Lots of large pot holes

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets

Deck Joints Poor Should be sealed to limit sediment into stream

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3077
SQ-3077

5.8km

2021 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Good

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3077
SQ-3077

5.8km

2021 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Joint replacement. 1 m². Priority:Low	Slab joints should be sealed
2 Approach. Approach surfacing grading. 1 m. Priority:Low	Fill and grade pot holes
3 Approach. Area/sight line brushing. 1 m². Priority:Medium	
4	
5	
6	
7	

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Right Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



Approach from Left Bank when facing downstream



Upstream Profile



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Outlet



Inlet



Downstream Profile



Upstream Profile