

SQ-3081
SQ-3081

ROGERS 01 9km

2021 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
50°3'26.89"	-122°25'28.2"
Crossing Name	Trib to Rogers Creek
FSR #	7976
Branch #	1
Road Name	ROGERS 01
User km	9
Previous Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	N
Superstructure	Rail Car
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	17.2
Deck Width (m)	4.8

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5572372.3
Accuracy (m)	

Timber – Untreated

Inspection

Date of Inspection 2021-09-21 10:17 AM

Inspector Name Malcolm Schulz


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2024

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Oct. 14, 2021
Load Rating: L75 or 68 tonnes
Next Inspection: 2023
Comments:



P.Eng Seal

SQ-3081
SQ-3081

ROGERS 01 9km

2021 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☐ 0 ☒ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Fair**

Posted Load Rating **68**

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills **Fair**

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill **Good**

Riprap **Fair** Some erosion under first row of riprap on woods side. No change since last inspection

Bearings

Corrosion Protection

SQ-3081
SQ-3081

ROGERS 01 9km

2021 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface **Good**

Running Planks **Good**

Sub Deck **Good**

Ties **Good**

Nails **Good**

Deck to Girder Bolts **Good**

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SQ-3081
SQ-3081

ROGERS 01 9km

2021 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders **Good**

Diaphragms

Bracing **Good**

Under Trussing

Hardware **Good**

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3081
SQ-3081

ROGERS 01 9km

2021 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	4	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Erosion on left side to be monitored under first row of riprap	Routine Inspection

2

3



Approach from Right Bank when facing downstream



Approach from Right Bank when facing downstream



Bearing



Bearing



Downstream Profile



Inlet



Outlet



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Deck



Deck