

SQ-3116
SQ-3116

LILLOOET WEST 01 22.4km

2021 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 49°51'39.49" Longitude -122°17'59.3"

Crossing Name Trib to Lillooet River

FSR # 8407 Branch # 1

Road Name LILLOOET WEST 01

User km 22.4

Previous Load Rating (tonnes) 150

Structure Class Temporary Bridge

Portable Y

Superstructure Steel Box Beam

Deck Type Steel

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 12.2

Deck Width (m) 4.87

Updated Data

Latitude 49°51'39.7" Longitude -122°17'59.55"

HD Diff. (m) 8.0 Accuracy (m) 9

Inspection

Date of Inspection 2021-08-25 1:11:27 PM

Recommended Next Inspection Year 2023

Inspector Name Forrest Simpson

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Bridge on active channel and rock fall zone at right approach. Add approach barriers and signage.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Nov. 12, 2021
Load Rating: L165 or 150 tonnes
Next Inspection: 2023
Comments:



P.Eng Seal

SQ-3116
SQ-3116

LILLOOET WEST 01 22.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2 Not mounted

Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Poor None

Posted Load Rating 150

Road Surface Fair Right approach in rock fall zone

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills Unrated Log sills wrapped In geotextile, can't access

Piles or Posts

Ballast Wall Fair Retaining fill

Wing Wall

Bracing

Hardware Unrated Fill covering lag bolts

Fill Good

Riprap Fair

Bearings Good

Corrosion Protection

SQ-3116
SQ-3116

LILLOOET WEST 01 22.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface **Good** Right approach in rock fall zone

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate **Good**

Gravel Surface

Curb Rail/Blocks/Posts **Good** Damage at end from poor alignment

Hand Rails/Walkouts

Hardware

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SQ-3116
SQ-3116

LILLOOET WEST 01 22.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Good Steel box asp

Diaphragms Unrated Steel box

Bracing Unrated Steel box

Under Trussing

Hardware Unrated Steel box

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3116
SQ-3116

LILLOOET WEST 01 22.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.2	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Add Warning Signs. 2 # of signs. Priority:High	Add delineators
2 Approach. Approach fenders (install). 4 # of units. Priority:High	Install approach barriers

3

4

5

6

7

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Deck



Approach from Right Bank when facing downstream



Approach from Right Bank when facing downstream



Structure ID



Upstream Profile



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Downstream from Crossing



Upstream from Crossing



Bearing