

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2021 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°42'19"	-123°6'52.3"
Crossing Name	Stawamus River
FSR #	9283
Branch #	1
Road Name	MAMQUAM 01
User km	4.5
Previous Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	24.8
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
49°42'19.21"	-123°6'52.2"
HD Diff. (m)	6.7
Accuracy (m)	9

Inspection

Date of Inspection 2021-09-20 12:51:28 PM

Recommended Next Inspection Year

Inspector Name Greg Dohm

Inspection Company FLNRORD


Inspector Comments Serial/ID Plate

30mm thick of bottom flange after peeling off spalled corroded metal. Plan to do close proximity inspection to quantify extent of corrosion . Find out more about calcium chloride and it's affect on corrosion rates.

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Oct. 15, 2021 Load Rating: L150 or 136 tonnes
Next Inspection: 2022

Comments:Ministry plan to do close proximity inspection to quantify extent of corrosion and upgrade or replacement options that may be necessary.



P.Eng Seal

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2021 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 136

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts Fair Corroding bearing plates - monitor

Ballast Wall Fair

Wing Wall Fair

Bracing Fair

Hardware Fair

Fill Fair

Riprap Fair

Bearings Fair Corroding bearing plates - monitor

Corrosion Protection Poor Corroding - monitor

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2021 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Fair

Grout Pockets Fair

Deck Joints Fair

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Fair

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2021 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Fair Corroding quite badly

Diaphragms Fair Corroding quite badly

Bracing Fair Corroding quite badly

Under Trussing

Hardware Fair

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3130
SQ-3130

MAMQUAM 01 4.5km

2021 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	7	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1 Corroding steel all over bridge.

Anually

2

3



Approach from Right Bank when facing downstream



Deck



Upstream from Crossing



Downstream from Crossing



2021 Inspection

CBR iPad Offline Ver 0.33

MAMQUAM 01 4.5km

SQ-3130
SQ-3130



Deck



Approach from Left Bank when facing downstream



Upstream Profile



Bearing



Bearing - woods



Bearing



Left Bank Abutment when facing downstream



Downstream Profile



Bearing



Bearing - town us



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Bearing - town upstream