

SQ-3204
SQ-3204

SLOQUET CREEK MAIN 16.4km

2021 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude	Longitude
49°41'2.65"	-122°23'30.6"
Crossing Name	Sloquet Tributary
FSR #	6780
Branch #	1
Road Name	SLOQUET CREEK MAIN
User km	16.4
Previous Load Rating (tonnes)	68
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	30.5
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°41'4.28"	-122°23'31.37"
HD Diff. (m)	52.4
Accuracy (m)	8

Inspection

Date of Inspection 2021-08-20 12:06:57 PM

Recommended Next Inspection Year 2024

Inspector Name Forrest Simpson

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Replace all guard rails. Evidence of recent industrial use on road. Minor damage from walking tracked equipment on deck

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Nov. 12, 2021
Load Rating: L75 or 68 tonnes
Next Inspection: 2022
Comments: replace guard rails



P.Eng Seal

SQ-3204
SQ-3204

SLOQUET CREEK MAIN 16.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Poor

Tight horizontal curve.

Bridge Ahead Signs
Missing

☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Minor

Delineator Missing
Left

☐ 0 ☒ 1 ☐ 2

Delineator Missing
Right

☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Concrete no posts

Posted Load Rating 68

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Ballast wall

Caps or Sills

Piles or Posts Good

Ballast Wall Good

Inverted?

Wing Wall

Bracing Good

Hardware Good

Fill Good

Riprap Good

Minimal, but on bedrock and well back

Bearings Good

Corrosion Protection Unrated

Not visible

SQ-3204
SQ-3204

SLOQUET CREEK MAIN 16.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets **Good** Where visible

Deck Joints **Good** Where visible

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Poor** Rotten

Hand Rails/Walkouts

Hardware **Fair**

Overall Deck Condition **Poor** Due to guard rails

Gravel Depth (mm)

Pier Deck

SQ-3204
SQ-3204

SLOQUET CREEK MAIN 16.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Good

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3204
SQ-3204

SLOQUET CREEK MAIN 16.4km

2021 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.5	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	4	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Full Curb Replacement. . Priority:High	Resolve all guard rails

2

3

4

5

6

7

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Right Bank when facing downstream



Deck



Guard Rail



Approach from Left Bank when facing downstream



Approach from Left Bank when facing downstream



Deck, damage to underside. Right bank u/s



Upstream Profile



Right Bank Abutment when facing downstream



2021 Inspection

CBR iPad Offline Ver 0.33

SLOQUET CREEK MAIN 16.4km

SQ-3204
SQ-3204



Superstructure



Left Bank Abutment when facing downstream



Structure ID



Downstream Profile




Upstream from Crossing



Downstream from Crossing



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



2021 Inspection

CBR iPad Offline Ver 0.33

SLOQUET CREEK MAIN 16.4km

SQ-3204
SQ-3204



Ballast wall