

SQ-3018
SQ-3018

RUTHERFORD 01 15.7km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 50°18'30.49"
Longitude -123°3'35.9"

Site Status Active

Insp. Status Inspect

Crossing Name Tributary to Rutherford Creek

FSR # 5673 Branch # 1

Road Name RUTHERFORD 01

User km 15.7

Previous Load
Rating (tonnes) 63

Structure Class Temporary Bridge

Portable N

Superstructure Rail Car

Deck Type Concrete Removable

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 17.2

Deck Width (m) 4.8

Updated Data

Latitude 0°0'0"
Longitude 0°0'0"

HD Diff. (m) 5600313.5 Accuracy (m)

Inspection

Date of Inspection 2022-09-28 3:32:45 PM

Inspector Name Forrest Simpson

Inspector Comments
Serial/ID Plate

Saw dust (from insects) noted in right bank crib logs.

Recommended Next Inspection 2024

Inspection Company MoF

P.Eng Comments

Load Rated by: MFLNRORD, Greg Dohm, PEng., Oct. 4, 2022

Load Rating: BCL625 or 63 tonnes

Next Inspection: 2024

Comments: complete noted repairs including complete curb replacement prior to industrial use.



PERMIT TO
PRACTICE: 1003022

SQ-3018
SQ-3018

RUTHERFORD 01 15.7km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

Curve

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Poor

Missing

Posted Load Rating 63

Road Surface Fair

Minor potholes town

Abutment

Log/Timber Cribs Fair

Tie Backs Fair

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Good

Fill Good

Riprap Fair Large but poorly graded

Bearings Good

Corrosion Protection

SQ-3018
SQ-3018

RUTHERFORD 01 15.7km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface **Good** Minor potholes town

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts **Good** Clips

Concrete Deck **Fair**

Grout Pockets

Deck Joints **Fair**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Poor** Damaged rails, rotten risers

Hand Rails/Walkouts

Hardware **Fair** Loose rails

Overall Deck Condition **Fair**

Gravel Depth (mm)

Pier Deck

SQ-3018
SQ-3018

RUTHERFORD 01 15.7km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Fair

Old rail cars

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3018
SQ-3018

RUTHERFORD 01 15.7km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.3	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	7	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	2.2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. . 2 . Priority:Low	
2 Approach. Add Warning Signs. 2 # of signs. Priority:High	Post delineators
3 Structure. Full Curb Replacement. . Priority:High	Replace all guard rail components
4 Approach. Approach fenders (install). 4 # of units. Priority:High	Install approach barriers

5

6

7

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Deck



Guard Rail



Deck



Approach from Right Bank when facing downstream



Left Bank Abutment when facing downstream



Superstructure



Superstructure



Right Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Upstream Profile



Left Bank Abutment when facing downstream, saw dust.