

SQ-3035
SQ-3035

LILLOOET RIVER 01 0.1km

2022 Inspection

CBR iPad Offline Ver 0.33



CBR Data

Latitude 50°29'27.09" Longitude -122°58'12.5"

Crossing Name Salmon River

FSR # 6123 Branch # 1

Road Name LILLOOET RIVER 01

User km 0.1

Previous Load Rating (tonnes) 54

Structure Class Permanent Bridge

Portable N

Superstructure Concrete Box Beam

Deck Type Concrete

Abutment Left Concrete Precast

Abutment Right Concrete Precast

Spans 1

Total Length (m) 12.5

Deck Width (m) 4.8

Updated Data

Latitude 50°29'27.14" Longitude -122°58'12.23"

HD Diff. (m) 5.4 Accuracy (m) 6

Inspection

Date of Inspection 2022-10-19 3:47:06 PM

Inspector Name Gino Fournier


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: MOF, Greg Dohm, PEng., Oct. 25, 2022
Load Rating: L60 or 54 tonnes
Next Inspection: 2023
Comments: replace curbs



P.Eng Seal

SQ-3035
SQ-3035

LILLOOET RIVER 01 0.1km

2022 Inspection

CBR iPad Offline Ver 0.33



Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2 Not needed. Nice straight approach

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated None and not needed

Posted Load Rating 54

Road Surface Good Paved

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier N/A

Concrete Good

Caps or Sills Good

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Good

Riprap N/A

Bearings Good

Corrosion Protection N/A

SQ-3035
SQ-3035

LILLOOET RIVER 01 0.1km

2022 Inspection

CBR iPad Offline Ver 0.33



Deck

Running Surface Good Paved

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Good

Grout Pockets Good

Deck Joints Good

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Poor Fully rotten

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Poor Due to rails rotten

Gravel Depth (mm)

Pier Deck N/A

SQ-3035
SQ-3035

LILLOOET RIVER 01 0.1km

2022 Inspection

CBR iPad Offline Ver 0.33



Steel/Concrete

Girders Good

Diaphragms N/A

Bracing N/A

Under Trussing N/A

Hardware N/A

Welded/grouted
shear connectors Good

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3035
SQ-3035

LILLOOET RIVER 01 0.1km

2022 Inspection

CBR iPad Offline Ver 0.33



Hazards

Estimated Present Water Level Depth (m)	.5	High Water	☒	Debris	☐
Estimated Present Water Level Width (m)	6	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)		Ice	☐		

Comments When old wooden substructure of old previous bridge collapses, fill will collapse in towards foundation. It would be good to check how deep the foundations of this bridge is.

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Curb Maintenance. # sites. Priority:High	Replace sideblock posts and rails both sides as they are fully rotten

2

3

4

5


6

7

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Rotten guardrails



Guard Rail



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream



Cracked and rotten post rails