

SQ-3079
SQ-3079

HURLEY 10.1km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 50°33'34.2" Longitude -123°1'30"

Site Status Active

Insp. Status Inspect

Crossing Name Rail Road Creek

FSR # 7973 Branch # 1

Road Name HURLEY

User km 10.1

Previous Load Rating (tonnes) 54

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Untreated

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 12.2

Deck Width (m) 4.5

Updated Data

Latitude 50°33'35.29" Longitude -123°1'30.96"

HD Diff. (m) 38.6 Accuracy (m) 6

Inspection

Date of Inspection 2022-10-20 3:58:41 PM

Inspector Name Gino Fournier


Inspector Comments Serial/ID Plate

Recommended Next Inspection

Inspection Company MoF

P.Eng Comments

Load Rated by: MOF, Greg Dohm, PEng., Oct. 25, 2022
Load Rating: L60 or 54 tonnes
Next Inspection: 2024
Comments:



PERMIT TO
PRACTICE: 1003022

SQ-3079
SQ-3079

HURLEY 10.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 54

Road Surface Fair

Abutment

Log/Timber Cribs Fair 3 high cw both sides

Tie Backs Fair

Bin Wall N/A

Pier N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Fair

Riprap Fair

Bearings N/A

Corrosion Protection N/A

SQ-3079
SQ-3079

HURLEY 10.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface Fair

Running Planks Fair

Sub Deck Fair

Ties Fair

Nails Fair

Deck to Girder Bolts Fair

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Fair

Will need to be replaced in near future

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck N/A

SQ-3079
SQ-3079

HURLEY 10.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Fair

Diaphragms Fair

Bracing Fair

Under Trussing N/A

Hardware Fair

Welded/grouted
shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3079
SQ-3079

HURLEY 10.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	4.5	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Minor redecking (wearing surface). m. Priority:Medium	Will need to be replaced over next 2 years with guardrails.

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------


1

2

3



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Upstream from Crossing



Downstream from Crossing



Worn running deck



Deck



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream

SQ-3079
SQ-3079

HURLEY 10.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck