

SQ-3133
SQ-3133

MAMQUAM 14.2km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°43'2.08"
Longitude -123°0'.97"

Site Status Active

Insp. Status Inspect

Crossing Name Trib to Mamquam

FSR # 9283 Branch # 1

Road Name MAMQUAM

User km 14.2

Previous Load Rating (tonnes) 150

Structure Class Major Culvert

Culvert Type Round

Culvert Material Steel (non-corrugated)

Opening Height (mm) 1830

Opening Width (mm) 1830

Inlet Cover (mm) 900

Outlet Cover (mm) 1000

Culvert Gradient % 8

Culvert Length (m) 11

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5534498.6 Accuracy (m)

Inspection

Date of Inspection 2022-09-28 1:23:24 PM

Inspector Name Mitch Lowe

Recommended Next Inspection 2024

Inspection Company MoF

Inspector Comments

Partially infilled culvert under old log bridge. Inlet subject to erosion. Low risk.


P.Eng Comments

Load Rated by: MOF, Greg Dohm, PEng., Oct. 14, 2022

Load Rating: L150 or 136 tonnes

Next Inspection: 2025

Comments:



PERMIT TO
PRACTICE: 1003022

SQ-3133
SQ-3133

MAMQUAM 14.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Fair**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Fair**

Posted Load Rating

Road Surface **Fair**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill **Fair** Some erosion occurring at inlet

Riprap **Fair**

Bearings

Corrosion Protection

SQ-3133
SQ-3133

MAMQUAM 14.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert

Baffles

Bolted Connections

Fair

Old riveted culvert

Coating

Coupled Connections

N/A

Old riveted culvert

Embedment Materials

Fill

Fair

Some erosion occurring at inlet

Floor

Fair

Footing

Head Walls

Inlet

Poor

Old log bridge holding up inlet fill is rotting.

Outlet

Poor

Old log bridge holding up inlet fill is rotting.

Overall

Rip Rap

Fair

Roof

Fair

Sidewalls

Fair

Trash Rack

Weirs/Backwater
Structures

Wing Walls

SQ-3133
SQ-3133

MAMQUAM 14.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SQ-3133
SQ-3133

MAMQUAM 14.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	High Water	☐	Debris	☒
Estimated Present Water Level Width (m)	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance	Ic	☐		
Comments				

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3



Inlet



Culvert Barrel



Inlet



Outlet