

SQ-3228
SQ-3228

HURLEY 4.2km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 50°32'48.69" Longitude -123°5'4"

Site Status Active

Insp. Status Do Not Inspect

Crossing Name Twenty Five Mile (Jim) Creek

FSR # 7973 Branch # 1

Road Name HURLEY

User km 4.2

Previous Load Rating (tonnes) 63

Structure Class Temporary Bridge

Portable N

Superstructure Log Stringers

Deck Type Gravel

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 2.4

Deck Width (m) 6.3

Updated Data

Latitude 50°32'49.18" Longitude -123°5'3.38"

HD Diff. (m) 19.3 Accuracy (m) 6

Inspection

Date of Inspection 2022-10-20 4:25:38 PM

Inspector Name Gino Fournier

Inspector Comments Serial/ID Plate

Recommended Next Inspection

Inspection Company MoF


P.Eng Comments

Load Rated by: MOF, Greg Dohm, PEng., Oct. 26, 2022

Load Rating: BCL625 or 63 tonnes

Next Inspection: inspect with road inspections.

Comments: Replace WBC with 1800 dia. CSP culvert. Install with 3m x 3m x 1m deep inlet sump, with riprap protection at both inlet and outlet slopes, minimum 500 cover.



PERMIT TO
PRACTICE: 1003022

SQ-3228
SQ-3228

HURLEY 4.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2 Culvert width of road. No signage needed

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Fair**

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

SQ-3228
SQ-3228

HURLEY 4.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface Good

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails

Deck to Girder Bolts N/A

Concrete Deck N/A

Grout Pockets N/A

Deck Joints N/A

Steel Deck Plate N/A

Gravel Surface Good

Curb Rail/Blocks/Posts N/A

Hand Rails/Walkouts N/A

Hardware N/A

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck N/A

SQ-3228
SQ-3228

HURLEY 4.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SQ-3228
SQ-3228

HURLEY 4.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	.1	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	2	Aggradation	☒	Scour	☒
Estimated High Water Level Clearance	0	Ic	☐		

Comments See photo comments. Structure needs to be replaced as it's plugged and sill erosion is occurring.

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. . . Priority:High	Replace with cmp.

2

3

4

5

6

7

Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Downstream from Crossing



Upstream from Crossing



Inlet 50% plugged



Inlet



Inlet erosion behind sill log upstream left side



Downstream Profile