

Structure #	Crossing Name	Forest Service Road	User km	CBR km		
61-046	Coglistiko River	Michelle-Coglistiko	23	23.2		



Figure 1-1: Upstream elevation.



Figure 1-2: Downstream elevation.



Figure 1-3: Looking towards camp end.



Figure 1-4: Looking towards woods end.



Figure 1-5: Looking upstream.



Figure 1-6: Looking downstream.

Structure #	Crossing Name	Forest Service Road	User km	CBR km		
61-046	Coglistiko River	Michelle-Coglistiko	23	23.2		



Figure 1-7: Damaged camp end downstream delineator.



Figure 1-8: Woods end downstream delineator.




Figure 1-9: Typical deck condition.



Figure 1-10: Typical end of deck condition.



Figure 1-11: Woods end upstream curb damaged.



Figure 1-12: Typical pockets of rot on bridge curb; upstream curb shown.

Structure #	Crossing Name	Forest Service Road	User km	CBR km		
61-046	Coglistiko River	Michelle-Coglistiko	23	23.2		



Figure 1-13: Typical longitudinal checks on bridge curb; downstream curb shown.



Figure 1-14: Middle bridge curb rail with one unsupported end; typical on both curbs.



Figure 1-15: Downstream curb anchor near camp end missing nut and washer.



Figure 1-16: Girder 1 upstream face.



Figure 1-17: Girder 2 downstream face.



Figure 1-18: Girder 3 upstream face.