

Structure #	Crossing Name	Forest Service Road	User km	CBR km		
61-046	Coglistiko River	Michelle-Coglistiko	23	23.2		



Figure 1-19: Girder 4 downstream face.



Figure 1-20: Typical downstream connection of diaphragm.




Figure 1-21: Typical underside of deck condition.



Figure 1-22: Woods end abutment.



Figure 1-23: Woods end abutment.



Figure 1-24: Woods end upstream wing wall.

Structure #	Crossing Name	Forest Service Road	User km	CBR km		
61-046	Coglistiko River	Michelle-Coglistiko	23	23.2		



Figure 1-25: Woods end downstream wing wall.



Figure 1-26: Camp end abutment.



Figure 1-27: Camp end abutment.



Figure 1-28: Camp end upstream wing wall.



Figure 1-29: Camp end downstream wing wall.