



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-078

Site #:	N3-078	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	0.40	User km:	63.32	Last Inspection Date:	2008/09/15
Project File ID #:	9699	Br.	02	Next Inspection Date:	2011/09/23
Road Name:	-SOUTH BR. A				
Crossing Name:	BLUEWATER R	Total Length (metres):	14.3		
Special Access:		Special Equipment:			
Longitude:	-117 6 27.6	Latitude:	51 40 49.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-079

Site #:	N3-079	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	1.60	User km:	64.90	Last Inspection Date:	2008/09/15
Project File ID #:	9699	Br.	02	Next Inspection Date:	2010/09/12
Road Name:	-SOUTH BR. A				
Crossing Name:	Unnamed	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-117 7 10.8	Latitude:	51 40 25.2		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: WO-2416

Site #:	N3-105	Year Superstructure Installed:	2001	Structure Type/Class:	Temporary Bridge
KM:	7.70	User km:	7.70	Last Inspection Date:	2020/09/10
Project File ID #:	7507	Br.	02	Next Inspection Date:	2022/09/10
Road Name:	-THOMPSON FALLS FSR				
Crossing Name:	Unnamed	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-116 55 37.8	Latitude:	51 30 56.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-074

Site #:	N3-074	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	0.74	User km:	3.30	Last Inspection Date:	2019/08/28
Project File ID #:	8566	Br.	01	Next Inspection Date:	2022/08/28
Road Name:	12 MILE FSR				
Crossing Name:	CANYON Cr	Total Length (metres):	17.3		
Special Access:			Special Equipment:		
Longitude:	-116 55 34.5	Latitude:	51 13 39.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-075

Site #:	N3-075	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	5.22	User km:	5.20	Last Inspection Date:	2019/08/28
Project File ID #:	8566	Br.	01	Next Inspection Date:	2022/08/28
Road Name:	12 MILE FSR				
Crossing Name:	TWELVE MILE Cr	Total Length (metres):	14.0		
Special Access:			Special Equipment:		
Longitude:	-116 54 21.8	Latitude:	51 11 35.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-001

Site #:	N3-001	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	3.00	User km:	4.30	Last Inspection Date:	2019/08/28
Project File ID #:	4170	Br.	01	Next Inspection Date:	2022/08/28
Road Name:	BEAVERFOOT				
Crossing Name:	WASHOUT Cr	Total Length (metres):	16.5		
Special Access:			Special Equipment:		
Longitude:	-116 37 34.7	Latitude:	51 12 38.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-083

Site #:	N3-083	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	9.07	User km:	10.30	Last Inspection Date:	2019/08/28
Project File ID #:	4170	Br.	01	Next Inspection Date:	2022/08/28
Road Name:	BEAVERFOOT				
Crossing Name:	FRASER Cr		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-116 34 0.0		Latitude:	51 10 24.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-002

Site #:	N3-002	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	38.74	User km:	39.10	Last Inspection Date:	2019/08/28
Project File ID #:	4170	Br.	01	Next Inspection Date:	2022/08/28
Road Name:	BEAVERFOOT				
Crossing Name:	THOMAS Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-116 16 35.0		Latitude:	51 1 21.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 24-JAN-20: JRG Jan 24, 2020 Record cap rotation at every inspection.				

Structure Name: PS-007

Site #:	N3-003	Year Superstructure Installed:	2000	Structure Type/Class:	Temporary Bridge
KM:	42.47	User km:	42.90	Last Inspection Date:	2020/09/10
Project File ID #:	4170	Br.	01	Next Inspection Date:	2022/09/10
Road Name:	BEAVERFOOT				
Crossing Name:	PAUL Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-116 14 19.1		Latitude:	50 59 57.6	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 27-FEB-17: N/A				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: WO5960

Site #:	N3-004	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	47.06	User km:	47.10	Last Inspection Date:	2020/09/10
Project File ID #:	4170	Br.	01	Next Inspection Date:	2022/09/10
Road Name:	BEAVERFOOT				
Crossing Name:	SYMOND Cr		Total Length (metres):	24.4	
Special Access:			Special Equipment:		
Longitude:	-116 11 25.3		Latitude:	50 58 21.3	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Other	# Spans: 1
Planned Inspection Comments:	IDIR\DMALWAY on 03-OCT-14: .				

Structure Name: TOC-0001

Site #:	N3-107	Year Superstructure Installed:	2012	Structure Type/Class:	Temporary Bridge
KM:	17.00	User km:	25.70	Last Inspection Date:	2020/09/10
Project File ID #:	7521	Br.	03	Next Inspection Date:	2022/09/10
Road Name:	BLACKWATER RIDGE				
Crossing Name:	Unnamed		Total Length (metres):	6.1	
Special Access:			Special Equipment:		
Longitude:	-117 22 40.5		Latitude:	51 32 3.2	
Superstructure:	Timber - untreated stringers		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 27-FEB-17: n/a				

Structure Name: 908832890

Site #:	N3-108	Year Superstructure Installed:	2012	Structure Type/Class:	Temporary Bridge
KM:	19.50	User km:		Last Inspection Date:	2020/09/10
Project File ID #:	7521	Br.	03	Next Inspection Date:	2022/09/10
Road Name:	BLACKWATER RIDGE				
Crossing Name:	Susan Lk Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-117 25 38.6		Latitude:	51 33 57.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 20-FEB-17: na				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-007

Site #:	N3-007	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	0.69	User km:	13.30	Last Inspection Date:	2019/08/28
Project File ID #:	7507	Br.	01	Next Inspection Date:	2022/08/28
Road Name:	BLAEBERRY FSR				
Crossing Name:	WILLOW BANK Cr		Total Length (metres):	7.6	
Special Access:			Special Equipment:		
Longitude:	-116 58 50.0		Latitude:	51 28 38.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 24-JAN-20: JRG Jan 24, 2020 Record lock block rotation at both abutments at every inspection.				

Structure Name: N3-008

Site #:	N3-008	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	7.77	User km:	20.40	Last Inspection Date:	2019/08/29
Project File ID #:	7507	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BLAEBERRY FSR				
Crossing Name:	Trapper Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-116 56 48.0		Latitude:	51 31 26.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-009

Site #:	N3-009	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	9.22	User km:	22.10	Last Inspection Date:	2019/08/29
Project File ID #:	7507	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BLAEBERRY FSR				
Crossing Name:	Unnamed		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-116 55 49.0		Latitude:	51 31 49.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-010

Site #:	N3-010	Year Superstructure Installed:	1989	Structure Type/Class:	Permanent Bridge
KM:	10.08	User km:	10.00	Last Inspection Date:	2019/08/29
Project File ID #:	7507	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BLAEBERRY FSR				
Crossing Name:	BLAEBERRY R #2	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-116 55 7.8	Latitude:	51 31 43.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 24-JAN-20: JRG Jan 24, 2020 Record depth and extent of left abutment scour at each inspection.				

Structure Name: N3-011

Site #:	N3-011	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	11.52	User km:	25.60	Last Inspection Date:	2019/08/29
Project File ID #:	7507	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BLAEBERRY FSR				
Crossing Name:	SPLIT Cr	Total Length (metres):	15.4		
Special Access:		Special Equipment:			
Longitude:	-116 53 56.0	Latitude:	51 31 35.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Binwall	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-015

Site #:	N3-015	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	33.50	User km:	47.40	Last Inspection Date:	2015/10/03
Project File ID #:	7507	Br.	01	Next Inspection Date:	2018/10/03
Road Name:	BLAEBERRY FSR				
Crossing Name:	Unnamed	Total Length (metres):	10.6		
Special Access:	ATV	Special Equipment:			
Longitude:	-116 44 45.0	Latitude:	51 39 14.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Missed in 2010, due to washout.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-037

Site #:	N3-037	Year Superstructure Installed:	1996	Structure Type/Class:	Major Culvert
KM:	4.07	User km:	41.00	Last Inspection Date:	2019/08/29
Project File ID #:	9699	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BLUEWATER CREEK FSR				
Crossing Name:	WHITE PINE Cr	Total Length (metres):	24.0		
Special Access:			Special Equipment:		
Longitude:	-117 17 18.3	Latitude:	51 34 47.3		
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: N3-038

Site #:	N3-038	Year Superstructure Installed:	1989	Structure Type/Class:	Temporary Bridge
KM:	10.93	User km:	48.20	Last Inspection Date:	2008/09/15
Project File ID #:	9699	Br.	01	Next Inspection Date:	2011/09/23
Road Name:	BLUEWATER CREEK FSR				
Crossing Name:	BLUEWATER R	Total Length (metres):	27.3		
Special Access:			Special Equipment:		
Longitude:	-117 16 50.5	Latitude:	51 38 3.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-039

Site #:	N3-039	Year Superstructure Installed:	1989	Structure Type/Class:	Temporary Bridge
KM:	14.12	User km:	51.00	Last Inspection Date:	2008/09/15
Project File ID #:	9699	Br.	01	Next Inspection Date:	2011/09/23
Road Name:	BLUEWATER CREEK FSR				
Crossing Name:	BLUEWATER R	Total Length (metres):	30.3		
Special Access:			Special Equipment:		
Longitude:	-117 16 28.5	Latitude:	51 39 32.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-096

Site #:	N3-096	Year Superstructure Installed:	2006	Structure Type/Class:	Permanent Bridge
KM:	0.21	User km:	19.60	Last Inspection Date:	2019/08/28
Project File ID #:	4170	Br.	06	Next Inspection Date:	2022/08/28
Road Name:	BRANCH 19.4				
Crossing Name:	Unnamed		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-116 29 7.5		Latitude:	51 6 10.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: WO-454

Site #:	N3-106	Year Superstructure Installed:	2011	Structure Type/Class:	Temporary Bridge
KM:	0.26	User km:		Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	18	Next Inspection Date:	2022/09/11
Road Name:	BUSH - BR 28				
Crossing Name:	Succour Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-117 26 47.5		Latitude:	51 39 18.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 04-NOV-14: .				

Structure Name: N3-018

Site #:	N3-018	Year Superstructure Installed:	1979	Structure Type/Class:	Permanent Bridge
KM:	0.40	User km:	3.30	Last Inspection Date:	2019/09/09
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/09/09
Road Name:	BUSH RIVER				
Crossing Name:	WAITABIT R		Total Length (metres):	46.0	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-117 10 33.7		Latitude:	51 29 57.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	1
Planned Inspection Comments:	IDIR\MIPENNER on 18-FEB-19: . IDIR\MIPENNER on 15-OCT-14: 3 year inspection interval seems too long, and bearing monitoring should start in 2015, therefore have set next insp date to 2015.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-021

Site #:	N3-021	Year Superstructure Installed:	1980	Structure Type/Class:	Major Culvert
KM:	7.75	User km:	10.70	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BUSH RIVER				
Crossing Name:	BLACKWATER Cr	Total Length (metres):	37.0		
Special Access:		Special Equipment:			
Longitude:	-117 15 34.6	Latitude:	51 31 50.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	<p>IDIR\DMALWAY on 22-FEB-17: Do the same detailed measure up in 2019 of the three sections and the bolt tearing location mapping.</p> <p>IDIR\DMALWAY on 07-JAN-16: 2016 inspection plan: Complete the same detailed inspection as 2016 for a comparison to the 2015 baseline.</p> <p>IDIR\MIPENNER on 07-JAN-16: 2015 inspection requires 2 people and detailed measurements in order to monitor inlet arch flattening, and bolt hole cracking along length of structure. Inspect annually. Inlet flattening measurements should be taken identically to the 1987 measurements shown in the pdf in general docs and photos, then submitted with the routine inspection. Bolt hole cracking and previous welded repairs need to be documented in detail, including (photos of all cracks and repairs, exact location of all cracks and repairs, typical size of cracks and repairs, sketch of complete structure showing location of cracks and repairs. This will establish a baseline for monitoring, measurement and documentation of these cracks in the future. Also, measure and document depth of cover at inlet and outlet and update cbr with this measurement.</p>				

Structure Name: N3-027

Site #:	N3-027	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	45.93	User km:	57.50	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BUSH RIVER				
Crossing Name:	HOPE Cr	Total Length (metres):	13.3		
Special Access:		Special Equipment:			
Longitude:	-117 24 5.7	Latitude:	51 46 43.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: measure curb riser spacing as they do not appear to meet ministry standard, on next inspection. DA. Feb 2014				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-024A

Site #:	N3-024	Year Superstructure Installed:	2019	Structure Type/Class:	Permanent Bridge
KM:	48.70	User km:	52.00	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BUSH RIVER				
Crossing Name:	Unnamed		Total Length (metres):	15.3	
Special Access:			Special Equipment:		
Longitude:	-117 29 45.2		Latitude:	51 44 24.9	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-029

Site #:	N3-029	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	67.40	User km:	71.50	Last Inspection Date:	2019/08/30
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/08/30
Road Name:	BUSH RIVER				
Crossing Name:	VALENCIENNES R		Total Length (metres):	33.2	
Special Access:			Special Equipment:		
Longitude:	-117 17 52.0		Latitude:	51 48 57.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	2
Planned Inspection Comments:					

Structure Name: N3-030

Site #:	N3-030	Year Superstructure Installed:	1990	Structure Type/Class:	Permanent Bridge
KM:	73.00	User km:	73.50	Last Inspection Date:	2019/09/09
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/09/09
Road Name:	BUSH RIVER				
Crossing Name:	BUSH R		Total Length (metres):	34.0	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-117 18 20.4		Latitude:	51 51 32.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	2
Planned Inspection Comments:	IDIR\JRUPAR on 09-MAY-19: JRG May 9, 2019 Thoroughly inspect timber substructure components during next close proximity inspection. Perform inspection at low water to access pier piles below sheathing.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-023

Site #:	N3-023	Year Superstructure Installed:	1980	Structure Type/Class:	Major Culvert
KM:	77.50	User km:	26.80	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BUSH RIVER				
Crossing Name:	SUMMIT Cr	Total Length (metres):	18.2		
Special Access:			Special Equipment:		
Longitude:	-117 25 55.3	Latitude:	51 38 57.1		
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: N3-032

Site #:	N3-032	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	86.10	User km:	90.80	Last Inspection Date:	2019/08/30
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/08/30
Road Name:	BUSH RIVER				
Crossing Name:	CAMP DAVID Cr	Total Length (metres):	15.5		
Special Access:			Special Equipment:		
Longitude:	-117 22 37.0	Latitude:	51 57 18.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments: IDIR\JRUPAR on 28-JAN-20: JRG Jan 28, 2020 Monitor loss of rip rap at left abutment. Take photos of issue at each inspection.					

Structure Name: N3-019

Site #:	N3-019	Year Superstructure Installed:	1980	Structure Type/Class:	Major Culvert
KM:	101.91	User km:	2.20	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	01	Next Inspection Date:	2022/08/29
Road Name:	BUSH RIVER				
Crossing Name:	MARL Cr	Total Length (metres):	20.2		
Special Access:			Special Equipment:		
Longitude:	-117 11 57.0	Latitude:	51 30 22.8		
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-055

Site #:	N3-055	Year Superstructure Installed:	1975	Structure Type/Class:	Permanent Bridge
KM:	4.90	User km:	4.90	Last Inspection Date:	2020/10/02
Project File ID #:	7663	Br.	01	Next Inspection Date:	2021/05/15
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	BEAVERMOUTH	Total Length (metres):	84.2		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-117 26 5.9	Latitude:	51 31 38.8		
Superstructure:	Glulam Girder	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	3
Planned Inspection Comments:	CBR_Conversion on 27-APR-21: JRG Apr 27, 2021 Annual close proximity inspection required to monitor condition of span 1 downstream girder.				

Structure Name: N3-056

Site #:	N3-056	Year Superstructure Installed:	2009	Structure Type/Class:	Major Culvert
KM:	8.30	User km:	8.30	Last Inspection Date:	2019/08/30
Project File ID #:	7663	Br.	01	Next Inspection Date:	2022/08/30
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	Unnamed	Total Length (metres):	26.0		
Special Access:		Special Equipment:			
Longitude:	-117 27 29.8	Latitude:	51 33 14.8		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N3-057

Site #:	N3-057	Year Superstructure Installed:	2009	Structure Type/Class:	Permanent Bridge
KM:	14.60	User km:	14.60	Last Inspection Date:	2019/08/30
Project File ID #:	7663	Br.	01	Next Inspection Date:	2022/08/30
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	Schlichting Cr	Total Length (metres):	27.4		
Special Access:		Special Equipment:			
Longitude:	-117 30 0.2	Latitude:	51 36 8.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-059

Site #:	N3-059	Year Superstructure Installed:		1975	Structure Type/Class:	Major Culvert		
KM:	17.60	User km:	17.60	Last Inspection Date:		2019/08/30		
Project File ID #:	7663	Br.	01	Next Inspection Date:		2022/08/30		
Road Name:		COLUMBIA RIVER WEST						
Crossing Name:		Unnamed		Total Length (metres):		36.0		
Special Access:				Special Equipment:				
Longitude:		-117 31 18.3		Latitude:		51 37 9.4		
Superstructure:			Abutments (Left/Right): <i>(looking downstream)</i>				# Spans:	0
Planned Inspection Comments:		IDIR\JRUPAR on 30-JAN-20: JRG Jan 30, 2020 Record inlet and outlet cover depths at next inspection.						

Structure Name: N3-109

Site #:	N3-109	Year Superstructure Installed:		2013	Structure Type/Class:	Major Culvert	
KM:	23.50	User km:	23.50	Last Inspection Date:		2019/08/30	
Project File ID #:	7663	Br.	01	Next Inspection Date:		2022/08/30	
Road Name:		COLUMBIA RIVER WEST					
Crossing Name:		unnamed		Total Length (metres):		18.5	
Special Access:				Special Equipment:			
Longitude:		-117 33 43.3		Latitude:		51 39 31.0	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:							

Structure Name: N3-060

Site #:	N3-060	Year Superstructure Installed:		2009	Structure Type/Class:	Major Culvert	
KM:	27.70	User km:	27.70	Last Inspection Date:		2019/08/30	
Project File ID #:	7663	Br.	01	Next Inspection Date:		2022/08/30	
Road Name:		COLUMBIA RIVER WEST					
Crossing Name:		Unnamed		Total Length (metres):		28.0	
Special Access:				Special Equipment:			
Longitude:		-117 35 50.0		Latitude:		51 41 2.0	
Superstructure:				Abutments (Left/Right): <i>(looking downstream)</i>		# Spans: 0	
Planned Inspection Comments:							



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-099

Site #:	N3-099	Year Superstructure Installed:	2010	Structure Type/Class:	Major Culvert
KM:	50.50	User km:	50.50	Last Inspection Date:	2021/09/18
Project File ID #:	7663	Br.	01	Next Inspection Date:	2022/09/18
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	Unnamed	Total Length (metres):	16.0		
Special Access:		Special Equipment:			
Longitude:	-117 41 59.7	Latitude:	51 45 28.7		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 11-SEP-14: .				

Structure Name: N3-064

Site #:	N3-064	Year Superstructure Installed:	1985	Structure Type/Class:	Temporary Bridge
KM:	64.00	User km:	64.20	Last Inspection Date:	2021/09/18
Project File ID #:	7663	Br.	01	Next Inspection Date:	2022/09/18
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	SWAN Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-117 48 51.4	Latitude:	51 49 30.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 28-JAN-22: BP Jan 28-22 Ensure 5 tonne load posting signs are in place IDIR\JRUPAR on 22-FEB-19: JRG Feb 22 2019 Record rot depth, location, and type (sap/heart) in crib members.				

Structure Name: N3-065A

Site #:	N3-065	Year Superstructure Installed:	2010	Structure Type/Class:	Temporary Bridge
KM:	66.90	User km:	66.90	Last Inspection Date:	2013/07/18
Project File ID #:	7663	Br.	01	Next Inspection Date:	2015/07/18
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	DOUBLE EDDY Cr	Total Length (metres):	15.2		
Special Access:		Special Equipment:			
Longitude:	-117 50 14.5	Latitude:	51 50 7.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-081

Site #:	N3-081	Year Superstructure Installed:	1993	Structure Type/Class:	Temporary Bridge
KM:	0.19	User km:	2.00	Last Inspection Date:	2007/07/18
Project File ID #:	9357	Br.	03	Next Inspection Date:	2009/08/31
Road Name:	DAINARD - BR 2.3				
Crossing Name:	DAINARD Cr		Total Length (metres):	15.0	
Special Access:			Special Equipment:		
Longitude:	-118 26 2.4		Latitude:	52 11 22.0	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-082

Site #:	N3-082	Year Superstructure Installed:	1994	Structure Type/Class:	Temporary Bridge
KM:	6.18	User km:	2.80	Last Inspection Date:	2003/09/01
Project File ID #:	9357	Br.	01	Next Inspection Date:	2009/08/31
Road Name:	DAINARD MAIN				
Crossing Name:	DAINARD Cr		Total Length (metres):	8.3	
Special Access:			Special Equipment:		
Longitude:	-118 25 18.7		Latitude:	52 11 34.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-085

Site #:	N3-085	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	13.98	User km:	13.70	Last Inspection Date:	2021/07/30
Project File ID #:	3461	Br.	01	Next Inspection Date:	2022/07/30
Road Name:	DONALD FSR				
Crossing Name:	CIRQUE Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-117 7 23.7		Latitude:	51 23 56.1	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 04-APR-22: DA March 2022, Ensure bridge is posted for 5 tonnes.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-070

Site #:	N3-070	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	8.79	User km:	5.10	Last Inspection Date:	2018/06/07
Project File ID #:	7746	Br.	01	Next Inspection Date:	2021/06/07
Road Name:	GLENOGLE FSR				
Crossing Name:	GLENOGLE Cr #1		Total Length (metres):	22.4	
Special Access:			Special Equipment:		
Longitude:	-116 46 38.0		Latitude:	51 18 28.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-091

Site #:	N3-091	Year Superstructure Installed:	2002	Structure Type/Class:	Permanent Bridge
KM:	5.50	User km:	5.40	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	07	Next Inspection Date:	2022/08/29
Road Name:	HOPE				
Crossing Name:	Unnamed		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-117 22 36.6		Latitude:	51 44 42.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 13-JAN-16: ensure posted at 5 tonnes load restriction. Determine level of deck rot in more detail, drill required. for 2017 inspection. ATV required for access				

Structure Name: N3-087

Site #:	N3-087	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	7.14	User km:	2.50	Last Inspection Date:	2019/08/28
Project File ID #:	4170	Br.	03	Next Inspection Date:	2022/08/28
Road Name:	MOOSE				
Crossing Name:	BEAVERFOOT R		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-116 21 53.1		Latitude:	51 4 43.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-090

Site #:	N3-090	Year Superstructure Installed:	2001	Structure Type/Class:	Major Culvert
KM:	13.62	User km:	8.20	Last Inspection Date:	2021/07/28
Project File ID #:	4170	Br.	03	Next Inspection Date:	2022/07/28
Road Name:	MOOSE				
Crossing Name:	Unnamed		Total Length (metres):	14.6	
Special Access:			Special Equipment:		
Longitude:	-116 21 25.1		Latitude:	51 6 26.4	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: N3-089

Site #:	N3-089	Year Superstructure Installed:	2001	Structure Type/Class:	Permanent Bridge
KM:	13.89	User km:	8.90	Last Inspection Date:	2019/08/28
Project File ID #:	4170	Br.	03	Next Inspection Date:	2022/08/28
Road Name:	MOOSE				
Crossing Name:	MOOSE Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-116 21 18.8		Latitude:	51 6 33.8	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	IDIR\JRUPAR on 31-JAN-20: JRG Jan 31, 2020 Record the angle of the R/B U/S pipe column at every inspection.				

Structure Name: N3-073A

Site #:	N3-073	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	5.57	User km:	5.70	Last Inspection Date:	2019/08/30
Project File ID #:	0763	Br.	01	Next Inspection Date:	2022/08/30
Road Name:	QUARTZ CREEK FSR				
Crossing Name:	Wiseman Lake Cr		Total Length (metres):	15.6	
Special Access:			Special Equipment:		
Longitude:	-117 21 9.0		Latitude:	51 26 24.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Ensure to get better pictures of rip on L/B, downstream. At time of original installation a repair was required at this spot. DA Feb 2014.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 18 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-036A

Site #:	N3-036	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	33.00	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	06	Next Inspection Date:	2022/08/29
Road Name:	RED				
Crossing Name:	SUCCOUR Cr	Total Length (metres):	8.6		
Special Access:		Special Equipment:			
Longitude:	-117 29 36.3	Latitude:	51 41 30.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 22-FEB-17: Needs a site ID number plate. DA				

Structure Name: N3-045

Site #:	N3-045	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	7.80	User km:	73.10	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	05	Next Inspection Date:	2022/08/29
Road Name:	SULLIVAN				
Crossing Name:	CHATTER Cr	Total Length (metres):	24.4		
Special Access:		Special Equipment:			
Longitude:	-117 26 30.0	Latitude:	51 47 15.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: WO 6521

Site #:	N3-115	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	21.30	User km:	82.50	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	05	Next Inspection Date:	2022/09/11
Road Name:	SULLIVAN				
Crossing Name:	unnamed	Total Length (metres):	9.1		
Special Access:		Special Equipment:			
Longitude:	-117 36 7.0	Latitude:	51 46 43.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 22-FEB-19: JRG Feb 22, 2019 Notable active channel. Monitor creek bedload and measure from underside of upstream girder to thalweg at each inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 19 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: WO2702

Site #:	N3-112	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	22.40	User km:	83.60	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	05	Next Inspection Date:	2022/09/11
Road Name:	SULLIVAN				
Crossing Name:	unnamed		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-117 37 6.0		Latitude:	51 46 45.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 22-FEB-19: JRG Feb 22, 2019 Notable active channel. Monitor creek bedload and measure from underside of upstream girder to thalweg at each inspection.				

Structure Name: N3-050

Site #:	N3-050	Year Superstructure Installed:	1987	Structure Type/Class:	Major Culvert
KM:	22.49	User km:	96.50	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	05	Next Inspection Date:	2022/08/29
Road Name:	SULLIVAN				
Crossing Name:	Nixon Cr		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-117 46 31.9		Latitude:	51 49 44.0	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 31-JAN-20: .				

Structure Name: N3-053

Site #:	N3-053	Year Superstructure Installed:	1988	Structure Type/Class:	Temporary Bridge
KM:	44.50	User km:	105.90	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	05	Next Inspection Date:	2022/09/11
Road Name:	SULLIVAN				
Crossing Name:	BOULDER Cr		Total Length (metres):	39.7	
Special Access:			Special Equipment:		
Longitude:	-117 52 37.7		Latitude:	51 52 38.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 20 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-044

Site #:	N3-044	Year Superstructure Installed:	1985	Structure Type/Class:	Permanent Bridge
KM:	51.65	User km:	68.20	Last Inspection Date:	2019/09/09
Project File ID #:	7521	Br.	05	Next Inspection Date:	2022/09/09
Road Name:	SULLIVAN				
Crossing Name:	PRATTLE Cr		Total Length (metres):	25.9	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-117 25 46.5		Latitude:	51 47 30.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Try to inspect at low water, check with district or primary RUP holder to determine best time. Close Proximity inspection completed in 2012, next planned peeper inspection in 2017. DA				

Structure Name: N3-043

Site #:	N3-043	Year Superstructure Installed:	1985	Structure Type/Class:	Permanent Bridge
KM:	57.11	User km:	66.40	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	05	Next Inspection Date:	2022/08/29
Road Name:	SULLIVAN				
Crossing Name:	BUSH R		Total Length (metres):	45.6	
Special Access:			Special Equipment:	Peeper Truck	
Longitude:	-117 21 58.0		Latitude:	51 48 28.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	2
Planned Inspection Comments:	IDIR\DMALWAY on 19-APR-22: Close proximity can be completed every 10 years for this bridge. IDIR\JRUPAR on 31-JAN-20: JRG Jan 31, 2020 Check size of ties at next inspection.				

Structure Name: N3-054

Site #:	N3-054	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	18.28	User km:	15.20	Last Inspection Date:	2019/08/29
Project File ID #:	7521	Br.	02	Next Inspection Date:	2022/08/29
Road Name:	SUSAN LAKE				
Crossing Name:	BLACKWATER Cr		Total Length (metres):	12.6	
Special Access:			Special Equipment:		
Longitude:	-117 17 44.0		Latitude:	51 33 15.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 21 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-113

Site #:	N3-113	Year Superstructure Installed:	2014	Structure Type/Class:	Major Culvert
KM:	18.54	User km:	32.70	Last Inspection Date:	2019/08/30
Project File ID #:	7521	Br.	02	Next Inspection Date:	2022/08/30
Road Name:	SUSAN LAKE				
Crossing Name:	Susan Lake Creek		Total Length (metres):	19.0	
Special Access:			Special Equipment:		
Longitude:	-117 25 35.2		Latitude:	51 34 0.8	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: N3-T01

Site #:	N3-T01	Year Superstructure Installed:	1985	Structure Type/Class:	Permanent Bridge
KM:	0.00	User km:	0.00	Last Inspection Date:	2003/04/01
Project File ID #:		Br.		Next Inspection Date:	2007/03/31
Road Name:					
Crossing Name:	<no crossing>		Total Length (metres):	16.9	
Special Access:			Special Equipment:		
Longitude:	0 0 0.0		Latitude:	0 0 0.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: N3-073

Site #:	STORE 12	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:		User km:		Last Inspection Date:	2010/07/29
Project File ID #:		Br.		Next Inspection Date:	2013/08/16
Road Name:					
Crossing Name:	Golden		Total Length (metres):	8.3	
Special Access:			Special Equipment:		
Longitude:	-116 58 41.7		Latitude:	51 18 31.3	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 22 of 22
Date Printed: 2022/06/08
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2022/12/30 Management Area: 53 Sort: Forest Service

Structure Name: N3-086

Site #:	STORE 12	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:		User km:		Last Inspection Date:	2009/09/30
Project File ID #:		Br.		Next Inspection Date:	2012/09/30
Road Name:					
Crossing Name:	Golden	Total Length (metres):	21.3		
Special Access:		Special Equipment:			
Longitude:	-116 58 41.7	Latitude:	51 18 31.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Deactivated June 2012. Do not inspect.DA				

Structure Name: N3-003

Site #:	STORE 12	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:		User km:		Last Inspection Date:	2013/07/19
Project File ID #:		Br.		Next Inspection Date:	2015/07/19
Road Name:					
Crossing Name:	Golden	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-116 58 41.7	Latitude:	51 18 31.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Type/Class Totals

Permanent Bridge Total: 34	Major Culvert Total: 12
Temporary Bridge Total: 18	Woodbox/Log Culvert Total: 0