



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-061

Site #:	N1-061	Year Superstructure Installed:	1994	Structure Type/Class:	Major Culvert
KM:	29.63	User km:	29.90	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	01	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD MAIN				
Crossing Name:	MORGAN Cr	Total Length (metres):	12.1		
Special Access:		Special Equipment:			
Longitude:	-114 34 9.8	Latitude:	49 18 26.1		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: LT: Inspector should record gradient next inspection				

Structure Name: N1-064

Site #:	N1-064	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	38.87	User km:	60.00	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	01	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD MAIN				
Crossing Name:	PARKER Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-114 33 22.3	Latitude:	49 13 57.1		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-066

Site #:	N1-066	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	65.22	User km:	86.50	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	01	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD MAIN				
Crossing Name:	BURNHAM Cr	Total Length (metres):	15.3		
Special Access:		Special Equipment:			
Longitude:	-114 32 10.4	Latitude:	49 2 27.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-067

Site #:	N1-067	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	65.40	User km:	86.60	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	01	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD MAIN				
Crossing Name:	COULDRY Cr		Total Length (metres):	23.5	
Special Access:			Special Equipment:		
Longitude:	-114 32 5.9		Latitude:	49 2 25.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-248

Site #:	N1-248	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	69.00	User km:	69.00	Last Inspection Date:	
Project File ID #:	0030	Br.	01	Next Inspection Date:	2021/08/01
Road Name:	FLATHEAD MAIN				
Crossing Name:	unknown		Total Length (metres):	40.3	
Special Access:			Special Equipment:		
Longitude:	-114 29 34.7		Latitude:	49 9 41.8	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N1-069A

Site #:	N1-069	Year Superstructure Installed:	2014	Structure Type/Class:	Temporary Bridge
KM:	5.50	User km:	95.50	Last Inspection Date:	2020/10/01
Project File ID #:	0030	Br.	03	Next Inspection Date:	2022/10/01
Road Name:	FLATHEAD FROZEN				
Crossing Name:	COULDREY Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-114 37 46.6		Latitude:	49 1 12.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N1-073

Site #:	N1-073	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	15.68	User km:	89.70	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	05	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD KISHINENA				
Crossing Name:	ELDER Cr	Total Length (metres):	15.3		
Special Access:			Special Equipment:		
Longitude:	-114 23 41.9	Latitude:	49 1 44.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-074

Site #:	N1-074	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	27.21	User km:	101.20	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	05	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD KISHINENA				
Crossing Name:	Unnamed	Total Length (metres):	10.6		
Special Access:			Special Equipment:		
Longitude:	-114 17 54.0	Latitude:	49 3 22.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-075

Site #:	N1-075	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	30.31	User km:	104.30	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	05	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD KISHINENA				
Crossing Name:	KISHINENA R	Total Length (metres):	26.4		
Special Access:			Special Equipment:		
Longitude:	-114 16 53.0	Latitude:	49 3 43.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-076

Site #:	N1-076	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	33.76	User km:	107.80	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	05	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD KISHINENA				
Crossing Name:	BEAVERTAIL Cr		Total Length (metres):	15.3	
Special Access:			Special Equipment:		
Longitude:	-114 14 25.0		Latitude:	49 4 6.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-078

Site #:	N1-078	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	12.54	User km:	93.00	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	07	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD SAGE				
Crossing Name:	SUNKIST Cr		Total Length (metres):	15.3	
Special Access:			Special Equipment:		
Longitude:	-114 21 29.0		Latitude:	49 8 36.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-079

Site #:	N1-079	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	17.13	User km:	98.00	Last Inspection Date:	2019/10/21
Project File ID #:	0030	Br.	07	Next Inspection Date:	2022/10/21
Road Name:	FLATHEAD SAGE				
Crossing Name:	ROCHE Cr		Total Length (metres):	14.3	
Special Access:			Special Equipment:		
Longitude:	-114 17 57.6		Latitude:	49 9 3.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 19-DEC-19: Please fill void under the sill using cement of epoxy grout and replace curbs and running planks prior to industrial use. Monitored low bed equipment crossing allowed provided sill condition is monitored during crossing. Inspector to downrate this bridge to 2 tonnes if above mentioned repairs are not completed by next routine inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-175

Site #:	N1-175	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	19.15	User km:	37.00	Last Inspection Date:	2019/06/19
Project File ID #:	0051	Br.	01	Next Inspection Date:	2022/06/19
Road Name:	TEEPEE CK/MAIN				
Crossing Name:	Unnamed		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-115 33 40.9		Latitude:	49 17 10.5	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-174

Site #:	N1-174	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	26.36	User km:	29.00	Last Inspection Date:	2019/06/19
Project File ID #:	0051	Br.	01	Next Inspection Date:	2022/06/19
Road Name:	TEEPEE CK/MAIN				
Crossing Name:	GOLD Cr		Total Length (metres):	14.3	
Special Access:			Special Equipment:		
Longitude:	-115 27 36.1		Latitude:	49 16 7.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-240

Site #:	N1-240	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	35.00	User km:	20.00	Last Inspection Date:	2019/06/19
Project File ID #:	0051	Br.	01	Next Inspection Date:	2022/06/19
Road Name:	TEEPEE CK/MAIN				
Crossing Name:	Plumbob Cr		Total Length (metres):	14.0	
Special Access:			Special Equipment:		
Longitude:	-115 21 27.7		Latitude:	49 17 36.7	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-177

Site #:	N1-177	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	20.41	User km:	20.00	Last Inspection Date:	2019/06/19
Project File ID #:	0051	Br.	04	Next Inspection Date:	2022/06/19
Road Name:	TEEPEE CK/JIM CK				
Crossing Name:	TEEPEE Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-115 31 24.5		Latitude:	49 16 47.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-181

Site #:	N1-181	Year Superstructure Installed:	1985	Structure Type/Class:	Major Culvert
KM:	8.09	User km:	11.80	Last Inspection Date:	2019/10/18
Project File ID #:	0072	Br.	01	Next Inspection Date:	2022/10/18
Road Name:	WILDHORSE/MAIN				
Crossing Name:	VICTORIA Cr		Total Length (metres):	16.1	
Special Access:			Special Equipment:		
Longitude:	-115 33 7.2		Latitude:	49 43 0.8	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N1-250

Site #:	N1-250	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	12.00	User km:	12.50	Last Inspection Date:	
Project File ID #:	0072	Br.	01	Next Inspection Date:	2022/08/15
Road Name:	WILDHORSE/MAIN				
Crossing Name:	Victoria Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-115 33 10.4		Latitude:	49 42 59.0	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 19-APR-22: One year post installation inspection				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-182A

Site #:	N1-182	Year Superstructure Installed:	2021	Structure Type/Class:	Permanent Bridge
KM:	13.91	User km:	19.50	Last Inspection Date:	
Project File ID #:	0072	Br.	01	Next Inspection Date:	2022/08/15
Road Name:	WILDHORSE/MAIN				
Crossing Name:	Unnamed		Total Length (metres):	13.6	
Special Access:			Special Equipment:		
Longitude:	-115 31 33.4		Latitude:	49 45 5.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 19-APR-22: One year post installation inspection				

Structure Name: N1-008

Site #:	N1-008	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	9.66	User km:	29.70	Last Inspection Date:	2019/09/12
Project File ID #:	0089	Br.	01	Next Inspection Date:	2022/09/12
Road Name:	BULL RIVER/MAIN				
Crossing Name:	DIBBLE Cr		Total Length (metres):	21.0	
Special Access:			Special Equipment:		
Longitude:	-115 19 42.4		Latitude:	49 34 7.5	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-015A

Site #:	N1-015	Year Superstructure Installed:	2011	Structure Type/Class:	Permanent Bridge
KM:	50.16	User km:	70.20	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	01	Next Inspection Date:	2022/09/15
Road Name:	BULL RIVER/MAIN				
Crossing Name:	WASHOUT Cr		Total Length (metres):	10.3	
Special Access:			Special Equipment:		
Longitude:	-115 8 43.8		Latitude:	49 51 53.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Origin of structure needs to be resolved. See p.eng comments in 2013 inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-017A

Site #:	N1-017	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	66.29	User km:	86.20	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	01	Next Inspection Date:	2022/09/15
Road Name:	BULL RIVER/MAIN				
Crossing Name:	Unnamed		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-115 7 20.5		Latitude:	50 0 13.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-046

Site #:	N1-046	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	10.74	User km:	40.10	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	02	Next Inspection Date:	2022/09/15
Road Name:	BULL/VAN CREEK				
Crossing Name:	VAN Cr #3		Total Length (metres):	11.0	
Special Access:			Special Equipment:		
Longitude:	-115 22 41.3		Latitude:	49 38 13.2	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-047

Site #:	N1-047	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	15.50	User km:	47.50	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	02	Next Inspection Date:	2022/09/15
Road Name:	BULL/VAN CREEK				
Crossing Name:	THUYA Cr		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-115 25 14.0		Latitude:	49 39 5.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N1-044

Site #:	N1-044	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	15.94	User km:	36.00	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	02	Next Inspection Date:	2022/09/15
Road Name:	BULL/VAN CREEK				
Crossing Name:	VAN Cr #2		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-115 20 4.0		Latitude:	49 36 39.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: LT: Take photos of wingwall cracks.				

Structure Name: N1-043

Site #:	N1-043	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	18.02	User km:	33.80	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	02	Next Inspection Date:	2022/09/15
Road Name:	BULL/VAN CREEK				
Crossing Name:	VAN Cr #1		Total Length (metres):	14.3	
Special Access:			Special Equipment:		
Longitude:	-115 20 2.0		Latitude:	49 35 45.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-042

Site #:	N1-042	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	13.00	User km:	59.50	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	04	Next Inspection Date:	2022/09/15
Road Name:	BULL/TANGLEFOOT CK				
Crossing Name:	TANGLEFOOT Cr		Total Length (metres):	22.5	
Special Access:			Special Equipment:		
Longitude:	-115 23 53.0		Latitude:	49 40 17.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-022A

Site #:	N1-022	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	14.32	User km:	33.60	Last Inspection Date:	2019/09/12
Project File ID #:	0089	Br.	05	Next Inspection Date:	2022/09/12
Road Name:	BULL/GALBRAITH CK				
Crossing Name:	GREEN Cr	Total Length (metres):	10.4		
Special Access:			Special Equipment:		
Longitude:	-115 17 42.1	Latitude:	49 43 40.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-023A

Site #:	N1-023	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	16.82	User km:	36.00	Last Inspection Date:	2019/09/12
Project File ID #:	0089	Br.	05	Next Inspection Date:	2022/09/12
Road Name:	BULL/GALBRAITH CK				
Crossing Name:	GALBRAITH Cr #1	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-115 19 26.0	Latitude:	49 44 20.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-024A

Site #:	N1-024	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	18.36	User km:	57.70	Last Inspection Date:	2019/09/12
Project File ID #:	0089	Br.	05	Next Inspection Date:	2022/09/12
Road Name:	BULL/GALBRAITH CK				
Crossing Name:	GALBRAITH Cr #2	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-115 20 25.0	Latitude:	49 44 45.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-025A

Site #:	N1-025	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	24.40	User km:	64.50	Last Inspection Date:	2019/09/12
Project File ID #:	0089	Br.	05	Next Inspection Date:	2022/09/12
Road Name:	BULL/GALBRAITH CK				
Crossing Name:	SUMMER Cr	Total Length (metres):	12.2		
Special Access:			Special Equipment:		
Longitude:	-115 24 6.4	Latitude:	49 46 10.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-026A

Site #:	N1-026	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	24.46	User km:	44.60	Last Inspection Date:	2019/09/12
Project File ID #:	0089	Br.	05	Next Inspection Date:	2022/09/12
Road Name:	BULL/GALBRAITH CK				
Crossing Name:	RAUALT Cr	Total Length (metres):	10.0		
Special Access:			Special Equipment:		
Longitude:	-115 24 23.5	Latitude:	49 45 54.7		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-028

Site #:	N1-028	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.02	User km:	60.20	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	06	Next Inspection Date:	2022/09/15
Road Name:	BULL/QUINN CK				
Crossing Name:	BULL R	Total Length (metres):	32.7		
Special Access:			Special Equipment:		
Longitude:	-115 9 59.3	Latitude:	49 46 32.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-030

Site #:	N1-030	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	16.32	User km:	76.30	Last Inspection Date:	2019/09/15
Project File ID #:	0089	Br.	06	Next Inspection Date:	2022/09/15
Road Name:	BULL/QUINN CK				
Crossing Name:	QUINN Cr	Total Length (metres):	15.5		
Special Access:			Special Equipment:		
Longitude:	-115 17 16.4	Latitude:	49 53 10.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-031

Site #:	N1-031	Year Superstructure Installed:	1979	Structure Type/Class:	Temporary Bridge
KM:	17.58	User km:	77.60	Last Inspection Date:	2020/10/06
Project File ID #:	0089	Br.	06	Next Inspection Date:	2022/10/06
Road Name:	BULL/QUINN CK				
Crossing Name:	GOAT Cr	Total Length (metres):	6.8		
Special Access:			Special Equipment:		
Longitude:	-115 17 53.0	Latitude:	49 53 53.0		
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-032

Site #:	N1-032	Year Superstructure Installed:	1995	Structure Type/Class:	Temporary Bridge
KM:	18.70	User km:	78.70	Last Inspection Date:	2020/10/06
Project File ID #:	0089	Br.	06	Next Inspection Date:	2022/10/06
Road Name:	BULL/QUINN CK				
Crossing Name:	QUINN Cr	Total Length (metres):	8.3		
Special Access:			Special Equipment:		
Longitude:	-115 17 36.3	Latitude:	49 54 24.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N1-055A

Site #:	N1-055	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	21.37	User km:	146.00	Last Inspection Date:	2019/06/25
Project File ID #:	0103	Br.	01	Next Inspection Date:	2022/06/25
Road Name:	ELK RIVER MAIN				
Crossing Name:	ELK R	Total Length (metres):	30.5		
Special Access:			Special Equipment:		
Longitude:	-114 55 19.4	Latitude:	50 23 28.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-054B

Site #:	N1-054	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	25.66	User km:	142.00	Last Inspection Date:	2019/06/25
Project File ID #:	0103	Br.	01	Next Inspection Date:	2022/06/25
Road Name:	ELK RIVER MAIN				
Crossing Name:	BLEASEDELL Cr	Total Length (metres):	21.3		
Special Access:			Special Equipment:		
Longitude:	-114 55 13.0	Latitude:	50 21 19.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-249

Site #:	N1-249	Year Superstructure Installed:	2020	Structure Type/Class:	Permanent Bridge
KM:	61.00	User km:	161.00	Last Inspection Date:	
Project File ID #:	0103	Br.	01	Next Inspection Date:	2022/08/01
Road Name:	ELK RIVER MAIN				
Crossing Name:	Tobermory	Total Length (metres):	12.6		
Special Access:			Special Equipment:		
Longitude:	-115 0 52.0	Latitude:	50 31 22.8		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N1-040

Site #:	N1-040	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	14.50	User km:	48.00	Last Inspection Date:	2019/07/24
Project File ID #:	0159	Br.	01	Next Inspection Date:	2022/07/24
Road Name:	SULPHUR CREEK				
Crossing Name:	HARTLEY Cr	Total Length (metres):	11.6		
Special Access:		Special Equipment:			
Longitude:	-115 1 38.0	Latitude:	49 34 40.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-090

Site #:	N1-090	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.47	User km:	5.30	Last Inspection Date:	2019/06/17
Project File ID #:	0245	Br.	02	Next Inspection Date:	2022/06/17
Road Name:	LITTLE LAMB CK				
Crossing Name:	LITTLE LAMB Cr	Total Length (metres):	11.0		
Special Access:		Special Equipment:			
Longitude:	-115 53 39.3	Latitude:	49 20 3.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-087

Site #:	N1-087	Year Superstructure Installed:	1993	Structure Type/Class:	Major Culvert
KM:	0.29	User km:	8.70	Last Inspection Date:	2019/06/17
Project File ID #:	0245	Br.	05	Next Inspection Date:	2022/06/17
Road Name:	IRISHMAN CK				
Crossing Name:	RABBITFOOT Cr	Total Length (metres):	16.0		
Special Access:		Special Equipment:			
Longitude:	-115 55 9.8	Latitude:	49 18 34.1		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: LT: Record gradient at next inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-093

Site #:	N1-093	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	0.20	User km:	9.00	Last Inspection Date:	2019/06/17
Project File ID #:	0245	Br.	06	Next Inspection Date:	2022/06/17
Road Name:	LAMB CREEK 6				
Crossing Name:	LAMB Cr	Total Length (metres):	15.6		
Special Access:		Special Equipment:			
Longitude:	-115 55 0.0	Latitude:	49 18 34.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-115

Site #:	N1-115	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	6.91	User km:	20.30	Last Inspection Date:	2019/06/20
Project File ID #:	0246	Br.	01	Next Inspection Date:	2022/06/20
Road Name:	MOYIE RIVER/MAIN				
Crossing Name:	NORTH MOYIE Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-116 4 35.6	Latitude:	49 22 12.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-219

Site #:	N1-219	Year Superstructure Installed:	2010	Structure Type/Class:	Permanent Bridge
KM:	1.60	User km:		Last Inspection Date:	2019/06/17
Project File ID #:	0246	Br.	12	Next Inspection Date:	2022/06/17
Road Name:	NEGRO CREEK				
Crossing Name:	Negro Creek	Total Length (metres):	8.4		
Special Access:		Special Equipment:			
Longitude:	-115 58 51.0	Latitude:	49 26 55.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Confirm coordinates				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-122

Site #:	N1-122	Year Superstructure Installed:	1990	Structure Type/Class:	Major Culvert
KM:	1.83	User km:	9.20	Last Inspection Date:	2019/06/17
Project File ID #:	0246	Br.	13	Next Inspection Date:	2022/06/17
Road Name:	PALMER BAR				
Crossing Name:	NEGRO Cr	Total Length (metres):	14.8		
Special Access:		Special Equipment:			
Longitude:	-115 58 1.2	Latitude:	49 26 19.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: N1-117

Site #:	N1-117	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	1.24	User km:	21.40	Last Inspection Date:	2019/06/20
Project File ID #:	0246	Br.	32	Next Inspection Date:	2022/06/20
Road Name:	CR0246.32				
Crossing Name:	NORTH MOYIE Cr	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-116 5 32.8	Latitude:	49 22 17.7		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-225

Site #:	N1-225	Year Superstructure Installed:	1990	Structure Type/Class:	Temporary Bridge
KM:	1.80	User km:	24.40	Last Inspection Date:	2021/09/26
Project File ID #:	0246	Br.	32	Next Inspection Date:	2022/09/26
Road Name:	CR0246.32				
Crossing Name:	Unknown	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-116 5 37.3	Latitude:	49 22 47.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 11-APR-22: BP Apr 11-22 Annual inspection required due to overall condition, especially rotting deck components CBR_Conversion on 17-FEB-14: Confirm coordinates, full measure of length and width, confirm user KM, post to 2 Tonnes				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 17 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-138

Site #:	N1-138	Year Superstructure Installed:	1987	Structure Type/Class:	Major Culvert
KM:	0.56	User km:	0.60	Last Inspection Date:	2019/09/24
Project File ID #:	0252	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	ST.MARYS RIVER/MAIN				
Crossing Name:	PERRY Cr OVERFLOW		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-115 55 39.4		Latitude:	49 35 10.1	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: N1-139A

Site #:	N1-139	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	21.39	User km:	24.90	Last Inspection Date:	2019/11/05
Project File ID #:	0252	Br.	01	Next Inspection Date:	2022/11/05
Road Name:	ST.MARYS RIVER/MAIN				
Crossing Name:	HELLROARING Cr		Total Length (metres):	33.5	
Special Access:			Special Equipment:		
Longitude:	-116 9 18.8		Latitude:	49 36 37.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: N1-211

Site #:	N1-211	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	4.01	User km:	0.00	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	02	Next Inspection Date:	2022/09/10
Road Name:	ANGUS CREEK				
Crossing Name:	unamed		Total Length (metres):	9.3	
Special Access:			Special Equipment:		
Longitude:	-116 8 49.2		Latitude:	49 34 1.7	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 18 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N1-196

Site #:	N1-196	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	17.00	User km:	17.00	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	04	Next Inspection Date:	2022/09/10
Road Name:	MEACHEN CREEK				
Crossing Name:	WHITE BOAR Cr	Total Length (metres):	9.6		
Special Access:			Special Equipment:		
Longitude:	-116 22 1.1	Latitude:	49 33 26.2		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-151

Site #:	N1-151	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	24.60	User km:	24.60	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	04	Next Inspection Date:	2022/09/10
Road Name:	MEACHEN CREEK				
Crossing Name:	MEACHEN Cr #3	Total Length (metres):	18.3		
Special Access:			Special Equipment:		
Longitude:	-116 27 49.8	Latitude:	49 32 53.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-152

Site #:	N1-152	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	25.50	User km:	25.50	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	04	Next Inspection Date:	2022/09/10
Road Name:	MEACHEN CREEK				
Crossing Name:	Unnamed	Total Length (metres):	12.2		
Special Access:			Special Equipment:		
Longitude:	-116 28 33.8	Latitude:	49 32 42.3		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 16-FEB-15: JN; 2015-02-16: check to see if rip rap repairs have been completed.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 19 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-154

Site #:	N1-154	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.20	User km:	0.20	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	05	Next Inspection Date:	2022/09/10
Road Name:	REDDING CREEK				
Crossing Name:	ST MARYS R	Total Length (metres):	60.4		
Special Access:			Special Equipment:		
Longitude:	-116 19 45.0	Latitude:	49 39 7.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	2
Planned Inspection Comments:					

Structure Name: N1-156

Site #:	N1-156	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	19.00	User km:	19.00	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	05	Next Inspection Date:	2022/09/10
Road Name:	REDDING CREEK				
Crossing Name:	BARIBEAU Cr	Total Length (metres):	15.0		
Special Access:			Special Equipment:		
Longitude:	-116 32 22.0	Latitude:	49 38 24.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-157

Site #:	N1-157	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	19.20	User km:	19.20	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	05	Next Inspection Date:	2022/09/10
Road Name:	REDDING CREEK				
Crossing Name:	REDDING Cr #1	Total Length (metres):	20.0		
Special Access:			Special Equipment:		
Longitude:	-116 32 24.0	Latitude:	49 38 14.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 20 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-158

Site #:	N1-158	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	24.00	User km:	24.00	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	05	Next Inspection Date:	2022/09/10
Road Name:	REDDING CREEK				
Crossing Name:	REDDING Cr #2		Total Length (metres):	18.0	
Special Access:			Special Equipment:		
Longitude:	-116 34 22.0		Latitude:	49 36 37.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-163

Site #:	N1-163	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	20.62	User km:	3.00	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	06	Next Inspection Date:	2022/09/10
Road Name:	WEST FORK				
Crossing Name:	ST MARYS-W FORK #1		Total Length (metres):	38.1	
Special Access:			Special Equipment:		
Longitude:	-116 24 48.7		Latitude:	49 43 43.7	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-162

Site #:	N1-162	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	23.56	User km:	0.50	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	06	Next Inspection Date:	2022/09/10
Road Name:	WEST FORK				
Crossing Name:	DEWAR Cr		Total Length (metres):	36.0	
Special Access:			Special Equipment:		
Longitude:	-116 22 54.4		Latitude:	49 43 40.6	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 21 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-161

Site #:	N1-161	Year Superstructure Installed:	1986	Structure Type/Class:	Permanent Bridge
KM:	24.48	User km:	49.50	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	06	Next Inspection Date:	2022/09/10
Road Name:	WEST FORK				
Crossing Name:	WHITE Cr	Total Length (metres):	28.0		
Special Access:		Special Equipment:			
Longitude:	-116 22 39.0	Latitude:	49 43 16.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-244

Site #:	N1-244	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	12.30	User km:	56.50	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	09	Next Inspection Date:	2022/09/10
Road Name:	DEWAR CREEK				
Crossing Name:	unknown	Total Length (metres):	12.6		
Special Access:		Special Equipment:			
Longitude:	-116 23 47.5	Latitude:	49 47 8.7		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-141A

Site #:	N1-141	Year Superstructure Installed:	2018	Structure Type/Class:	Permanent Bridge
KM:	13.34	User km:	58.00	Last Inspection Date:	2019/09/10
Project File ID #:	0252	Br.	09	Next Inspection Date:	2022/09/10
Road Name:	DEWAR CREEK				
Crossing Name:	IRISH QUEEN Cr	Total Length (metres):	18.7		
Special Access:		Special Equipment:			
Longitude:	-116 24 10.0	Latitude:	49 47 31.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 22 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: WO-582

Site #:	N1-165	Year Superstructure Installed:	2012	Structure Type/Class:	Temporary Bridge
KM:	5.73	User km:	5.73	Last Inspection Date:	2021/10/02
Project File ID #:	0252	Br.	10	Next Inspection Date:	2022/10/02
Road Name:	WHITE CREEK				
Crossing Name:	Unnamed		Total Length (metres):	16.3	
Special Access:			Special Equipment:		
Longitude:	-116 19 26.0		Latitude:	49 45 2.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\MACLOET on 24-JAN-22: Ensure crossing is physically barricaded to prevent use. Monitor deck and substructure conditions. CBR_Conversion on 17-FEB-14: One year post installation inspection of this temporary install. Check with district prior to inspection as may be get permanent replacement in summer 2012. DA.				

Structure Name: N1-208

Site #:	N1-208	Year Superstructure Installed:	2002	Structure Type/Class:	Permanent Bridge
KM:	8.27	User km:	8.00	Last Inspection Date:	2021/09/29
Project File ID #:	0252	Br.	20	Next Inspection Date:	2022/09/29
Road Name:	MARK CREEK				
Crossing Name:	MARK Cr		Total Length (metres):	16.5	
Special Access:			Special Equipment:		
Longitude:	-116 2 32.1		Latitude:	49 44 5.3	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\BPELLETT on 11-APR-22: BP Apr 11-22 Check W-beams for loose or missing bolts and directly measure lean of right abutment posts with every annual inspection.				

Structure Name: N1-194

Site #:	N1-194	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	0.01	User km:	39.70	Last Inspection Date:	2019/06/19
Project File ID #:	5433	Br.	05	Next Inspection Date:	2022/06/19
Road Name:	BOYD CREEK				
Crossing Name:	YAHK R		Total Length (metres):	13.0	
Special Access:			Special Equipment:		
Longitude:	-115 42 41.7		Latitude:	49 2 42.7	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 23 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N1-102A

Site #:	N1-102	Year Superstructure Installed:	2011	Structure Type/Class:	Permanent Bridge
KM:	18.82	User km:	38.40	Last Inspection Date:	2019/10/21
Project File ID #:	5466	Br.	01	Next Inspection Date:	2022/10/21
Road Name:	LOGGEPOLE CREEK				
Crossing Name:	NORTH LOGGEPOLE Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-114 46 29.9		Latitude:	49 17 36.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\JNAUL on 19-DEC-19: Inspector to downrate this bridge to 2 tonnes if approach no posts and damaged rail components are not repaired by next routine inspection.				

Structure Name: N1-101A

Site #:	N1-101	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	28.79	User km:	13.00	Last Inspection Date:	2019/10/21
Project File ID #:	5466	Br.	01	Next Inspection Date:	2022/10/21
Road Name:	LOGGEPOLE CREEK				
Crossing Name:	MORRISEY Cr #2		Total Length (metres):	30.5	
Special Access:			Special Equipment:		
Longitude:	-114 58 54.0		Latitude:	49 21 59.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-204

Site #:	N1-204	Year Superstructure Installed:	1996	Structure Type/Class:	Permanent Bridge
KM:	0.20	User km:	26.00	Last Inspection Date:	2019/10/21
Project File ID #:	5466	Br.	07	Next Inspection Date:	2022/10/21
Road Name:	CABIN CREEK				
Crossing Name:	BEAN Cr		Total Length (metres):	6.8	
Special Access:			Special Equipment:		
Longitude:	-114 56 7.1		Latitude:	49 18 23.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 24 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-104

Site #:	N1-104	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	38.58	User km:	64.00	Last Inspection Date:	2019/10/21
Project File ID #:	5466	Br.	07	Next Inspection Date:	2022/10/21
Road Name:	CABIN CREEK				
Crossing Name:	Unnamed		Total Length (metres):	12.6	
Special Access:			Special Equipment:		
Longitude:	-114 45 34.5		Latitude:	49 9 40.4	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-105

Site #:	N1-105	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	52.38	User km:	77.00	Last Inspection Date:	2019/10/21
Project File ID #:	5466	Br.	07	Next Inspection Date:	2022/10/21
Road Name:	CABIN CREEK				
Crossing Name:	STORM Cr		Total Length (metres):	12.6	
Special Access:			Special Equipment:		
Longitude:	-114 38 2.2		Latitude:	49 6 2.5	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-128

Site #:	N1-128	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	5.33	User km:	6.00	Last Inspection Date:	2019/09/24
Project File ID #:	5577	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	PERRY CREEK/MAIN				
Crossing Name:	LISBON Cr		Total Length (metres):	11.6	
Special Access:			Special Equipment:		
Longitude:	-116 0 12.5		Latitude:	49 33 10.6	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 25 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N1-130

Site #:	N1-130	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	18.12	User km:	18.70	Last Inspection Date:	2019/09/24
Project File ID #:	5577	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	PERRY CREEK/MAIN				
Crossing Name:	MANCHESTER Cr		Total Length (metres):	9.5	
Special Access:			Special Equipment:		
Longitude:	-116 6 9.0		Latitude:	49 28 18.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-131

Site #:	N1-131	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	18.80	User km:	19.30	Last Inspection Date:	2019/09/24
Project File ID #:	5577	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	PERRY CREEK/MAIN				
Crossing Name:	PERRY Cr		Total Length (metres):	18.3	
Special Access:			Special Equipment:		
Longitude:	-116 6 24.0		Latitude:	49 28 0.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-132

Site #:	N1-132	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	22.67	User km:	23.20	Last Inspection Date:	2019/09/24
Project File ID #:	5577	Br.	01	Next Inspection Date:	2022/09/24
Road Name:	PERRY CREEK/MAIN				
Crossing Name:	GALAWAY Cr		Total Length (metres):	10.6	
Special Access:			Special Equipment:		
Longitude:	-116 7 19.0		Latitude:	49 26 7.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 26 of 29
 Date Printed: 2022/08/22
 User Id: IDIR\HABEURSK
 Database: PROD
 Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-206

Site #:	N1-206	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.70	User km:	2.30	Last Inspection Date:	2019/09/24
Project File ID #:	5577	Br.	06	Next Inspection Date:	2022/09/24
Road Name:	SAWMILL CREEK				
Crossing Name:	SAWMILL Cr		Total Length (metres):	6.3	
Special Access:			Special Equipment:		
Longitude:	-116 2 36.6		Latitude:	49 32 41.3	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-172

Site #:	N1-172	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	0.76	User km:	2.00	Last Inspection Date:	2017/07/27
Project File ID #:	5957	Br.	01	Next Inspection Date:	2020/07/27
Road Name:	LOST DOG/MAIN				
Crossing Name:	MATHER Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-115 53 48.0		Latitude:	49 42 49.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments: IDIR\JNAUL on 18-FEB-15: JN; 2015-02-18: Photo of scour at left abutment are not clear when compared to 2013 photos. Re-inspect in 2015 to determine if the repairs to abutment are completed. IDIR\JNAUL on 10-APR-14: JN; 2014-04-10: Reinspect in fall of 2014; if the deck, ties and curbs are not replaced in 2014, then the inspector shall post this structure at 5 tonnes (in 2014) and measure rot depths in ties for new load rating. Please upload or send us photos for our records.					

Structure Name: N1-241

Site #:	N1-241	Year Superstructure Installed:	2015	Structure Type/Class:	Permanent Bridge
KM:	7.80	User km:	7.80	Last Inspection Date:	2019/06/19
Project File ID #:	7576	Br.	01	Next Inspection Date:	2022/06/19
Road Name:	LINKLATER MAIN				
Crossing Name:	Purcell Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-115 17 53.0		Latitude:	49 3 25.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 27 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-095

Site #:	N1-095	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	16.35	User km:	19.80	Last Inspection Date:	2019/06/19
Project File ID #:	7576	Br.	01	Next Inspection Date:	2022/06/19
Road Name:	LINKLATER MAIN				
Crossing Name:	GOLD GRK		Total Length (metres):	26.0	
Special Access:			Special Equipment:		
Longitude:	-115 19 24.0		Latitude:	49 7 34.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-098

Site #:	N1-098	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.09	User km:	30.40	Last Inspection Date:	2019/06/19
Project File ID #:	7576	Br.	02	Next Inspection Date:	2022/06/19
Road Name:	SINK CREEK				
Crossing Name:	LINKLATER Cr		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-115 16 3.7		Latitude:	49 2 54.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: N1-096

Site #:	N1-096	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.10	User km:	31.20	Last Inspection Date:	2019/06/19
Project File ID #:	7576	Br.	03	Next Inspection Date:	2022/06/19
Road Name:	LINKLATER CREEK				
Crossing Name:	PURCEL Cr		Total Length (metres):	9.6	
Special Access:			Special Equipment:		
Longitude:	-115 17 28.2		Latitude:	49 3 8.3	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 28 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status:Inspect

Structure Name: N1-097A

Site #:	N1-097	Year Superstructure Installed:	1994	Structure Type/Class:	Major Culvert
KM:	3.54	User km:	33.50	Last Inspection Date:	2019/06/19
Project File ID #:	7576	Br.	03	Next Inspection Date:	2022/06/19
Road Name:	LINKLATER CREEK				
Crossing Name:	LINKLATER Cr N.FK		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-115 15 58.4		Latitude:	49 3 19.2	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: N1-167

Site #:	N1-167	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	5.08	User km:	6.50	Last Inspection Date:	2019/06/17
Project File ID #:	8620	Br.	01	Next Inspection Date:	2022/06/17
Road Name:	SUNDOWN CREEK				
Crossing Name:	Unnamed		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-115 50 19.0		Latitude:	49 11 31.0	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:					

Structure Name: N1-169

Site #:	N1-169	Year Superstructure Installed:	2003	Structure Type/Class:	Permanent Bridge
KM:	6.82	User km:	8.20	Last Inspection Date:	2019/11/05
Project File ID #:	8620	Br.	01	Next Inspection Date:	2022/11/05
Road Name:	SUNDOWN CREEK				
Crossing Name:	SUNDOWN Cr		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-115 49 52.0		Latitude:	49 10 41.5	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans: 1
Planned Inspection Comments:	IDIR\JNAUL on 19-DEC-19: Inspector to down rate this bridge to 2 tonnes if rotten timber curb components are not replaced by next routine inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 29 of 29
Date Printed: 2022/08/22
User Id: IDIR\HABEURSK
Database: PROD
Report Id: CBR003

Forest District: Rocky Mountain Natural Resource District Next Planned Inspection Date: 2000/01/01 - 2022/12/30 Inspection Status: Inspect

Structure Name: N1-222

Site #:	N1-222	Year Superstructure Installed:	1998	Structure Type/Class:	Temporary Bridge
KM:	0.20	User km:		Last Inspection Date:	2020/09/02
Project File ID #:	9823	Br.	01	Next Inspection Date:	2022/09/02
Road Name:	NEGRO LAKE EAST				
Crossing Name:	Unknown	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-115 56 36.0	Latitude:	49 25 30.8		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 21-FEB-14: Confirm user KM.				

Structure Name: N1-153

Site #:	N1-153	Year Superstructure Installed:	2005	Structure Type/Class:	Permanent Bridge
KM:	27.60	User km:	27.60	Last Inspection Date:	2019/09/10
Project File ID #:	R08423	Br.	1	Next Inspection Date:	2022/09/10
Road Name:	CP 55				
Crossing Name:	MEACHEN Cr #4	Total Length (metres):	21.3		
Special Access:		Special Equipment:			
Longitude:	-116 28 32.4	Latitude:	49 32 39.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Type/Class Totals

Permanent Bridge Total: 73
Temporary Bridge Total: 6

Major Culvert Total: 7
Woodbox/Log Culvert Total: 0