



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-102

Site #:	64-102	Year Superstructure Installed:	2000	Structure Type/Class:	Temporary Bridge
KM:	1.14	User km:	1.00	Last Inspection Date:	2020/07/09
Project File ID #:	6315	Br.	14	Next Inspection Date:	2022/07/09
Road Name:	BONAPARTE/FROSTY				
Crossing Name:	Frosty Cr		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-120 43 50.8		Latitude:	51 15 55.9	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: 64-007

Site #:	64-007	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	7.30	User km:	7.30	Last Inspection Date:	2019/07/15
Project File ID #:	6061	Br.	01	Next Inspection Date:	2022/07/15
Road Name:	BOWERS/CANIM				
Crossing Name:	Jim Cr		Total Length (metres):	19.8	
Special Access:			Special Equipment:		
Longitude:	-120 42 27.6		Latitude:	51 44 16.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: KT70920

Site #:	64-144	Year Superstructure Installed:	2007	Structure Type/Class:	Temporary Bridge
KM:	0.50	User km:	0.50	Last Inspection Date:	2020/07/11
Project File ID #:	10592	Br.	01	Next Inspection Date:	2022/07/11
Road Name:	CL10592.01				
Crossing Name:	Unknown S4		Total Length (metres):	7.5	
Special Access:			Special Equipment:		
Longitude:	-120 33 13.5		Latitude:	51 47 23.8	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: one year post construction inspection, temporary BCTS installation DA. See monitor item.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: WO1618

Site #:	64-145	Year Superstructure Installed:	1998	Structure Type/Class:	Temporary Bridge
KM:	1.40	User km:	1.40	Last Inspection Date:	2020/07/11
Project File ID #:	10592	Br.	01	Next Inspection Date:	2022/07/11
Road Name:	CL10592.01				
Crossing Name:	Canimred		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-120 33 4.4		Latitude:	51 47 38.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Installed BCTS 2009, one year post construction inspection				

Structure Name: 64-087

Site #:	64-087	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	1.56	User km:	1.00	Last Inspection Date:	2019/07/14
Project File ID #:	5712	Br.	07	Next Inspection Date:	2022/07/14
Road Name:	CLINTON/TULERIC LAKE				
Crossing Name:	Last Course Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-120 47 3.6		Latitude:	51 11 59.2	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: 64-088

Site #:	64-088	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	5.44	User km:	5.00	Last Inspection Date:	2019/07/14
Project File ID #:	5712	Br.	07	Next Inspection Date:	2022/07/14
Road Name:	CLINTON/TULERIC LAKE				
Crossing Name:	Joe Ross Cr		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-120 44 2.2		Latitude:	51 11 15.8	
Superstructure:	Compo Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-038

Site #:	64-038	Year Superstructure Installed:	1981	Structure Type/Class:	Major Culvert
KM:	14.63	User km:	7.00	Last Inspection Date:	2019/07/14
Project File ID #:	5712	Br.	06	Next Inspection Date:	2022/07/14
Road Name:	CLINTON/UPPER LOON				
Crossing Name:	Coal Cr	Total Length (metres):	30.0		
Special Access:		Special Equipment:			
Longitude:	-120 55 31.9	Latitude:	51 10 46.7		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: 64-082

Site #:	64-082	Year Superstructure Installed:	1999	Structure Type/Class:	Major Culvert
KM:	5.42	User km:	14.00	Last Inspection Date:	2019/07/14
Project File ID #:	6315	Br.	01	Next Inspection Date:	2022/07/14
Road Name:	EAGAN/BONAPARTE				
Crossing Name:	Young Cr	Total Length (metres):	20.0		
Special Access:		Special Equipment:			
Longitude:	-120 56 23.2	Latitude:	51 17 49.6		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: 64-018

Site #:	64-018	Year Superstructure Installed:	1989	Structure Type/Class:	Temporary Bridge
KM:	7.24	User km:	6.00	Last Inspection Date:	2021/09/09
Project File ID #:	9173	Br.	01	Next Inspection Date:	2022/09/09
Road Name:	GOTCHEN LAKE				
Crossing Name:	Gotchen Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-120 40 55.9	Latitude:	52 8 20.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: inspection changed to 2013 BT				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-133A

Site #:	64-133	Year Superstructure Installed:	2017	Structure Type/Class:	Woodbox/Log Culvert
KM:	5.40	User km:	5.40	Last Inspection Date:	2020/07/10
Project File ID #:	7357	Br.	02	Next Inspection Date:	2022/07/10
Road Name:	GREEN LAKE/JIM LAKE				
Crossing Name:	Unnamed		Total Length (metres):	5.0	
Special Access:			Special Equipment:		
Longitude:	-121 8 43.3		Latitude:	51 24 30.6	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: 64-139

Site #:	64-139	Year Superstructure Installed:	2011	Structure Type/Class:	Temporary Bridge
KM:	2.30	User km:	2.30	Last Inspection Date:	2020/07/12
Project File ID #:	5289	Br.	21	Next Inspection Date:	2022/07/12
Road Name:	GRIZZLY LAKE				
Crossing Name:	Grizzly Lake outlet		Total Length (metres):	6.1	
Special Access:			Special Equipment:		
Longitude:	-120 46 24.0		Latitude:	51 37 5.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans: 1
Planned Inspection Comments:					

Structure Name: 64-135

Site #:	64-135	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	3.70	User km:	0.50	Last Inspection Date:	2019/07/16
Project File ID #:	10522	Br.	01	Next Inspection Date:	2022/07/16
Road Name:	HOOLIGAN CREEK FSR				
Crossing Name:	Hooligan Ck tributary		Total Length (metres):	6.0	
Special Access:			Special Equipment:		
Longitude:	-120 49 24.8		Latitude:	51 24 0.1	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-136

Site #:	64-136	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	6.10	User km:	3.00	Last Inspection Date:	2019/07/16
Project File ID #:	10522	Br.	01	Next Inspection Date:	2022/07/16
Road Name:	HOOLIGAN CREEK FSR				
Crossing Name:	Hooligan Ck Tributary		Total Length (metres):	7.3	
Special Access:			Special Equipment:		
Longitude:	-120 47 22.9		Latitude:	51 24 0.3	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: 64-137

Site #:	64-137	Year Superstructure Installed:		Structure Type/Class:	Major Culvert
KM:	6.30	User km:	3.20	Last Inspection Date:	2019/07/16
Project File ID #:	10522	Br.	01	Next Inspection Date:	2022/07/16
Road Name:	HOOLIGAN CREEK FSR				
Crossing Name:	Hooligan Ck Tributary		Total Length (metres):	7.3	
Special Access:			Special Equipment:		
Longitude:	-120 47 12.9		Latitude:	51 23 57.1	
Superstructure:			Abutments (Left/Right): (looking downstream)	# Spans:	0
Planned Inspection Comments:					

Structure Name: 64-096

Site #:	64-127	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	0.34	User km:	0.30	Last Inspection Date:	2019/07/16
Project File ID #:	10522	Br.	03	Next Inspection Date:	2022/07/16
Road Name:	HOOLIGAN CREEK SOUTH				
Crossing Name:	Hooligan Creek		Total Length (metres):	6.0	
Special Access:			Special Equipment:		
Longitude:	-120 49 19.8		Latitude:	51 23 50.7	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-068

Site #:	64-068	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.44	User km:	9.80	Last Inspection Date:	2019/07/14
Project File ID #:	9909	Br.	01	Next Inspection Date:	2022/07/14
Road Name:	JEEP LAKE				
Crossing Name:	Unnamed	Total Length (metres):	6.0		
Special Access:		Special Equipment:			
Longitude:	-121 7 19.0	Latitude:	51 18 39.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: see how serious bearing etc are.				

Structure Name: 64-025

Site #:	64-025	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	3.80	User km:	3.80	Last Inspection Date:	2019/07/15
Project File ID #:	7376	Br.	02	Next Inspection Date:	2022/07/15
Road Name:	MACDONALD-TAKAGI				
Crossing Name:	Neff Cr	Total Length (metres):	8.6		
Special Access:		Special Equipment:			
Longitude:	-120 48 48.0	Latitude:	51 49 2.4		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: WO5656

Site #:	64-140	Year Superstructure Installed:	2012	Structure Type/Class:	Permanent Bridge
KM:	2.60	User km:	2.60	Last Inspection Date:	2019/07/16
Project File ID #:	8434	Br.	10	Next Inspection Date:	2022/07/16
Road Name:	MH 8434.10				
Crossing Name:	Unnamed	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-120 32 49.5	Latitude:	51 35 30.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Inspect one year after installation. MRF 03/2013				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: TKA006

Site #:	64-142	Year Superstructure Installed:	2012	Structure Type/Class:	Temporary Bridge
KM:	0.30	User km:	0.30	Last Inspection Date:	2020/07/11
Project File ID #:	8611	Br.	19	Next Inspection Date:	2022/07/11
Road Name:	MH 8611.19				
Crossing Name:	Unknown Cr		Total Length (metres):	6.1	
Special Access:			Special Equipment:		
Longitude:	-120 27 18.3		Latitude:	51 59 57.4	
Superstructure:	Timber - untreated stringers	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: One year post installation inspection. MRF 02/2013				

Structure Name: 64-116

Site #:	64-116	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	2.90	User km:	2.90	Last Inspection Date:	2019/07/16
Project File ID #:	10591	Br.	01	Next Inspection Date:	2022/07/16
Road Name:	MH10591.01				
Crossing Name:	Price Creek Raspberry Lk FSR		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-120 48 9.7		Latitude:	51 26 5.7	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-159

Site #:	64-159	Year Superstructure Installed:	2020	Structure Type/Class:	Major Culvert
KM:	0.50	User km:	0.50	Last Inspection Date:	
Project File ID #:	5289	Br.	30	Next Inspection Date:	2021/08/20
Road Name:	MH5289.30				
Crossing Name:	Unnamed Cr		Total Length (metres):	7.3	
Special Access:			Special Equipment:		
Longitude:	-120 46 4.0		Latitude:	51 35 52.0	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status:Inspect Sort: Forest

Structure Name: 64-157

Site #:	64-157	Year Superstructure Installed:	2017	Structure Type/Class:	Temporary Bridge
KM:	0.20	User km:	0.20	Last Inspection Date:	2020/07/10
Project File ID #:	5956	Br.	29	Next Inspection Date:	2022/07/10
Road Name:	MH5956.29				
Crossing Name:	Unnamed		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-120 58 21.0		Latitude:	52 1 24.0	
Superstructure:	Steel Box Beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					

Structure Name: S/N 06498

Site #:	64-166	Year Superstructure Installed:	2020	Structure Type/Class:	Temporary Bridge
KM:	1.30	User km:	4.50	Last Inspection Date:	
Project File ID #:	5956	Br.	30	Next Inspection Date:	2021/08/20
Road Name:	MH5956.30				
Crossing Name:	Unnamed		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-120 53 55.6		Latitude:	52 0 24.7	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 12-MAY-21: One year post installation inspection				

Structure Name: 64-155

Site #:	64-155	Year Superstructure Installed:	2015	Structure Type/Class:	Temporary Bridge
KM:	0.50	User km:	0.50	Last Inspection Date:	2020/07/11
Project File ID #:	6061	Br.	20	Next Inspection Date:	2022/07/11
Road Name:	MH6061.20				
Crossing Name:	Unnamed Creek		Total Length (metres):	10.0	
Special Access:			Special Equipment:		
Longitude:	-120 40 7.9		Latitude:	51 47 45.6	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: TKA010

Site #:	64-174	Year Superstructure Installed:	2020	Structure Type/Class:	Temporary Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2015/10/06
Project File ID #:	8434	Br.	23	Next Inspection Date:	2021/08/20
Road Name:	MH8434.23				
Crossing Name:	Unnamed		Total Length (metres):	15.2	
Special Access:			Special Equipment:		
Longitude:	-120 27 29.0		Latitude:	51 35 39.2	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 12-MAY-21: One year post installation inspection CBR_Conversion on 11-MAY-21:				

Structure Name: TKA030

Site #:	64-175	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	2.30	User km:	2.30	Last Inspection Date:	
Project File ID #:	8434	Br.	23	Next Inspection Date:	2021/08/20
Road Name:	MH8434.23				
Crossing Name:	Unknown		Total Length (metres):	12.2	
Special Access:			Special Equipment:		
Longitude:	-120 26 13.3		Latitude:	51 35 10.7	
Superstructure:	Steel Box Beam	Abutments (Left/Right): (looking downstream)	Other	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 12-MAY-21: One year post installation inspection				

Structure Name: 64-156

Site #:	64-156	Year Superstructure Installed:		Structure Type/Class:	Temporary Bridge
KM:	0.10	User km:	0.10	Last Inspection Date:	2020/07/09
Project File ID #:	10650	Br.	01	Next Inspection Date:	2022/07/09
Road Name:	MHB 10650.01				
Crossing Name:	unknown		Total Length (metres):	4.8	
Special Access:			Special Equipment:		
Longitude:	-121 43 58.1		Latitude:	51 12 39.9	
Superstructure:	Log Stringers	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-121

Site #:	64-162	Year Superstructure Installed:	2019	Structure Type/Class:	Temporary Bridge
KM:	1.40	User km:	1.40	Last Inspection Date:	2010/05/26
Project File ID #:	5289	Br.	11	Next Inspection Date:	2021/05/26
Road Name:	MHD 5289.11				
Crossing Name:	Windy Creek		Total Length (metres):	9.0	
Special Access:			Special Equipment:		
Longitude:	-120 36 8.6		Latitude:	51 39 19.0	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans: 1
Planned Inspection Comments:	IDIR\MRFENNEL on 26-FEB-21: Post installation inspection				

Structure Name: 64-122

Site #:	64-122	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	1.20	User km:	66.00	Last Inspection Date:	2019/07/15
Project File ID #:	5289	Br.	12	Next Inspection Date:	2022/07/15
Road Name:	MHD 5289.12				
Crossing Name:	Needa01		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-120 40 20.0		Latitude:	51 37 20.9	
Superstructure:	Concrete Slab Girders		Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans: 1
Planned Inspection Comments:					

Structure Name: 64-130

Site #:	64-130	Year Superstructure Installed:	2012	Structure Type/Class:	Major Culvert
KM:	1.10	User km:	1.10	Last Inspection Date:	2019/07/16
Project File ID #:	8434	Br.	07	Next Inspection Date:	2022/07/16
Road Name:	MHD 8434.07				
Crossing Name:	Wavy/Spectical Wavy 02		Total Length (metres):	24.0	
Special Access:			Special Equipment:		
Longitude:	-120 30 41.7		Latitude:	51 36 5.4	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Verify depth of cover for outlet and inlet. MRF 02/2013				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 11 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-069

Site #:	64-132	Year Superstructure Installed:	2006	Structure Type/Class:	Temporary Bridge
KM:	8.00	User km:	8.00	Last Inspection Date:	2020/07/10
Project File ID #:	5956	Br.	15	Next Inspection Date:	2022/07/10
Road Name:	MHH 5956.15				
Crossing Name:	614 Rd Unnamed Ck Lang Lake West	Total Length (metres):	7.6		
Special Access:		Special Equipment:			
Longitude:	-121 0 40.6	Latitude:	51 58 53.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: check strucutre # as this bridge has been moved from Boas East				

Structure Name: 64-077

Site #:	64-077	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	0.14	User km:	1.00	Last Inspection Date:	2019/07/14
Project File ID #:	9979	Br.	01	Next Inspection Date:	2022/07/14
Road Name:	MOUNT ROSEMARY				
Crossing Name:	Eightythree Cr	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-121 23 9.2	Latitude:	51 27 18.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-026

Site #:	64-026	Year Superstructure Installed:	1993	Structure Type/Class:	Permanent Bridge
KM:	0.70	User km:	0.70	Last Inspection Date:	2019/06/23
Project File ID #:	8611	Br.	01	Next Inspection Date:	2022/06/23
Road Name:	SPANISH CREEK				
Crossing Name:	Hendrix Cr	Total Length (metres):	24.8		
Special Access:		Special Equipment:			
Longitude:	-120 41 30.3	Latitude:	51 58 9.6		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: check for sloughing on approaches some repairs made 2011				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 12 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-027

Site #:	64-027	Year Superstructure Installed:	1993	Structure Type/Class:	Temporary Bridge
KM:	11.64	User km:	11.00	Last Inspection Date:	2021/09/08
Project File ID #:	8611	Br.	01	Next Inspection Date:	2022/09/08
Road Name:	SPANISH CREEK				
Crossing Name:	Deception Cr	Total Length (metres):	17.0		
Special Access:		Special Equipment:			
Longitude:	-120 34 6.1	Latitude:	51 58 56.7		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-099

Site #:	64-099	Year Superstructure Installed:	2001	Structure Type/Class:	Major Culvert
KM:	2.00	User km:	2.00	Last Inspection Date:	2019/06/23
Project File ID #:	8611	Br.	02	Next Inspection Date:	2022/06/23
Road Name:	SPANISH/ART CREEK				
Crossing Name:	Hotfish Cr	Total Length (metres):	21.0		
Special Access:		Special Equipment:			
Longitude:	-120 36 37.6	Latitude:	51 58 34.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: 64-167

Site #:	64-167	Year Superstructure Installed:	2020	Structure Type/Class:	Temporary Bridge
KM:	3.80	User km:	5.30	Last Inspection Date:	
Project File ID #:	8611	Br.	04	Next Inspection Date:	2021/08/20
Road Name:	SPANISH/DECEPTION				
Crossing Name:	Unnamed	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-120 34 16.3	Latitude:	52 0 36.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 13 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-168

Site #:	64-168	Year Superstructure Installed:	2020	Structure Type/Class:	Temporary Bridge
KM:	5.60	User km:	7.10	Last Inspection Date:	
Project File ID #:	8611	Br.	04	Next Inspection Date:	2021/08/20
Road Name:	SPANISH/DECEPTION				
Crossing Name:	Unnamed		Total Length (metres):	9.1	
Special Access:			Special Equipment:		
Longitude:	-120 34 31.7		Latitude:	52 1 28.4	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-091

Site #:	64-091	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	1.23	User km:	1.00	Last Inspection Date:	2019/06/23
Project File ID #:	8611	Br.	07	Next Inspection Date:	2022/06/23
Road Name:	SPANISH/NO NAME				
Crossing Name:	Ex Cr		Total Length (metres):	27.0	
Special Access:			Special Equipment:		
Longitude:	-120 31 58.0		Latitude:	51 59 20.2	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: 64-092

Site #:	64-092	Year Superstructure Installed:	2000	Structure Type/Class:	Major Culvert
KM:	1.85	User km:	1.60	Last Inspection Date:	2019/06/23
Project File ID #:	8611	Br.	07	Next Inspection Date:	2022/06/23
Road Name:	SPANISH/NO NAME				
Crossing Name:	Ex Creek		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-120 32 2.8		Latitude:	51 59 39.2	
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 14 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-028

Site #:	64-028	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	1.70	User km:	1.70	Last Inspection Date:	2019/06/23
Project File ID #:	8611	Br.	03	Next Inspection Date:	2022/06/23
Road Name:	SPANISH/PENDLETON				
Crossing Name:	Deception Cr		Total Length (metres):	33.9	
Special Access:			Special Equipment:		
Longitude:	-120 34 3.2		Latitude:	51 57 44.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-100

Site #:	64-100	Year Superstructure Installed:	2001	Structure Type/Class:	Temporary Bridge
KM:	4.10	User km:	4.10	Last Inspection Date:	2020/07/11
Project File ID #:	8611	Br.	17	Next Inspection Date:	2022/07/11
Road Name:	SPANISH/UPPER BURTT				
Crossing Name:	Unnamed		Total Length (metres):	15.0	
Special Access:			Special Equipment:		
Longitude:	-120 41 24.1		Latitude:	52 0 37.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-029

Site #:	64-029	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	0.10	User km:	0.00	Last Inspection Date:	2021/09/10
Project File ID #:	6411	Br.	01	Next Inspection Date:	2022/09/10
Road Name:	SPOUT-OIE LAKE				
Crossing Name:	Eagle Cr		Total Length (metres):	12.0	
Special Access:			Special Equipment:		
Longitude:	-121 27 38.5		Latitude:	52 1 8.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 15 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-062

Site #:	64-062	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	20.80	User km:	20.00	Last Inspection Date:	2019/07/15
Project File ID #:	6411	Br.	01	Next Inspection Date:	2022/07/15
Road Name:	SPOUT-OIE LAKE				
Crossing Name:	Borthwick Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-121 13 2.8	Latitude:	51 59 42.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: changed next inspection to 2013				

Structure Name: 64-070

Site #:	64-070	Year Superstructure Installed:	1999	Structure Type/Class:	Permanent Bridge
KM:	2.34	User km:	2.30	Last Inspection Date:	2019/07/15
Project File ID #:	9907	Br.	01	Next Inspection Date:	2022/07/15
Road Name:	SUTHERLAND LAKE				
Crossing Name:	Unnamed	Total Length (metres):	9.0		
Special Access:		Special Equipment:			
Longitude:	-120 52 27.3	Latitude:	51 38 2.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-086

Site #:	64-086	Year Superstructure Installed:	2000	Structure Type/Class:	Permanent Bridge
KM:	2.40	User km:	2.40	Last Inspection Date:	2019/07/15
Project File ID #:	6048	Br.	01	Next Inspection Date:	2022/07/15
Road Name:	TATTON/CANAMA				
Crossing Name:	Muench Cr	Total Length (metres):	10.0		
Special Access:		Special Equipment:			
Longitude:	-121 38 26.4	Latitude:	51 49 9.1		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: low use, changed inspection to 2013 BT				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 16 of 16
Date Printed: 2022/04/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: 100 Mile House Natural Resource District Next Planned Inspection Date: < 2022/12/30 Inspection Status: Inspect Sort: Forest

Structure Name: 64-040

Site #:	64-040	Year Superstructure Installed:	1988	Structure Type/Class:	Temporary Bridge
KM:	13.70	User km:	14.00	Last Inspection Date:	2020/07/12
Project File ID #:	8434	Br.	01	Next Inspection Date:	2022/07/12
Road Name:	WAVEY LAKE				
Crossing Name:	Jim Cr	Total Length (metres):	13.0		
Special Access:		Special Equipment:			
Longitude:	-120 31 35.5	Latitude:	51 34 21.5		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:					

Structure Name: 64-119

Site #:	64-119	Year Superstructure Installed:	2007	Structure Type/Class:	Major Culvert
KM:	15.30	User km:	64.00	Last Inspection Date:	2019/07/15
Project File ID #:	5289	Br.	01	Next Inspection Date:	2022/07/15
Road Name:	WINDY MOUNTIAN				
Crossing Name:	Unnamed J9site	Total Length (metres):	22.0		
Special Access:		Special Equipment:			
Longitude:	-120 40 54.8	Latitude:	51 38 14.5		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					

Structure Name: 64-046

Site #:	64-046	Year Superstructure Installed:	1992	Structure Type/Class:	Permanent Bridge
KM:	21.80	User km:	71.00	Last Inspection Date:	2019/07/15
Project File ID #:	5289	Br.	01	Next Inspection Date:	2022/07/15
Road Name:	WINDY MOUNTIAN				
Crossing Name:	Noname Cr	Total Length (metres):	11.4		
Special Access:		Special Equipment:			
Longitude:	-120 36 28.6	Latitude:	51 38 18.1		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Type/Class Totals

Permanent Bridge Total: 16
Temporary Bridge Total: 20

Major Culvert Total: 11
Woodbox/Log Culvert Total: 1