



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 1 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N3-102

Site #:	N3-102	Year Superstructure Installed:	2009	Structure Type/Class:	Major Culvert
KM:	3.40	User km:	3.40	Last Inspection Date:	2020/09/09
Project File ID #:	4170	Br.	01	Next Inspection Date:	2023/09/09
Road Name:	BEAVERFOOT				
Crossing Name:	unknown	Total Length (metres):	13.0		
Special Access:		Special Equipment:			
Longitude:	-116 37 12.7	Latitude:	51 12 29.6		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 29-JAN-18: document if number plate is installed at next inspection				

Structure Name: N3-104

Site #:	N3-104	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	21.10	User km:	21.10	Last Inspection Date:	2020/09/10
Project File ID #:	4170	Br.	01	Next Inspection Date:	2023/09/10
Road Name:	BEAVERFOOT				
Crossing Name:	Unnamed S3	Total Length (metres):	8.5		
Special Access:		Special Equipment:			
Longitude:	-116 27 55.7	Latitude:	51 5 44.8		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:					

Structure Name: N3-110

Site #:	N3-110	Year Superstructure Installed:	2013	Structure Type/Class:	Permanent Bridge
KM:	22.90	User km:	22.90	Last Inspection Date:	2020/09/10
Project File ID #:	4170	Br.	01	Next Inspection Date:	2023/09/10
Road Name:	BEAVERFOOT				
Crossing Name:	unnamed crk	Total Length (metres):	7.5		
Special Access:		Special Equipment:			
Longitude:	-116 26 55.7	Latitude:	51 5 3.3		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 03-OCT-14: .				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 2 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Management Area:

Structure Name: N3-007

Site #:	N3-007	Year Superstructure Installed:	1994	Structure Type/Class:	Permanent Bridge
KM:	0.69	User km:	13.30	Last Inspection Date:	2022/08/02
Project File ID #:	7507	Br.	01	Next Inspection Date:	2023/08/02
Road Name:	BLAEBERRY FSR				
Crossing Name:	WILLOW BANK Cr		Total Length (metres):	7.6	
Special Access:			Special Equipment:		
Longitude:	-116 58 50.0		Latitude:	51 28 38.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 24-JAN-20: JRG Jan 24, 2020 Record lock block rotation at both abutments at every inspection.				

Structure Name: N3-012A

Site #:	N3-012	Year Superstructure Installed:	2016	Structure Type/Class:	Permanent Bridge
KM:	15.15	User km:	15.00	Last Inspection Date:	2020/09/10
Project File ID #:	7507	Br.	01	Next Inspection Date:	2023/09/10
Road Name:	BLAEBERRY FSR				
Crossing Name:	BLAEBERRY R #3		Total Length (metres):	48.8	
Special Access:			Special Equipment:		
Longitude:	-116 52 20.0		Latitude:	51 32 55.0	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Pile -Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\MRFENNEL on 29-JAN-18: na				

Structure Name: N3-013

Site #:	N3-013	Year Superstructure Installed:	1997	Structure Type/Class:	Permanent Bridge
KM:	23.34	User km:	37.50	Last Inspection Date:	2020/09/10
Project File ID #:	7507	Br.	01	Next Inspection Date:	2023/09/10
Road Name:	BLAEBERRY FSR				
Crossing Name:	Unnamed		Total Length (metres):	11.5	
Special Access:			Special Equipment:		
Longitude:	-116 46 44.0		Latitude:	51 34 44.0	
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 17-FEB-14: Noticable approach erosion noted from flight June 2012 event. DA.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 3 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: PS-066

Site #:	N3-117	Year Superstructure Installed:	2018	Structure Type/Class:	Temporary Bridge
KM:	30.50	User km:	30.50	Last Inspection Date:	2021/07/28
Project File ID #:	7507	Br.	01	Next Inspection Date:	2023/07/28
Road Name:	BLAEBERRY FSR				
Crossing Name:	unknown	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-116 44 50.0	Latitude:	51 37 24.0		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	CBR_Conversion on 19-JUL-19: Structure installed at new location in 2018				

Structure Name: N3-096

Site #:	N3-096	Year Superstructure Installed:	2006	Structure Type/Class:	Permanent Bridge
KM:	0.21	User km:	19.60	Last Inspection Date:	2022/08/03
Project File ID #:	4170	Br.	06	Next Inspection Date:	2023/08/03
Road Name:	BRANCH 19.4				
Crossing Name:	Unnamed	Total Length (metres):	18.3		
Special Access:		Special Equipment:			
Longitude:	-116 29 7.5	Latitude:	51 6 10.9		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\BPelletT on 01-FEB-23: BP Feb 1-23 Monitor movement and rotation of each block in the left abutment				

Structure Name: N3-026

Site #:	N3-026	Year Superstructure Installed:	1985	Structure Type/Class:	Major Culvert
KM:	53.60	User km:	57.10	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	01	Next Inspection Date:	2023/09/11
Road Name:	BUSH RIVER				
Crossing Name:	Unnamed	Total Length (metres):	24.0		
Special Access:		Special Equipment:			
Longitude:	-117 26 37.5	Latitude:	51 45 52.3		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 4 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N3-033

Site #:	N3-033	Year Superstructure Installed:	1992	Structure Type/Class:	Temporary Bridge
KM:	93.00	User km:	97.90	Last Inspection Date:	2021/07/29
Project File ID #:	7521	Br.	01	Next Inspection Date:	2023/07/29
Road Name:	BUSH RIVER				
Crossing Name:	BUSH R	Total Length (metres):	22.5		
Special Access:		Special Equipment:			
Longitude:	-117 22 7.1	Latitude:	52 0 41.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 29-JAN-20: JRG Jan 29, 2020 Monitor slope of right abutment and possible scour below crib.				

Structure Name: N3-055

Site #:	N3-055	Year Superstructure Installed:	1975	Structure Type/Class:	Permanent Bridge
KM:	4.90	User km:	4.90	Last Inspection Date:	2022/08/28
Project File ID #:	7663	Br.	01	Next Inspection Date:	2023/08/28
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	BEAVERMOUTH	Total Length (metres):	84.2		
Special Access:		Special Equipment:	Peeper Truck		
Longitude:	-117 26 5.9	Latitude:	51 31 38.8		
Superstructure:	Glulam Girder	Abutments (Left/Right): (looking downstream)	Concrete Cast in Place	# Spans:	3
Planned Inspection Comments:	IDIR\HABEURSK on 13-MAR-23: 2021/08/28 entered in error. hb CBR_Conversion on 27-APR-21: JRG Apr 27, 2021 Annual close proximity inspection required to monitor condition of span 1 downstream girder.				

Structure Name: N3-097

Site #:	N3-097	Year Superstructure Installed:	2010	Structure Type/Class:	Major Culvert
KM:	43.00	User km:	43.00	Last Inspection Date:	2020/09/09
Project File ID #:	7663	Br.	01	Next Inspection Date:	2023/09/09
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	Unnamed	Total Length (metres):	15.0		
Special Access:		Special Equipment:			
Longitude:	-117 42 42.2	Latitude:	51 42 34.4		
Superstructure:		Abutments (Left/Right): (looking downstream)		# Spans:	0
Planned Inspection Comments:	CBR_Conversion on 11-SEP-14: .				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 5 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N3098

Site #:	N3-098	Year Superstructure Installed:	2010	Structure Type/Class:	Major Culvert
KM:	49.60	User km:	49.60	Last Inspection Date:	2020/09/09
Project File ID #:	7663	Br.	01	Next Inspection Date:	2023/09/09
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	Unnamed		Total Length (metres):	16.5	
Special Access:			Special Equipment:		
Longitude:	-117 41 54.9		Latitude:	51 45 4.1	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 30-JAN-18: na				

Structure Name: N3-099

Site #:	N3-099	Year Superstructure Installed:	2010	Structure Type/Class:	Major Culvert
KM:	50.50	User km:	50.50	Last Inspection Date:	2022/08/04
Project File ID #:	7663	Br.	01	Next Inspection Date:	2023/08/04
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	Unnamed		Total Length (metres):	16.0	
Special Access:			Special Equipment:		
Longitude:	-117 41 59.7		Latitude:	51 45 28.7	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:	CBR_Conversion on 31-JAN-23: BP Jan 23-21 Measure corrugation profile and wall thickness during 2023 routine inspection				

Structure Name: N3-063

Site #:	N3-063	Year Superstructure Installed:	2013	Structure Type/Class:	Temporary Bridge
KM:	57.30	User km:	57.30	Last Inspection Date:	2021/09/18
Project File ID #:	7663	Br.	01	Next Inspection Date:	2023/09/18
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	SMITH Cr		Total Length (metres):	14.6	
Special Access:			Special Equipment:		
Longitude:	-117 44 39.6		Latitude:	51 47 39.4	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 6 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Management Area:

Structure Name: N3-064

Site #:	N3-064	Year Superstructure Installed:	1985	Structure Type/Class:	Temporary Bridge
KM:	64.00	User km:	64.20	Last Inspection Date:	2022/08/04
Project File ID #:	7663	Br.	01	Next Inspection Date:	2023/08/04
Road Name:	COLUMBIA RIVER WEST				
Crossing Name:	SWAN Cr	Total Length (metres):	12.0		
Special Access:		Special Equipment:			
Longitude:	-117 48 51.4	Latitude:	51 49 30.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 28-JAN-22: BP Jan 28-22 Ensure 5 tonne load posting signs are in place IDIR\JRUPAR on 22-FEB-19: JRG Feb 22 2019 Record rot depth, location, and type (sap/heart) in crib members.				

Structure Name: N3-095

Site #:	N3-095	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	4.26	User km:	12.00	Last Inspection Date:	2020/09/09
Project File ID #:	8108	Br.	01	Next Inspection Date:	2023/09/09
Road Name:	DOGTOTH FSR				
Crossing Name:	Gorman Cr	Total Length (metres):	18.2		
Special Access:		Special Equipment:			
Longitude:	-117 6 44.8	Latitude:	51 21 1.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:					

Structure Name: WO3405

Site #:	N3-T02	Year Superstructure Installed:	2008	Structure Type/Class:	Permanent Bridge
KM:	1.81	User km:	16.10	Last Inspection Date:	2020/09/09
Project File ID #:	3461	Br.	05	Next Inspection Date:	2023/09/09
Road Name:	DONALD BR 13.9				
Crossing Name:	Cirque Cr	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:	-117 6 30.0	Latitude:	51 23 58.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:					



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 7 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N3-085

Site #:	N3-085	Year Superstructure Installed:	1998	Structure Type/Class:	Permanent Bridge
KM:	13.98	User km:	13.70	Last Inspection Date:	2022/08/03
Project File ID #:	3461	Br.	01	Next Inspection Date:	2023/08/03
Road Name:	DONALD FSR				
Crossing Name:	CIRQUE Cr	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-117 7 23.7	Latitude:	51 23 56.1		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\JRUPAR on 04-APR-22: DA March 2022, Ensure bridge is posted for 5 tonnes.				

Structure Name: N3-042

Site #:	N3-042	Year Superstructure Installed:	1995	Structure Type/Class:	Permanent Bridge
KM:	0.50	User km:	0.50	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	04	Next Inspection Date:	2023/09/11
Road Name:	ESPLANADE BAY				
Crossing Name:	SUCCOUR Cr	Total Length (metres):	11.6		
Special Access:		Special Equipment:			
Longitude:	-117 32 7.0	Latitude:	51 42 51.0		
Superstructure:	Concrete Slab Girders	Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 04-FEB-21: .				

Structure Name: N3-091

Site #:	N3-091	Year Superstructure Installed:	2002	Structure Type/Class:	Permanent Bridge
KM:	5.50	User km:	5.40	Last Inspection Date:	2022/08/01
Project File ID #:	7521	Br.	07	Next Inspection Date:	2023/08/01
Road Name:	HOPE				
Crossing Name:	Unnamed	Total Length (metres):	12.2		
Special Access:		Special Equipment:			
Longitude:	-117 22 36.6	Latitude:	51 44 42.2		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 26-APR-23: BP Apr 26-23 Ensure structure is effectively barricaded to traffic				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 8 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N3-092

Site #:	N3-092	Year Superstructure Installed:	2002	Structure Type/Class:	Permanent Bridge
KM:	7.75	User km:	7.50	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	07	Next Inspection Date:	2023/09/11
Road Name:	HOPE				
Crossing Name:	Unnamed		Total Length (metres):	16.2	
Special Access:			Special Equipment:		
Longitude:	-117 22 8.8		Latitude:	51 43 42.8	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Sill - Permanent Materials	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 13-JAN-16: ATV access required, bring bridge closed signs with inspector for 2017 inspection.				

Structure Name: N3-093

Site #:	N3-093	Year Superstructure Installed:	2002	Structure Type/Class:	Permanent Bridge
KM:	12.97	User km:	12.90	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	07	Next Inspection Date:	2023/09/11
Road Name:	HOPE				
Crossing Name:	Unnamed		Total Length (metres):	8.3	
Special Access:			Special Equipment:		
Longitude:	-117 18 50.1		Latitude:	51 42 54.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Lock Blocks	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 13-JAN-16: ATV access required, bring bridge closed signs with inspector in 2017.				

Structure Name: N3-094

Site #:	N3-094	Year Superstructure Installed:	2004	Structure Type/Class:	Permanent Bridge
KM:	17.31	User km:	17.50	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	07	Next Inspection Date:	2023/09/11
Road Name:	HOPE				
Crossing Name:	Unnamed		Total Length (metres):	8.0	
Special Access:			Special Equipment:		
Longitude:	-117 16 32.9		Latitude:	51 42 47.9	
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Concrete Precast	# Spans:	1
Planned Inspection Comments:	IDIR\DMALWAY on 13-JAN-16: ATV access required, bring bridge closed signs for next 2017 inspection.				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 9 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status: Inspect Management Area:

Structure Name: N3-090

Site #:	N3-090	Year Superstructure Installed:	2001	Structure Type/Class:	Major Culvert
KM:	13.62	User km:	8.20	Last Inspection Date:	2022/08/03
Project File ID #:	4170	Br.	03	Next Inspection Date:	2023/08/03
Road Name:	MOOSE				
Crossing Name:	Unnamed		Total Length (metres):	14.6	
Special Access:			Special Equipment:		
Longitude:	-116 21 25.1		Latitude:	51 6 26.4	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: N3-051

Site #:	N3-051	Year Superstructure Installed:	1987	Structure Type/Class:	Major Culvert
KM:	21.19	User km:	98.05	Last Inspection Date:	2020/09/11
Project File ID #:	7521	Br.	05	Next Inspection Date:	2023/09/11
Road Name:	SULLIVAN				
Crossing Name:	Unnamed		Total Length (metres):	20.0	
Special Access:			Special Equipment:		
Longitude:	-117 47 17.6		Latitude:	51 50 10.3	
Superstructure:			Abutments (Left/Right): (looking downstream)		# Spans: 0
Planned Inspection Comments:					

Structure Name: N3-049

Site #:	N3-049	Year Superstructure Installed:	1986	Structure Type/Class:	Temporary Bridge
KM:	30.60	User km:	91.90	Last Inspection Date:	2021/07/29
Project File ID #:	7521	Br.	05	Next Inspection Date:	2023/07/29
Road Name:	SULLIVAN				
Crossing Name:	GAME Cr		Total Length (metres):	22.0	
Special Access:			Special Equipment:		
Longitude:	-117 43 2.1		Latitude:	51 48 34.2	
Superstructure:	Steel I-beam		Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans: 1
Planned Inspection Comments:	IDIR\MIPENNER on 12-JAN-16: monitor current deck situation				



BC Ministry of Forests, Lands, and Natural Resource Operations

Inspections Due - Detailed Report

Page: 10 of 10
Date Printed: 2023/07/19
User Id: IDIR\MRFENNEL
Database: PROD
Report Id: CBR003

Forest District: Selkirk Natural Resource District Next Planned Inspection Date: < 2023/12/30 Inspection Status:Inspect Management Area:

Structure Name: N3-052

Site #:	N3-052	Year Superstructure Installed:	1987	Structure Type/Class:	Temporary Bridge
KM:	39.50	User km:	100.50	Last Inspection Date:	2021/07/29
Project File ID #:	7521	Br.	05	Next Inspection Date:	2023/07/29
Road Name:	SULLIVAN				
Crossing Name:	CARIBOU Cr	Total Length (metres):	12.3		
Special Access:		Special Equipment:			
Longitude:	-117 49 19.3	Latitude:	51 50 59.4		
Superstructure:	Steel I-beam	Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated	# Spans:	1

Planned Inspection Comments:

Structure Type/Class Totals

Permanent Bridge Total: 15
Temporary Bridge Total: 6

Major Culvert Total: 7
Woodbox/Log Culvert Total: 0