

TABLE 2 Summary of Roads - Multi-year Plan OP#26

Road ID	Associated Block	Area	Planned Year	Road Length (m)	From (m)	To (m)	Road Type	Comments
MAQ1800	MA124	Mamquam	2021	6106	0.0	6106.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ 1850	MA124	Mamquam	2021	1368	0.0	1368.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ 1851	MA124	Mamquam	2021	156	0.0	156.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ 1870	MA124	Mamquam	2021	387	0.0	387.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ 1870	MA124	Mamquam	2021	324	387.0	711.0	new construction	
MAQ 1880	MA124	Mamquam	2021	703	0.0	703.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ 1881	MA124	Mamquam	2021	908	0.0	908.0	new construction	
MAQ 1910	MA131	Mamquam	2021	632	0.0	630.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ 1914	MA131	Mamquam	2021	417	0.0	417.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ 1914	MA131	Mamquam	2021	308	417.0	735.0	new construction	
CN3000	CN109	Culliton	2021	816	0.0	817.0	new construction	
CN3010	CN109	Culliton	2021	95	0.0	951.0	new construction	
CN3011	CN109	Culliton	2021	247	0.0	247.0	new construction	
CN3020	CN109	Culliton	2021	173	0.0	320.0	new construction	
CN3030	CN109	Culliton	2021	286	0.0	286.0	new construction	
PX1000	PH103A	Phelix	2022	988	4283.0	5515.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
PX1400	PH103A	Phelix	2022	676	0.0	676.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAM2200	MA117, MA710	Mamquam	2022	4463	3618.0	8084.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAM2905	MA710	Mamquam	2022	1295	0.0	1295.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAM2910	MA117	Mamquam	2022	815	0.0	815.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAM2913	MA117	Mamquam	2022	873	0.0	873.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
ML1000	WF12	Mill Creek	2022	5855	0.0	5855.0	Bridge replacement reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
WF1500	WF12	Mill Creek	2022	899	0.0	899.0	new construction	
WF2000	WF04, WF05	Mill Creek	2022	2089	0.0	2089.0	new construction	
WF2100	WF05,WF06	Mill Creek	2022	1259	0.0	1259.0	new construction	
Woodfibe Mainline	WF15	Woodfibre	2022	5503	0.0	5503.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
WF5-2 (Mill Creek Woodfibre Connection)	Woodfibre Blocks	Woodfibre	2022	835	0.0	835.0	New Bridge and new road section	
WF5-2 (Mill Creek Woodfibre Connection)	Woodfibre Blocks	Woodfibre	2022	247	835.0	1082.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
Woodfibre South Mainline	Woodfibre Blocks	Woodfibre	2022	1051	0.0	1051.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
CK1240	CU650A	Culliton	2022	1731	0.0	1731.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
CK1241	CU650A	Culliton	2022	1795	0.0	1795.0	new construction	
CK1242	CU650A	Culliton	2022	884	0.0	884.0	new construction	
CK1243	CU650A	Culliton	2022	400	0.0	400.0	new construction	
CK1244	CU650A	Culliton	2022	891	0.0	891.0	new construction	
SQ_HA1000	HA502A, HA503A	Haylemore	2023	16600	0.0	16600.0	reconstruction	Road is in good shape up to 8km just some minor surfacing and maintenance needed, but beyond that the road is becoming overcome with alder, it will need to be brushed and some culverts re-installed, some sections will require surfacing and repairs.
SQ_HA2000	HA502A, HA503A	Haylemore	2023		0.0	3.3	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
SQ_MA1000	MA207, MA257	Mamquam	2023	2674	21890.0	24500.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ1500	MA207	Mamquam	2023	2502	0.0	2502.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.
MAQ1520	MA207	Mamquam	2023	248	0.0	248.0	reconstruction	road is overcome with alder, it will need to be brushed and culverts re-installed, some sections may require surfacing and repairs.