BC Ministry of Forests and Range

Routine Condition Bridge Inspection Form
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION

(enter either long/lat or UTM below – not both)

*Site #: CK 2154	*Crossing Name: Wahleach Crk	*Type/Class: ☐ Temporary bridge ☐ Permanent bridge	*Project File ID#: 8149
*Structure #: CK 2154			*Br. 03
*FSR Name: Jones Main	*Forest District: Fr. Hwy	*Kilometres: 0.6	User km:

Longitude: (ddd / mm / ss.s) 121 36 8.2	OR	UTM Zone	UTM Easting	UTM Northing
Latitude: (ddd / mm / ss.s) 49 15 19.6				

LEFT/RIGHT APPROACHES (as seen facing downstream) E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G (F) P UR	
Bridge Ahead Signs Missing	(0) 1 2	
Brushing Required	Yes (No)	
Delineator Missing Left	(0) 1 2	
Delineator Missing Right	(0) 1 2	
Fender Condition	E G (F) P None UR	
Posted Load Rating	62 (tonnes) or None	
Road Surface	E (G) F P UR	

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Cribs	E G F P (N/A) UR	
Tie-backs	E G F P (N/A) UR	
Bin Wall	E G F P (N/A) UR	
Concrete (cast in place; lock blocks, precast)	E G F P (N/A) UR	
Caps or Sills	E (G) F P N/A UR	
Piles or Posts	E G F P N/A UR	
Ballast Wall	E (G) F P N/A UR	
Wing Wall	E (G) F P N/A UR	
Bracing	E (G) F P N/A UR	
Hardware	E (G) F P N/A UR	
Fill	E (G) F P N/A UR	
Riprap	E (G) F P N/A UR	
Bearings	E (G) F P N/A UR	
Corrosion Protection	E (G) F P N/A UR	

Span 1 of ____ (spans are numbered consecutively starting from the left abutment)

Use "Additional Spans" Sheet for Multiple Spans

DECK

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E (G) F P N/A UR	
Running Planks	E G F P (N/A) UR	
Sub-deck	E G F P (N/A) UR	
Ties	E G F P (N/A) UR	
Nails	E G F P (N/A) UR	
Deck to Girder Bolts	E G F P (N/A) UR	
Concrete Deck	E (G) F P N/A UR	
Grout Pockets	E (G) F P N/A UR	
Deck Joints	E (G) F P N/A UR	
Steel Deck Plate	E G F P (N/A) UR	
Gravel Surface	E G F P (N/A) UR	
Gravel Deck Depth	____ metres or (N/A)	
Curb Rail/Blocks/Posts	E (G) F P UR	
Handrails/ Walkouts	E G F P (N/A) UR	
Hardware	E G F P (N/A) UR	
Overall Deck Condition	E (G) F P UR	

BC Ministry of Forests and Range

Routine Condition Bridge Inspection Form
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION

*Site #: CK 2154 | *Structure #: Ck 2154

SUPERSTRUCTURE

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Girders	E (G) F P UR	
Diaphragms	E (G) F P N/A UR	
Bracing	E (G) F P N/A UR	
Under-trussing	E G F P (N/A) UR	
Hardware	E G F P (N/A) UR	
Welded / Grouted Shear Connectors	E G F P (N/A) UR	

Stream CHANNEL

Width Clearance

*Est. Present Water Level Depth 0.5 (m) | *Est. Present Water Level Depth 10 (m) | *Est. Present Water Level Depth 2.5 (m)

HAZARDS (circle yes or no for each item))

High Water? Yes (No) | Scour? Yes (No) | Ice? Yes (No) | Debris? Yes (No) | Aggradation? (Yes) No

Comments

REPAIRS: ☐ Recommended ☒ Not required (H = High, M= Medium, L = Low)

Repair Item #	*Priority (circle)	*Estimate ($)	*Repair Description
1	H M L		
2	H M L		
3	H M L		

*Monitoring Status: ☐ Recommended ☐ Not required

Monitor Item #	*Monitor Description
1	
2	

PHOTO LOG

Photo #	Description	Photo #	Description

INSPECTOR TO COMPLETE THIS SECTION

As-built Drawings Checked? Yes No

P Eng Inspection Required? Yes No

Inspector's Estimate of Full Log Haul Traffic Replacement Date (year):
(PEng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR)
2021

*Date of Inspection (yyyy/mm/dd)	*Inspection Company Name	*Inspector's Name (print)	Inspector's Signature
2011/11/15	Onsite Eng Ltd	Greg Honeysett	Greg Honeysett

Inspector's Comments

PROFESSIONAL ENGINEER (PEng) TO COMPLETE THIS SECTION

Current Load Rating GVW (tonnes): 68 tonnes
(PEng to update structure details screen in CBR as necessary)

Date of Next Planned Inspection (yyyy/mm/dd) 2014/09/30

Reviewer Company Name	Reviewed by - PEng's Name (print)	Reviewed by - PEng's Signature	Date Reviewed (yyyy/mm/dd)
MoF	T. Miller		Jan 24, 2012

PEng Reviewer's Comments

PROFESSIONAL ENGINEER PROVINCE OF BRITISH COLUMBIA T. W. MILLER # 35995

* Denotes Mandatory Information for Corporate Bridge Register

Bridge identification indicates L75 rating, send asbuilt for confirmation.

CK2154 Crossing upstream

CK2154 Abutment Left Bank

CK2154 Abutment Rigth Bank

CK2154 Approach Right Bank