BC Ministry of Forests and Range

Routine Condition Bridge Inspection Form
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION

(enter either long/lat or UTM below – not both)

*Site #: CK-2317	*Crossing Name: Foley Creek	*Type/Class: ☐ Temporary bridge ☒ Permanent bridge	*Project File ID#: 5127
*Structure #:			*Br. 15
*FSR Name: Chilliwack - Foley Creek	*Forest District: CK	*Kilometres: 11.9km	User km: NOT MEASURED

Longitude: (ddd / mm / ss.s) 121° 32' 17.4"	OR	UTM Zone	UTM Easting	UTM Northing
Latitude: (ddd / mm / ss.s) 49° 09' 14.9"				

LEFT/RIGHT APPROACHES (as seen facing downstream)

E = excellent; G = good; F = fair; P = poor; N/A = not appl., UR = Unrated

Item	Present Condition (circle or fill-in))	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E G (F) P UR	Bridge in S-curve
Bridge Ahead Signs Missing	0 1 (2)	
Brushing Required	Yes (No)	
Delineator Missing Left	(0) 1 2	
Delineator Missing Right	(0) 1 2	
Fender Condition	E (G) F P None UR	NJBs
Posted Load Rating	_____(tonnes) or (None)	
Road Surface	E (G) F P UR	

LEFT/RIGHT ABUTMENTS (as seen facing downstream)

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Log/Timber Cribs	E G F P (N/A) UR	
Tie-backs	E G F P (N/A) UR	
Bin Wall	E G F P (N/A) UR	
Concrete (cast in place; lock blocks, precast)	E G F P (N/A) UR	
Caps or Sills	E (G) F P N/A UR	
Piles or Posts	E (G) F P N/A UR	POST+PAD
Ballast Wall	E (G) F P N/A UR	CONC
Wing Wall	E G F P (N/A) UR	
Bracing	E (G) F P N/A UR	
Hardware	E (G) F P N/A UR	
Fill	E (G) F P N/A UR	
Riprap	E (G) F P N/A UR	
Bearings	E (G) F P N/A UR	
Corrosion Protection	E (G) F P N/A UR	PAINTED

Span 1 of 1 (spans are numbered consecutively starting from the left abutment)

Use "Additional Spans" Sheet for Multiple Spans

DECK

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Running Surface (N/A if running surface is gravel or timber planks)	E (G) F P N/A UR	
Running Planks	E G F P (N/A) UR	
Sub-deck	E G F P (N/A) UR	
Ties	E G F P (N/A) UR	
Nails	E G F P (N/A) UR	
Deck to Girder Bolts	E G F P (N/A) UR	
Concrete Deck	E (G) F P N/A UR	
Grout Pockets	E (G) F P N/A UR	
Deck Joints	E (G) F P N/A UR	
Steel Deck Plate	E G F P (N/A) UR	
Gravel Surface	E G F P (N/A) UR	
Gravel Deck Depth	_____ metres or (N/A)	
Curb Rail/Blocks/Posts	E (G) F P UR	
Handrails/ Walkouts	E G F P (N/A) UR	
Hardware	E (G) F P N/A UR	
Overall Deck Condition	E (G) F P UR	

BC Ministry of Forests and Range

Routine Condition Bridge Inspection Form
(except for log stringer or timber stringer bridges)

GENERAL INFORMATION

*Site #: CL-2317

*Structure #:

SUPERSTRUCTURE

Item	Present Condition (circle)	Comments (a comment is mandatory if condition "Poor" is selected)
Girders	E (G) F P UR	
Diaphragms	E G F P (N/A) UR	
Bracing	E (G) F P N/A UR	
Under-trussing	E G F P (N/A) UR	
Hardware	E (G) F P N/A UR	
Welded / Grouted Shear Connectors	E (G) F P N/A UR	

Stream CHANNEL

*Est. Present Water Level Depth 0.3 (m) | *Est. Present Water Level Width 8 (m) | *Est. High Water Level Clearance 1.5 (m)

HAZARDS (circle yes or no for each item))

High Water? Yes (No) | Scour? Yes (No) | Ice? Yes (No) | Debris? Yes (No) | Aggradation? Yes (No)

Comments

REPAIRS: ☐ Recommended ☐ Not required (H = High, M= Medium, L = Low)

Repair Item #	*Priority (circle)	*Estimate ($)	*Repair Description
1	H M L		
2	H M L		
3	H M L		

*Monitoring Status: ☐ Recommended ☐ Not required

Monitor Item #	*Monitor Description
1	
2	

PHOTO LOG

Photo #	Description	Photo #	Description
	R->L		From u/s
	u/s		left abut
	d/s		left abut
	L->R		right abut
			Girders

INSPECTOR TO COMPLETE THIS SECTION

As-built Drawings Checked? Yes (No)

P Eng Inspection Required? Yes (No)

Inspector's Estimate of Full Log Haul Traffic Replacement Date (year): 2050
(PEng to review and evaluate inspector's estimate, and to update "Full Log Haul Traffic Replacement (year)" on structure details screen in CBR)

*Date of Inspection (yyyy/mm/dd)	*Inspection Company Name	*Inspector's Name (print)	Inspector's Signature
2011/11/10	Onsite Engineering	Jeremy Araki	

Inspector's Comments

PROFESSIONAL ENGINEER (PEng) TO COMPLETE THIS SECTION

Current Load Rating GVW (tonnes): 68 tonnes
(PEng to update structure details screen in CBR as necessary)

Date of Next Planned Inspection (yyyy/mm/dd) 2014/09/30

Reviewer Company Name	Reviewed by - PEng's Name (print)	Reviewed by - PEng's Signature	Date Reviewed (yyyy/mm/dd)
MoF	T. Miller		2012/02/07

PEng Reviewer's Comments
Post bridge ahead signs.

* Denotes Mandatory Information for Corporate Bridge Register

Present load rating of L75 or 68 tonnes to continue.

PROFESSIONAL ENGINEER PROVINCE OF BRITISH COLUMBIA J. C. P. ARAKI # 29756

PROFESSIONAL ENGINEER PROVINCE OF BRITISH COLUMBIA T. W. MILLER # 35995

CK2317 Downstream

CK2317 Right to Left Approach

CK2317 Left to Right Approach

CK2317 Upstream

CK2317 Left Abutment

CK2317 From Upstream

CK2317 Right Abutment

CK2317 Left Abutment riprap

CK2317 Girders